

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22001214/UEA3Q2**Date:** 13/04/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210031652
Claimant Vehicle No :	GBJ2571D	Insured Vehicle No :	SMY8960R
Date of Loss:	08/02/2022	Nature of Claim:	TP
		Claim No:	1037804687SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBJ2571D		
Make & Model:	TOYOTA HIACE, 3.0 D TURBO 5 DR (M)	Engine No:	1KD2842039
Reg. Date:	01/03/2019 (Man. Year: 2018)	Chassis No:	JTFHT02PX00247747
Colour:	Silver	Odometer:	76674 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	OHTSU 6 mm	Rear Left Side:	OHTSU 6 mm
Front Right Side:	OHTSU 6 mm	Rear Right Side:	OHTSU 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,458.02	4,347.45	2,110.57	32.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,810.00	2,110.00	700.00	24.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,268.02	6,457.45	2,810.57	30.33
Approved Total (Overridden) (S\$)		5,150.00		
(S\$)	9,268.02	5,150.00	4,118.02	44.43
+ GST 7.00/7.00% (S\$)	648.76	360.50	288.26	44.43
Nett Amount (S\$)	9,916.78	5,510.50	4,406.28	44.43
+ Loss of Use (6.0 x S\$100.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		6,112.50		
Global Sum Settlement (S\$)		6,110.00		

INSPECTION

Date of Assignment:	09/02/2022		
Date Inspected:	09/02/2022	Inspected At:	Tan Lim Motor Pte Ltd (Defu) 1 Defu Lane 6 Singapore 539365
Estimated Period of Repair:	5.0 days		

Adjuster: MARCUS CHUA**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE LID	Badly Dented	1,979.70 FL	*1,979.70 FL
2	1		*TAILGATE LID CENTRE LOGO BADGE	Necessary	71.60 FL	*71.60 FL
3	1		*TAILGATE LID LOCK TOP	Dented / Jammed	262.30 FL	*262.30 FL
4	1		*TAILGATE LID LOCK LATCH BOTTOM	Not Necessary	180.00 FL	*- FL
5	1		*TAILGATE LID WEATHERSTRIP	Twisted	189.60 FL	*189.60 FL
6	2		*TAILGATE LID RUBBER STOPPER	Not Necessary	50.00 FL	*- FL
7	2		*TAILGATE LID SIDE CATCH	Not Necessary	52.80 FL	*- FL
8	2		*TAILGATE LID SIDE CATCH LATCH	Not Necessary	97.80 FL	*- FL
9	1		*REAR END PANEL -OUTER	Badly Dented	388.30 FL	*388.30 FL
10	1		*REAR END PANEL -INNER	Badly Dented	1,155.00 FL	*1,155.00 FL
11	1		*REAR WINDSCREEN WEATHERSTRIP	No such part	298.70 FL	*- FL
12	1		*REAR BUMPER	Distorted	395.00 FL	*395.00 FL
13	1		*REAR BUMPER BEAM	Not fitted	165.00 FL	*- FL
14	4		*REAR BUMPER SIDE HOLDER CLIPS	Not Necessary	43.20 FL	*- FL
15	2		*REAR BUMPER SIDE HOLDER	Not Necessary	51.00 FL	*- FL
16	1		*REAR LAMP	N/S Cracked / O/SNot Necessary	720.00 FL	*360.00 FL
17	6		*REAR LAMP HOLDER CLIPS	Not Necessary	30.00 FL	*- FL
18	2		*REAR LAMP PANEL	Dented	270.00 FL	*270.00 FL
19	1		*SPARE TYRE CARRIAGE HOLDER	Not Necessary	485.60 FL	*- FL
20	2		*REAR FENDER AIR VENT	Not Necessary	470.00 FL	*- FL
21	2		*REAR LAMP CORNER PANEL	Repair	90.00 FL	*- FL
22	1		*TAILGATE LID 70KM/H STICKER	Necessary	20.00 FS	*10.00 FS
23	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*40.00 FS
24	1		*TAILGATE LID HIACE BADGE	Necessary	48.00 FS	*30.00 FS
25	1		*TAILGATE LID TOYOTA BADGE	Necessary	72.00 FS	*40.00 FS
26	1		*SET REAR BUMPER PARKING SENSOR	Shorted	450.00 FS	*200.00 FS
27	1		*REAR LICENCE PLATE	Cracked	40.00 FS	*40.00 FS
28	1		*REAR STEEL PLATE	Bent	245.10 FL	*245.10 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	8,380.70	5,676.60
- List Item Discount on L Items 25.00/25.00% (\$)	1,922.68	1,329.15
Total Parts (\$)	6,458.02	4,347.45

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	50.00	20.00
2	TO RUST-PROOFING OF THE AFFECTED AREAS	New	150.00	60.00
3	TO TRANSFER OF TAILGATE FITTINGS ,FIXTURE AND PERFORM WATERSEEPAGE TEST	New	120.00	60.00
4	TO REMOVE AND REFIT INTERIOR FITTINGS ,TRIIMINGS ,GARNISH AND OTHER TO ENABLE REPAIR	New	120.00	0.00
5	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	120.00	120.00
6	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	1,300.00	1,000.00
7	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	950.00	850.00
Gross Labour Cost (\$\$)			2,810.00	2,110.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >