

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/III22001222/VVF3E2

Date: 11/05/2022

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447_01

Claimant Vehicle No : YN8208X **Insured Vehicle No :** SND4866E

Date of Loss: 28/01/2022 Nature of Claim: TP Claim No: MFL2022D0000910

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **YN8208X**
Make & Model: ISUZU FVR34P, 17.6 D (M) Engine No: 6HK1664526
Reg. Date: 22/05/2015 (Man. Year: 2014) Chassis No: JALFVR347E7000788
Colour: Blue Odometer: 372461 km
Engine Capacity: 7790 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 275/70 R22.5 Rear Tyre Size: 275/70 R22.5
Front Left Side: Bridgestone 5 mm Rear Left Side: Bridgestone 5 mm
Front Right Side: Bridgestone 5 mm Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,869.00	3,844.00	4,025.00	51.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,950.00	780.00	4,170.00	84.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,819.00	4,624.00	8,195.00	63.93
Approved Total (Overridden) (S\$)		3,700.00		
Nett Amount (S\$)	12,819.00	3,700.00	9,119.00	71.14

INSPECTION

Date of Assignment: 09/02/2022

Date Inspected: 11/02/2022 Inspected At:

Bak Heng Motor Repairing (HQ)
5032, ANG MO KIO INDUS PARK 2, #01-291
Singapore 569535

Estimated Period of Repair: 4.0 days

Adjuster: Thevan Thomas Karthikesavan

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 11 May 2022)	
Parts:	N/A	ISUZU FVR34P 17.6 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YN8208X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR LH LAMP SUPPORT BRACKET	Serviceable	650.00 F	*- F
2	1	*REAR LH TAIL LAMP ASSY (GRAZED / CRACKED)	Not Consistent With The Impact	210.00 F	*- F
3	1	*REAR RH LAMP SUPPORT BRACKET	Slack/Bent/Cut	650.00 F	*400.00 F
4	1	*REAR RH TAIL LAMP ASSY	Cracked	230.00 F	*210.00 F
5	1	*REAR RH NUMBER PLATE LAMP	Cracked	71.00 F	*71.00 F
6	1	*REAR RH NUMBER PLATE LAMP BRACKET	Bent	85.00 F	*85.00 F
7	1	*REAR RH NUMBER PLATE	Crumpled / Cut	38.00 F	*38.00 F
8	1	*REAR RH NUMBER PLATE BRACKET	Bent / Cut	80.00 F	*80.00 F
9	1	*REAR CENTRE DISPOSAL SPLASH SHIELD PANEL	Buckled / Cut	2,100.00 F	*1,300.00 F
10	1	*REAR BUMPER ASSY	Buckled	1,800.00 F	*900.00 F
11	1	*REAR BUMPER SUPPORT BRACKET L/R	O/S Bent / N/S Repair	1,400.00 F	*400.00 F
12	1	*REAR BUMPER CAUTION STICKER	Necessary	180.00 F	*90.00 F
13	1	*REVERSE BUZZER	Torn / Cracked	195.00 F	*150.00 F
14	1	*REAR RH WHEEL MUD FLAP	Torn	180.00 F	*120.00 F

F=Franchise part.

Total Parts (S\$) 7,869.00 3,844.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO SPRAY UNDERCARRIAGE & CHASSIS FRAME WITH ANTI RUST UNDERCOATING	New	200.00	50.00
2	TO CHECK WIRING SYSTEM AND LIGHTS	New	150.00	30.00
3	TO MOUNT VEHICLE ON JIG BENCH TO CHECK, STRAIGHTEN & ALIGN REAR L/R CHASSIS AND REAR CROSS MEMBER	New	1,400.00	0.00
4	TO PUTTY AND RESPRAY PAINT ON AFFECTED AREA	New	1,200.00	300.00
5	TO RENEW DAMAGED PARTS, STRAIGHTEN / REPAIR AND ALIGNED ALL PARTS	New	2,000.00	400.00
Gross Labour Cost (\$)			4,950.00	780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >