



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLV 2957T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	DEFORMED	1,050.50	1,050.50
2	FRONT BUMPER SIDE RETAINER RH & LH @\$45.00	N/S DAMAGED	90.00	45.00
2	FRONT BUMPER FOGLAMP COVER RH & LH @\$101.00	N/S CUT	202.00	101.00
1	FRONT BUMPER REINFORCEMENT	DENTED	510.00	397.00
1	FRONT BUMPER LOWER GRILLE	CRACKED	216.00	216.00
1	FRONT HEADLAMP LH	CRACKED	2,250.00	2,250.00
2	FRONT HEADLAMP LOWER BRACKET LH	NOT NECESSARY	45.60	-
1	FRONT FENDER RH	NOT NECESSARY	456.80	-
1	FRONT FENDER INNER SHIELD RH	NOT NECESSARY	116.50	-
1	FRONT WASHER TANK	NOT NECESSARY	318.00	-
1	FRONT WASHER TANK MOTOR	NOT NECESSARY	352.00	-
1	FRONT SUPPORT PANEL	NOT NECESSARY	510.00	-
1	FRONT GRILLE	CRACKED	352.00	352.00
1	FRONT GRILLE CHROME MOULDING	CRACKED	255.00	255.00
	LESS 20% DISCOUNT		-1,344.88	-933.30
			5,379.52	3,733.20
<u>SPECIAL NETT ITEMS</u>				
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	100.00	30.00
1	FRONT BUMPER LOWER GARNISH (SN)	DEFORMED	680.00	350.00
1	SET FRONT SUPPORT PANEL CLIPS (SN)	NOT NECESSARY	100.00	-
1	SET FRONT FENDER INNER SHIELD CLIPS (SN)	NOT NECESSARY	80.00	-
1	FRONT TYRE LH (SN)	NOT NECESSARY	350.00	-
1	FRONT RIM LH (SN)	NOT NECESSARY	550.00	-
1	SET FRONT CAR PLATE WITH COVER (SN)	NOT NECESSARY	70.00	-
			1,930.00	380.00
<u>LABOUR</u>				
	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS AND REPLACE DAMAGED PARTS.		1,600.00	400.00
	TO SUPPLY PAINT MATERIALS, EXPANDABLE ITEMS & PUTTY, RESPRAY PAINT ON PARTS REPLACED.		1,200.00	250.00
	TO REMOVE AND REFIX WIRING AT DAMAGED AREAS.		180.00	30.00

Report Ref No. CS/AIS22001224/Any3m4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PERFORM ANTI RUST TREATMENT ON AFFECTED AREAS.	NOT NECESSARY	150.00	-
	TO CHECK HEADLAMP BEAM.	NOT NECESSARY	120.00	-
	TO CONDUCT WATER SEPAGE TEST.	NOT NECESSARY	100.00	-
	TO CONDUCT WHEEL ALIGNMENT TEST.	NOT NECESSARY	150.00	-
			3,500.00	680.00
GRAND TOTAL			10,809.52	4,793.20
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,800.00

Report Ref No. CS/AIS22001224/Any3m4

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.