



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                  |  |   |   |            |
|--|--|---|---|------------|
| ALLIANZ INSURANCE SINGAPORE PTE LTD<br>79 ROBINSON ROAD<br>#09-01 SINGAPORE 068897 |  |   | Ref: CS/AIS22001224/Any3m4<br>Date: 22/11/2022<br>Code: AIS |            |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                  |  |   |   |            |
|  | Insured Veh.   | SNC 3455U   | Veh. Inspected  | SLV 2957T  |
|  | Policy No.   |   | Coverage (\$)   | 0.00       |
|  | Claim No.  | 2022 22003897/fq  | Excess (\$)   | 0.00       |
|  | Assign From  | SHANTI  | Assign Date   | 09/02/2022 |
| <b>2. Vehicle Particulars &amp; Condition</b>                                      |  |   |   |            |
|  | Make & Model   | HONDA SHUTTLE   | c.c   | 1496       |
|  | Engine No.   | HIDDEN  | Year of Reg.  | 2017       |
|  | Chassis No.  | GK81104864  | Colour  | BLACK      |
|  | Odometer   | 66056 KM  | Steering  | IN ORDER   |
|  | Brakes   | IN ORDER  | Modification  | SPORTS RIM |
|  | General  | GOOD  |   |            |
| <b>3. Conditions of Tyres</b>  |  |   |   |            |
|  |  | Size  | Make  | Balance    |
|  | R/H Front Tyre   | 205/50 R16  | ROADX   | 6 mm       |
|  | L/H Front Tyre   | 205/50 R16  | ROADX   | 6 mm       |
|  | R/H Rear Tyre  | 205/50 R16  | ROADX   | 6 mm       |
|  | L/H Rear Tyre  | 205/50 R16  | ROADX   | 6 mm       |
| <b>4. Description of Damages</b>   |  |   |   |            |
|  | THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.<br>DAMAGES SEE DETAILS.  |   |   |            |
| <b>5. General Information</b>  |  |   |   |            |
|  | Accident Date  | 07/02/2022  | Inspection Date   | 09/02/2022 |
|  | Survey held at   | ACE AUTOLUTION PTE LTD<br>13 KAKI BUKIT ROAD 4<br>#03-29 BARTLEY BIZ CENTRE<br>SINGAPORE 417807 |   |            |
| <b>5a. Remarks</b>   |  |   |   |            |
|  | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |   |   |            |
| <b>5b. Estimate Days of Repair</b>   |  |   |   |            |
|  | ESTIMATED NORMAL PERIOD FOR REPAIR:  |   | 3 Working Days  |            |