#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS4/TMI22001225/VCY3E2

**Date:** 07/07/2022

**REFERENCE** 

Handling Insurer: Tokio Marine Insurance Singapore Ltd Policy No: MW005395

Claimant Vehicle SHC533T Insured Vehicle No : EM778L

Date of Loss: 08/02/2022 Nature of Claim: TP Claim No: M2200671

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SHC533T

Make & Model: TOYOTA PRIUS, 1.5 (A) Engine No: 2ZR2C06135

Reg. Date: 01/04/2019 (Man. Year: 2018) Chassis No: JTDKB3FU503079792

Colour: Yellow Odometer: 263201 km

Engine Capacity: 1798 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Good

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: West Lake 5 mm Rear Left Side: West Lake 5 mm
Front Right Side: West Lake 5 mm Rear Right Side: West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,186.22	143.10	3,043.12	95.51
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,580.00	1,300.00	280.00	17.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,777.22	1,454.10	3,323.12	69.56
+ GST 7.00/7.00% (S\$)	334.41	101.79	232.62	69.56
Nett Amount (S\$)	5,111.63	1,555.89	3,555.74	69.56

**INSPECTION** 

Date of Assignment: 09/02/2022 Present Location: ComfortDelGro Engineering Pte Ltd (Loyang)

ComfortDelGro Engineering Pte Ltd (Loyang)

Date Inspected: 09/02/2022 Inspected At: 59 Loyang Drive

Singapore 508969

Estimated Period of Repair: 3.0 days

Adjuster: Thevan Thomas Karthikesavan Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Different 1 cents -Finalise confirm amount: \$1,454.09

## **REPAIR DETAILS**

## Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 07 Jul 2022)

Parts: 144 TOYOTA PRIUS 1.5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHC533T)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*FRT FENDER HYBRID EMBLEM RH	Necessary	86.50 FL	-	*86.50 FL
2	1		*FRONT BUMPER FOG LAMP	Serviceable	920.00 FL	-	*- FL
3	1		*HEADLAMP RH	Serviceable	2,637.60 FL	-	*- FL
4	1		*FRONT BUMPER COVER	Repair	499.90 FL	-	*- FL
5	1		*FRONT BUMPER CLIPS	Necessary	22.00 FL	-	*22.00 FL
6	1		*FRONT BUMPER SIDE BRACKET RH	Necessary	82.30 FL	-	*82.30 FL
F=Fra	anchise	part. L=ListIt	emDisc.	-			
				Sub Total (S\$)	4,248.30	190.80	
			- List Item Discount on L Items	25.00/25.00% (S\$)	1,062.08	47.70	
				Total Parts (S\$)	3,186.22		143.10
			Report was unsubmitted during	na this print-out			]

# Recommended Miscellaneous Items

No	Qty	Particulars		Repairer's	Amount
Mis	cella	neous Items			
1	1	OD/TP Case (Insurer)		11.00	11.00
			Sub Total (S\$)	11.00	11.00

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PANEL BEATING	New	800.00	700.00
2	SPRAY PAINTING CHARGE	New	600.00	500.00
3	CHECK ALL LIGHTING	New	60.00	20.00
4	TUFF KOTE	New	60.00	20.00
Sup	<u>plementary #1</u>			
Lab	<u>our Items</u>			
5	TOWING FEE	New	60.00	60.00
		Gross Labour Cost (S\$)	1,580.00	1,300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >