

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD INV No. AC2202099

300 BEACH ROAD INV Date 12/04/2022

#17-04/07 THE CONCOURSE Reference CC4/LPC22001226/Kea3q2

SINGAPORE 199555 Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SME 6622K

Insured Veh. SKR 5356R

Claim No. 21/22/22/VP05/025423

Policy No. Z21VP05028464

Accident Date 29/01/2022

Inspection Date 21/02/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

LKM



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	LONPAC INSURAI	NCE BHD	Ref:	CC4/LPC22001226/Kea3q2		
	300 BEACH ROAD #17-04/07 THE CC	NCOURSESINGAPORE 199555	Date:	12/04/2022		
			Code:	LPC2		
1.		Policy Particulars	- THIRD PARTY CLAIN	Λ		
	Insured Veh.	SKR 5356R	Veh. Inspected	SME 6622K		
	Policy No.	Z21VP05028464	Coverage (\$)	0.00		
	Claim No.	21/22/22/VP05/025423	Excess (\$)	0.00		
	Assign From	KENNY	Assign Date	09/02/2022		
2.		Vehicle Partic	ulars & Condition			
	Make & Model	B.M.W. 320I GT (A)	c.c	1997		
	Engine No.	HIDDEN	Year of Reg.	2014		
	Chassis No.	WBA3X12030D735069	Colour	METALLIC DARK BLUE		
	Odometer	95939 KM	Steering	IN ORDER		
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM		
	General	GOOD				
3.		Condition	ons of Tyres			
		Size	Make	Balance		
		0.20				
	R/H Front Tyre	225/50 R18	MICHELIN	8 mm		
	R/H Front Tyre L/H Front Tyre		MICHELIN MICHELIN	8 mm 8 mm		
	-	225/50 R18				
	L/H Front Tyre	225/50 R18 225/50 R18	MICHELIN	8 mm		
4.	L/H Front Tyre R/H Rear Tyre	225/50 R18 225/50 R18 225/50 R18 225/50 R18	MICHELIN MICHELIN	8 mm 8 mm		
4.	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre	225/50 R18 225/50 R18 225/50 R18 225/50 R18	MICHELIN MICHELIN MICHELIN on of Damages	8 mm 8 mm		
4.	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre	225/50 R18 225/50 R18 225/50 R18 225/50 R18 225/50 R18 Description STAINED DAMAGES AT THE REA	MICHELIN MICHELIN MICHELIN on of Damages	8 mm 8 mm		
4.	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre THE VEHICLE SUS	225/50 R18 225/50 R18 225/50 R18 225/50 R18 225/50 R18 Description STAINED DAMAGES AT THE REALES.	MICHELIN MICHELIN MICHELIN on of Damages	8 mm 8 mm		
	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre THE VEHICLE SUS	225/50 R18 225/50 R18 225/50 R18 225/50 R18 225/50 R18 Description STAINED DAMAGES AT THE REALES.	MICHELIN MICHELIN MICHELIN on of Damages AR PORTION.	8 mm 8 mm		
	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre THE VEHICLE SUST	225/50 R18 225/50 R18 225/50 R18 225/50 R18 Description STAINED DAMAGES AT THE REALETAILS. General	MICHELIN MICHELIN MICHELIN On of Damages AR PORTION. Information	8 mm 8 mm 8 mm		
	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre THE VEHICLE SUS DAMAGES SEE D	225/50 R18 225/50 R18 225/50 R18 225/50 R18 225/50 R18 Description STAINED DAMAGES AT THE REAL ETAILS. General 29/01/2022	MICHELIN MICHELIN MICHELIN On of Damages AR PORTION. Information Inspection Date	8 mm 8 mm 8 mm		
	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre THE VEHICLE SUS DAMAGES SEE D	225/50 R18 225/50 R18 225/50 R18 225/50 R18 225/50 R18 Description STAINED DAMAGES AT THE REAL ETAILS. General 29/01/2022 DING AUTO PTE LTD BLK 10 #01-20 SIN MING IND E	MICHELIN MICHELIN MICHELIN On of Damages AR PORTION. Information Inspection Date	8 mm 8 mm 8 mm		
5.	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre THE VEHICLE SUS DAMAGES SEE D Accident Date Survey held at	225/50 R18 225/50 R18 225/50 R18 225/50 R18 225/50 R18 Description STAINED DAMAGES AT THE REAL ETAILS. General 29/01/2022 DING AUTO PTE LTD BLK 10 #01-20 SIN MING IND E	MICHELIN MICHELIN MICHELIN ON OF Damages AR PORTION. Information Inspection Date ST SEC C SINGAPORE 57 Emarks HOUT PREJUDICE" BASIS	8 mm 8 mm 21/02/2022 75645		
5.	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre THE VEHICLE SUS DAMAGES SEE D Accident Date Survey held at	225/50 R18 225/50 R18 225/50 R18 225/50 R18 225/50 R18 Description STAINED DAMAGES AT THE REAL ETAILS. General 29/01/2022 DING AUTO PTE LTD BLK 10 #01-20 SIN MING IND E REDN WAS CONDUCTED ON A"WITCE TO YOUR INSTRUCTIONS, W	MICHELIN MICHELIN MICHELIN ON OF Damages AR PORTION. Information Inspection Date ST SEC C SINGAPORE 57 Emarks HOUT PREJUDICE" BASIS	8 mm 8 mm 21/02/2022 75645		
5. 5a.	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre THE VEHICLE SUST DAMAGES SEE D Accident Date Survey held at A)THE INSPECTICE B)IN ACCORDANCE	225/50 R18 225/50 R18 225/50 R18 225/50 R18 225/50 R18 Description STAINED DAMAGES AT THE REAL ETAILS. General 29/01/2022 DING AUTO PTE LTD BLK 10 #01-20 SIN MING IND E REDN WAS CONDUCTED ON A"WITCE TO YOUR INSTRUCTIONS, W	MICHELIN MICHELIN MICHELIN ON OF DAMAGES AR PORTION. Information Inspection Date ST SEC C SINGAPORE 57 Emarks HOUT PREJUDICE" BASISE HAVE NOT AUTHORISE Days of Repair	8 mm 8 mm 21/02/2022 75645		



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SME 6622K

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER COVER	BUCKLED / CRACKED	1,428.48	1,428.48
1	REAR BUMPER RETAINER RH	SERVICEABLE	184.20	-
1	REAR BUMPER RETAINER LH	SERVICEABLE	184.20	-
1	REAR BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	564.30	-
1	REAR BUMPER SUPPORT BRACKET RH	SERVICEABLE	214.85	-
1	REAR BUMPER SUPPORT BRACKET LH	SERVICEABLE	214.85	-
1	REAR BUMPER LOWER CHROME TRIM	DENTED	231.55	231.55
1	REAR BUMPER REFLECTOR RH	SERVICEABLE	45.50	-
1	REAR BUMPER TOWING CAP	SERVICEABLE	52.45	-
	LESS 5% DISCOUNT		-156.02	-
	LESS 10% DISCOUNT		-	-166.00
			2,964.36	1,494.03
	SPECIAL NETT ITEMS			
2	REVERSE SENSOR @\$287.10 (SN)	SERVICEABLE	574.20	-
1	REAR BUMPER CLIPS /BRACKET (SN)	SERVICEABLE	120.00	-
			694.20	-
	LABOUR			
	PANEL BEAT & STRAIGHTEN -ACCIDENT AREA.INCLUSIVE OF THE REPAIR OF REAR BUMPER REINFORCEMENT .		1,000.00	400.00
	SPRAY PAINT -REAR BUMPER ,TAIL GATE COVER & END PANEL.		1,200.00	440.00
	REMOVE & REFIT REAR BUMPER COMPONENTS.}		150.00	60.00
	ALIGN REVERSE SENSOR & TEST WIRING.}		150.00	-
	RUST PROOFING.	NOT NECESSARY	100.00	-
			2,600.00	900.00
	GRAND TOTAL		6,258.56	2,394.03

Report Ref No. CC4/LPC22001226/Kea3q2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		1,900.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CC4/LPC22001226/Kea3q2

KONG SENG CHEONG

Licensed Appraiser



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SME 6622K


INSPECTION















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315


Reg. No: 199607198R GST Reg. No. 19-9607198-R
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R









51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SME 6622K

RE-INSPECTION



