

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22001228/AYA3Q2**Date:** 23/06/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210111726
Claimant Vehicle No :	SND868B	Insured Vehicle No :	SME3401B
Date of Loss:	09/02/2022	Nature of Claim:	TP
		Claim No:	6914613642SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SND868B	Engine No:	F4151394B38B15A
Make & Model:	BMW 318i, 1.5 SEDAN LED NAV (A)	Chassis No:	WBA8E36090NT89587
Reg. Date:	16/09/2016 (Man. Year: 2016)	Odometer:	73573 km
Colour:	Blue		
Engine Capacity:	1499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/35 R19	Rear Tyre Size:	235/35 R19
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,201.34	6,366.63	5,834.71	47.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,080.00	1,060.00	1,020.00	49.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,281.34	7,426.63	6,854.71	48.00
Approved Total (Overridden) (S\$)		5,900.00		
Nett Amount (S\$)	14,281.34	5,900.00	8,381.34	58.69
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	09/02/2022	
Date Inspected:	09/02/2022	Inspected At: Ryder Auto Pte Ltd (HQ) 2 Kaki Bukit Ave 2, #02-19 AutoHub @ Kaki Bukit Singapore 417921
Estimated Period of Repair:	4.0 days	

Adjuster: ADRIAN LING**Manager:** Ezlyna*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,395.20 FL	*1,395.20 FL
2	10		*FRONT BUMPER CLIPS	Necessary	100.00 FS	*30.00 FS
3	1		*FRONT O/S HEAD LAMP	Cracked	4,156.80 FL	*3,250.00 FL
4	1		*FRONT O/S FENDER	Repair	920.30 FL	*- FL
5	1		*FRONT O/S FENDER INNER TRIM	Not Necessary	156.70 FL	*- FL
6	6		*FRONT O/S FENDER INNER TRIM CLIPS	Not Necessary	60.00 FS	*- FS
7	1		*FRONT O/S FOG LAMP	Cracked	625.80 FL	*425.00 FL
8	1		*FRONT O/S FOG LAMP GARNISH	Cracked	120.50 FL	*120.50 FL
9	1		*FRONT O/S KNUCKLE	Not Necessary	634.70 FL	*- FL
10	1		*FRONT O/S BEARING	Not Necessary	645.20 FL	*- FL
11	1		*FRONT O/S UPPER ARM	Not Necessary	377.10 FL	*- FL
12	1		*FRONT O/S LOWER ARM	Not Necessary	377.10 FL	*- FL
13	1		*FRONT O/S STEERING BALL JOINT	Not Necessary	398.50 FL	*- FL
14	1		*FRONT O/S TIE ROD LINKAGE	Not Necessary	145.10 FL	*- FL
15	1		*FRONT ENFORCEMENT	Bent	484.50 FL	*484.50 FL
16	1		*FRONT BUMPER SPONGE	Cracked	130.40 FL	*130.40 FL
17	1		*FRONT O/S INTERCOOLER	Dented	584.70 FL	*584.70 FL
18	1		*FRONT O/S INTERCOOLER BRACKET	Not Necessary	82.50 FL	*- FL
19	1		*FRONT O/S INTERCOOLER COVER	Cracked	94.50 FL	*94.50 FL
20	1		*FRONT O/S HORN	Not Necessary	343.20 FL	*- FL
21	1		*FRONT BUMPER GRILLE LOWER	Cracked	310.20 FL	*310.20 FL
22	1		*FRONT O/S FOG LAMP BRACKET	Cracked	135.40 FL	*135.40 FL
23	1		*FRONT O/S FOG LAMP GARNISH STRIP	Cracked	110.30 FL	*110.30 FL
24	1		*FRONT O/S FENDER INNER TRIM	Not Necessary	446.40 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,835.10	7,070.70
- List Item Discount on L Items 5.00/10.00% (\$\$)	633.76	704.07
Total Parts (\$\$)	12,201.34	6,366.63

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE DAMAGED PARTS ,STRAIGHTEN & WELDING	New	800.00	400.00
2	TO SPRAY PAINTING	New	600.00	400.00
3	TO CHECK FOR FAULT CODE AND RESETTNG (HEAD LAMP)	New	250.00	180.00
4	TO REMOVE AND REFIT UNDER CARRIAGE	New	150.00	0.00
5	TO CHECK FRONT WHEEL ALIGNMENT	New	100.00	0.00
6	TO CHECK WIRING	New	80.00	30.00
7	TO RE SEAL ANTI RUST	New	100.00	50.00
Gross Labour Cost (\$\$)			2,080.00	1,060.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >