

WBA8E36090N789587

ESTIMATE OF REPAIR

Veh# : SND868B

Model:

BMW 318i
(16/9/2016)

Accident Date : 9/2/2022

Location : DEFU LANE 10 & DEFU AVE 1 JUCTION

3P:

SME3401B (AIG)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Front bumper <i>Rehanded</i>	1,395.20	100.00 30	
2	10 pcs	Front bumper clips <i>new</i>		100.00	
3	1 pc	Front o/s head lamp <i>cracked</i>	4,156.80	3250	
4	1 pc	Front o/s fender <i>Repair</i>	920.30	x	
5	1 pc	Front o/s fender inner trim <i>new</i>	156.70	x	
6	6pcs	Front o/s fender inner trim clips <i>new</i>		60.00	+
7	1 pc	Front o/s fog lamp <i>cracked</i>	625.80	425	
8	1 pc	Front o/s fog lamp garnish <i>cracked</i>	120.50	✓	
9	1 pc	Front o/s knuckle	634.70	x	
10	1 pc	Front o/s bearing	645.20	x	
11	1 pc	Front o/s upper arm	377.10	x	
12	1 pc	Front o/s lower arm	377.10	x	
13	1 pc	Front o/s steering ball joint	398.50	x	
14	1pc	Front o/s tie rod linkage	145.10	x	
Sub Total:			9,953.00	160.00	0.00
			5%	0%	10%
After Less %:			8,957.70	160.00	0.00
Labour					
1		To dismantle damaged parts, straighten & welding.		800.00 400	
2		To spray painting.		600.00 400	
3		To check for fault code and resetting (head lamp)		250.00 180	
4		To remove and refit under carriage		150.00 x	
5		To check front wheel alignment		100.00 x	
6		To check wiring.		80.00 30	
7		To re seal anti rust.		100.00 50	
Sub Total:				2,080.00	
Total:				11,197.70	

Chan San Choon
Director
DipEng, AAE, MIMI, MSAE (Auto)



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Mobil 1



Adrian Lij
L/S 09/02/22.

04 Days

Supplementary: 1665
Total: 742663
L/S: SSK

SUPPLEMENTARY ESTIMATE OF REPAIR

Veh# : SND868B

Model:

BMW 318i

Accident Date : 9/2/2022

(16/9/2016)

Location : DEFU LANE 10 & DEFU AVE 1 JUCTION

3P:

SME3401B (AIG)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1pc	Front enforcement <i>Bent</i>	484.50	✓	
2	1pc	Front bumper sponge <i>crushed</i>	130.40	✓	
3	1pc	Front o/s intercooler <i>Dented</i>	584.70	✓	
4	1pc	Front o/s intercooler bracket <i>Adaptation</i>	82.50	+	
5	1pc	Front o/s intercooler cover <i>crushed</i>	94.50	✓	
6	1pc	Front o/s horn <i>Adaptation</i>	343.20	+	
7	1pc	Front bumper grill lower <i>crushed</i>	310.20	✓	
8	1pc	Front o/s fog lamp bracket <i>crushed</i>	135.40	✓	
9	1pc	Front o/s fog lamp garnish strip <i>crushed</i>	110.30	✓	
10	1pc	Front o/s fender inner trim <i>Adaptation</i>	446.40	+	
		Sub Total:	2,722.10	0.00	0.00
			5%	0%	10%
		After Less %:	2,586.00	0.00	0.00
		Total:		2,586.00	
		After less 20%		2,068.80	

Chan San Choon
Director
DipEng, AAE MIMI,MSAE(Aust)



Supplementary: 1665