

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/ICS22001229/AQY3E2  
**Date:** 27/06/2022

### REFERENCE

Handling Insurer: ECICS Limited Policy No: MPC21P00260600  
**Claimant Vehicle No :** SFM8797S **Insured Vehicle No :** SMU7389T  
Date of Loss: 31/01/2022 Nature of Claim: TP Claim No: DMPC2200050H

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SFM8797S**  
Make & Model: TOYOTA PRIUS, 1.8 (A) Engine No: 2ZR4508932  
Reg. Date: 18/12/2009 (Man. Year: 2009) Chassis No: JTDKN36U301117068  
Colour: White Odometer: 395808 km  
Engine Capacity: 1798 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15  
Front Left Side: Firenza 6 mm Rear Left Side: Firenza 6 mm  
Front Right Side: Firenza 6 mm Rear Right Side: Firenza 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	26,364.90	5,187.65	21,177.25	80.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,820.00	2,020.00	6,800.00	77.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>35,184.90</b>	<b>7,207.65</b>	<b>27,977.25</b>	<b>79.51</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,700.00</b>		

**Nett Amount (S\$)**      **35,184.90**      **5,700.00**      **29,484.90**      **83.80**

---

**INSPECTION**

Date of Assignment:                      09/02/2022

Date Inspected:                              09/02/2022 Inspected At:

SR  
AUTOWORKS  
PTE LTD (HQ)  
8 Kaki Bukit  
Avenue 4,  
Premier @  
Kaki Bukit  
#02-24  
Singapore  
415875

Estimated Period of Repair:              8.0 days

---

**Adjuster: ADRIAN LING**

---

**Manager: SHIAU CHAN**

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Reference

**Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 23 Jun 2022)

**Parts:** 144 TOYOTA PRIUS 1.8 (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** LKK Auto Consultants Pte Ltd/SFM8797S/27/06/2022 11:52

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Not Necessary	1,359.00 FL	*- FL
2	1		*FRONT BUMPER	Deformed	670.00 FL	*670.00 FL
3	2		*FRONT BUMPER SIDE RETAINER	Necessary	250.00 FL	*250.00 FL
4	1		*FRONT BUMPER LOGO	Necessary	189.00 FL	*189.00 FL
5	1		*FRONT BUMPER TOP GRILLE	Not Necessary	298.50 FL	*- FL
6	2		*FRONT BUMPER FOG LAMP	Not Necessary	1,308.00 FL	*- FL
7	2		*FRONT BUMPER FOG LAMP COVER	Not Necessary	196.00 FL	*- FL
8	2		*FRONT BUMPER SIGNAL LAMP	Not Necessary	906.40 FL	*- FL
9	1		*FRONT BUMPER GRILLE BASE	Not Necessary	296.00 FL	*- FL
10	1		*FRONT BUMPER GRILLE AIR DUCT INNER	Not Necessary	54.00 FL	*- FL
11	1		*FRONT BUMPER NO PLATE GARNISH	Cracked	112.00 FL	*112.00 FL
12	1		*FRONT BUMPER TOP RUBBER	Not Necessary	68.00 FL	*- FL
13	1		*FRONT BUMPER LOWER BEAM	Not Necessary	485.00 FL	*- FL

LKK Auto Consultants Pte Ltd/SFM8797S/27/06/2022 11:52. Not valid without Reference section.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
14	2		<b>*FRONT BUMPER LOWER BEAM BRACKET</b>	Not Necessary	422.00 FL	*- FL
15	1		<b>*FRONT BUMPER LOWER ABSORBER</b>	Deformed	258.00 FL	*258.00 FL
16	1		<b>*FRONT BUMPER LOWER GRILLE</b>	Deformed	186.00 FL	*186.00 FL
17	1		<b>*FRONT BUMPER UNDER GARNISH</b>	Not Necessary	452.00 FL	*- FL
18	1		<b>*FRONT BUMPER REINFORCEMENT</b>	Dented	498.00 FL	*498.00 FL
19	1		<b>*FRONT BUMPER TOWING COVER</b>	Not Necessary	85.00 FL	*- FL
20	1		<b>*FRONT BUMPER SPONGE</b>	Cracked	185.00 FL	*185.00 FL
21	1		<b>*HEADLAMP</b>	N/S Cracked	5,378.00 FL	*1,099.00 FL
22	1		<b>*FRONT SUPPORT TOP PANEL</b>	Not Necessary	468.00 FL	*- FL
23	1		<b>*FRONT SUPPORT TOP GARNISH</b>	Not Necessary	289.00 FL	*- FL
24	2		<b>*FRONT SUPPORT AIR ARCH</b>	Not Necessary	48.00 FL	*- FL
25	1		<b>*TAILGATE</b>	Repair	1,126.00 FL	*- FL
26	1		<b>*TAILGATE QUARTER GLASS MOULDING</b>	Not Necessary	124.00 FL	*- FL
27	1		<b>*TAILGATE WINDSCREEN MOULDING</b>	Not Necessary	154.00 FL	*- FL
28	1		<b>*TAILGATE LOGO</b>	Not Necessary	185.00 FL	*- FL
29	1		<b>*TAILGATE EMBLEM (TOYOTA)</b>	Not Necessary	82.90 FL	*- FL
30	1		<b>*TAILGATE EMBLEM (PRIUS)</b>	Not Necessary	82.90 FL	*- FL
31	1		<b>*TAILGATE EMBLEM (HYBRID)</b>	Necessary	82.90 FL	*82.90 FL
32	1		<b>*TAILGATE OUTER GARNISH</b>	Not Necessary	889.70 FL	*- FL
33	2		<b>*TAILGATE SIDE STOPPER (OUTER)</b>	Not Necessary	110.00 FL	*- FL
34	2		<b>*TAILGATE SIDE STOPPER (INNER)</b>	Not Necessary	100.00 FL	*- FL

LKK Auto Consultants Pte Ltd/SFM8797S/27/06/2022 11:52. Not valid without Reference section.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
35	1		<b>*TAILGATE INNER LOCK</b>	Not Necessary	457.90 FL	*- FL
36	1		<b>*TAILGATE WEATHERSTRIP</b>	Not Necessary	365.20 FL	*- FL
37	1		<b>*TAILGATE INNER LOWER TRIM BOARD</b>	Not Necessary	524.00 FL	*- FL
38	1		<b>*TAILGATE DETECTOR SENSOR</b>	Cracked	482.40 FL	*135.00 FL
39	2		<b>*TAILGATE HINGE</b>	Not Necessary	178.00 FL	*- FL
40	2		<b>*TAILGATE ABSORBER</b>	Not Necessary	554.00 FL	*- FL
41	1		<b>*TAILLAMP</b>	N/S Cracked	2,231.60 FL	*493.00 FL
42	2		<b>*TAILLAMP SIDE COVER</b>	Not Necessary	512.00 FL	*- FL
43	1		<b>*REAR BUMPER</b>	Deformed	658.00 FL	*658.00 FL
44	1		<b>*REAR LOWER BUMPER</b>	Deformed	552.60 FL	*345.00 FL
45	1		<b>*REAR BUMPER SIDE RETAINER</b>	Necessary	120.00 FL	*120.00 FL
46	1		<b>*REAR BUMPER REINFORCEMENT</b>	Dented	318.40 FL	*318.40 FL
47	1		<b>*REAR BUMPER TOWING COVER</b>	Not Necessary	66.00 FL	*- FL
48	1		<b>*REAR BUMPER LOWER SIDE GARNISH</b>	N/S Deformed	754.00 FL	*377.00 FL
49	1		<b>*REAR BUMPER UNDER COVER CENTER</b>	Deformed	258.00 FL	*258.00 FL
50	2		<b>*REAR BUMPER UNDER COVER SIDE</b>	Not Necessary	508.00 FL	*- FL
51	1		<b>*REAR WIRE HARNESS</b>	Not Necessary	653.70 FL	*- FL
52	1		<b>*END PANEL</b>	Repair	611.80 FL	*- FL
53	1		<b>*END PANEL TOP GARNISH</b>	Deformed	175.90 FL	*175.90 FL
54	1		<b>*REAR FLOOR PANEL</b>	Repair	845.00 FL	*- FL
55	1		<b>*REAR FLOOR PANEL TOP BOARD</b>	Not Necessary	685.00 FL	*- FL
56	2		<b>*REAR FLOOR PANEL TOOL BOX</b>	Not Necessary	1,128.60 FL	*- FL

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
57	2		<b>*REAR FENDER INNER TRIM</b>	Not Necessary	1,311.40 FL	*- FL
58	2		<b>*REAR FENDER INNER SHIELD</b>	Not Necessary	450.00 FL	*- FL
59	1		<b>*REAR EXHAUST SILENCER</b>	Not Necessary	1,163.40 FL	*- FL
60	2		<b>*REAR EXHAUST MOUNTING</b>	Not Necessary	99.40 FL	*- FL
61	1		<b>*REAR EXHAUST GASKET</b>	Not Necessary	56.00 FL	*- FL
62	1		<b>*REAR EXHAUST HEAT PLATE</b>	Not Necessary	314.60 FL	*- FL
63	1		<b>*FRONT NUMBER PLATE</b>	Dented	50.00 FS	*50.00 FS
64	1		<b>*FRONT BUMPER CLIPS</b>	Necessary	50.00 FS	*30.00 FS
65	1		<b>*COOLANT</b>	Not Necessary	80.00 FS	*- FS
66	1		<b>*TAILGATE CENTER MOULDING CLIP</b>	Not Necessary	50.00 FS	*- FS
67	1		<b>*TAILGATE INNER BOARD CLIP</b>	Not Necessary	50.00 FS	*- FS
68	1		<b>*TAILGATE WINDSCREEN SEALANT</b>	Not Necessary	80.00 FS	*- FS
69	1		<b>*TAILGATE WINDSCREEN INNER SEAL</b>	Not Necessary	50.00 FS	*- FS
70	1		<b>*TAILGATE QUARTER GLASS INNER SEAL</b>	Not Necessary	80.00 FS	*- FS
71	1		<b>*TAILGATE QUARTER GLASS SEALANT</b>	Not Necessary	60.00 FS	*- FS
72	1		<b>*REAR BUMPER CLIP</b>	Necessary	60.00 FS	*30.00 FS
73	1		<b>*REVERSE SENSOR</b>	Damaged	380.00 FS	*200.00 FS
74	1		<b>*TAIL LAMP CLIP</b>	Necessary	30.00 FS	*10.00 FS
75	1		<b>*REAR END PANEL SEALANT</b>	Necessary	80.00 FS	*60.00 FS
76	1		<b>*REAR FLOOR PANEL SEALANT</b>	Not Necessary	80.00 FS	*- FS
77	1		<b>*REAR FENDER INNER TRIM CLIP</b>	Not Necessary	60.00 FS	*- FS
78	1		<b>*REAR FENDER INNER SHIELD CLIP</b>	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

**LKK Auto Consultants Pte Ltd/SFM8797S/27/06/2022 11:52.** Not valid without Reference section.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				<b>Sub Total (S\$)</b>	<b>34,723.20</b>	<b>6,790.20</b>
				<b>- List Item Discount on L Items 25.00/25.00% (S\$)</b>	<b>8,358.30</b>	<b>1,602.55</b>
				<b>Total Parts (S\$)</b>	<b>26,364.90</b>	<b>5,187.65</b>

LKK Auto Consultants Pte Ltd/SFM8797S/27/06/2022 11:52. Not valid without Reference section.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	PANEL BEATING, REMOVAL AND REPLACING PARTS. (FRONT)	New	1,400.00	300.00
2	TO SPRAY PAINT AFFECTED AREA. (FRONT)	New	1,400.00	250.00
3	TUFF COAT. (FRONT)	New	250.00	0.00
4	WIRING AND BULB CHECK. (FRONT)	New	50.00	30.00
5	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL GAS. (FRONT)	New	200.00	0.00
6	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST. (FRONT)	New	200.00	0.00
7	TO SPRAY PAINT AFFECTED AREA. (REAR)	New	1,600.00	700.00
8	WIRING AND BULB CHECK. (REAR)	New	50.00	30.00
9	REMOVE AND REFIX TAILGATE WINDSCREEN. (REAR)	New	150.00	0.00
10	REMOVE AND REFIX TAILGATE QUARTER GLASS. (REAR)	New	150.00	0.00
11	TRANSFER TAILGATE MECHANISM. (REAR)	New	150.00	0.00
12	CONDUCT WATER LEAKAGE TEST. (REAR)	New	100.00	0.00
13	REMOVE AND REFIT REAR RACK TO FACILITATE REPAIR. (REAR)	New	300.00	0.00

No	Particulars	Lab.Type	Repairer's	Amount
14	REMOVE AND REFIX TRIM, FLOOR MAT AND INTERIOR. (REAR)	New	350.00	0.00
15	REMOVE AND REFIX REAR REVERSE SENSOR. (REAR)	New	120.00	50.00
16	REMOVE AND REFIX REAR EXHAUST SYSTEM. (REAR)	New	300.00	0.00
17	REMOVE AND REFIX CUSHION SEAT / UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR. (REAR)	New	250.00	60.00
18	PANEL BEATING, REMOVAL AND REPLACING PARTS. (REAR)	New	1,800.00	600.00
<b>Gross Labour Cost (S\$)</b>			<b>8,820.00</b>	<b>2,020.00</b>

LKK Auto Consultants Pte Ltd/SFM8797S/27/06/2022 11:52. Not valid without Reference section.

**< END OF ESTIMATES >**