

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)  
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
 Singapore 408933  
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI22001233/AQY3M4  
**Date:** 04/07/2022

### REFERENCE

|                       |                                               |                      |                        |
|-----------------------|-----------------------------------------------|----------------------|------------------------|
| Handling Insurer:     | China Taiping Insurance (Singapore) Pte. Ltd. | Policy No:           | DMCVSNW00151062102     |
| Claimant Vehicle No : | GBJ8151T                                      | Insured Vehicle No : | GBK521G                |
| Date of Loss:         | 06/02/2022                                    | Nature of Claim:     | TP                     |
|                       |                                               | Claim No:            | SNM22D200938/C02/TANKW |

### DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                   |             |             |
|-----------------------------|-----------------------------------|-------------|-------------|
| Reg No:                     | GBJ8151T                          | Engine No:  | HR16136554D |
| Make & Model:               | NISSAN NV200, 1.6 VANETTE DX (A)  | Chassis No: | VM20129887  |
| Reg. Date:                  | 04/09/2019 (Man. Year: 2018)      | Odometer:   | 87406 km    |
| Colour:                     | Silver                            |             |             |
| Engine Capacity:            | 1597 cc                           |             |             |
| Market Value/New Car Price: | N/A                               |             |             |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |             |

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

### CONDITION OF TYRES

|                   |                |                  |                |
|-------------------|----------------|------------------|----------------|
| Front Tyre Size:  | 175/70 R14C    | Rear Tyre Size:  | 175/70 R14C    |
| Front Left Side:  | Windforce 6 mm | Rear Left Side:  | Windforce 6 mm |
| Front Right Side: | Windforce 6 mm | Rear Right Side: | Windforce 6 mm |

*The above values represent the remaining tyre treads depth*

| COST OF CLAIMS                           | Repairer's       | Adjuster's      | Difference       | Diff %       |
|------------------------------------------|------------------|-----------------|------------------|--------------|
| Parts                                    | 17,405.13        | 4,483.90        | 12,921.23        | 74.24        |
| Miscellaneous Items                      | 0.00             | 0.00            | 0.00             |              |
| Labour                                   | 5,670.00         | 1,830.00        | 3,840.00         | 67.72        |
| Paintwork Labour                         | 0.00             | 0.00            | 0.00             |              |
| Towing                                   | 0.00             | 0.00            | 0.00             |              |
| <b>Calculated Gross Total (S\$)</b>      | <b>23,075.13</b> | <b>6,313.90</b> | <b>16,761.23</b> | <b>72.64</b> |
| <b>Approved Total (Overridden) (S\$)</b> |                  | <b>5,000.00</b> |                  |              |
| <b>Nett Amount (S\$)</b>                 | <b>23,075.13</b> | <b>5,000.00</b> | <b>18,075.13</b> | <b>78.33</b> |

### INSPECTION

|                             |            |                                                                                                                       |
|-----------------------------|------------|-----------------------------------------------------------------------------------------------------------------------|
| Date of Assignment:         | 11/02/2022 |                                                                                                                       |
| Date Inspected:             | 09/02/2022 | Inspected At: HD Perfect Autowork Pte Ltd (HQ)<br>8 Kaki Bukit Ave 4, #08-09 Premier @ Kaki Bukit<br>Singapore 415875 |
| Estimated Period of Repair: | 6.0 days   |                                                                                                                       |

**Adjuster:** ADRIAN LING

**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

### Reference

|                      |                                                                                                                                                                              |                                                                   |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------|
| <b>Part Source:</b>  | (Last Synchronised: 04 Jul 2022)                                                                                                                                             |                                                                   |
| <b>Parts:</b>        | N/A                                                                                                                                                                          | NISSAN NV200 1.6 VANETTE DX (A) (Model not available in database) |
| <b>Labour:</b>       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                                 |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for GBJ8151T)                                                                                                                                    |                                                                   |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                                   |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                                   |

### Recommended Parts

| No. | Qty | Part No. | Particulars                               | Condition     | Repairer's  | Amount       |
|-----|-----|----------|-------------------------------------------|---------------|-------------|--------------|
| 1   | 1   |          | *REAR BUMPER                              | Deformed      | 566.90 FL   | *566.90 FL   |
| 2   | 1   |          | *REAR BUMPER SPONGE                       | Cracked       | 145.89 FL   | *145.89 FL   |
| 3   | 2   |          | *REAR BUMPER SIDE RETAINER                | Necessary     | 79.40 FL    | *79.40 FL    |
| 4   | 1   |          | *TAILGATE                                 | Dented        | 2,080.40 FL | *1,659.00 FL |
| 5   | 2   |          | *TAILGATE STOPPER                         | Not Necessary | 42.80 FL    | *- FL        |
| 6   | 1   |          | *TAILGATE LOGO                            | Necessary     | 67.50 FL    | *67.50 FL    |
| 7   | 1   |          | *TAILGATE NV200 EMBLEM                    | Necessary     | 66.30 FL    | *66.30 FL    |
| 8   | 1   |          | *TAILGATE VENETTE EMBLEM                  | Necessary     | 68.50 FL    | *68.50 FL    |
| 9   | 1   |          | *TAILGATE OUTER MOULDING                  | Cracked       | 389.50 FL   | *389.50 FL   |
| 10  | 1   |          | *TAILGATE OUTER LOCK HANDLE               | Not Necessary | 279.40 FL   | *- FL        |
| 11  | 1   |          | *TAILGATE LOWER LOCK CENTER COVER GARNISH | Deformed      | 235.50 FL   | *235.50 FL   |
| 12  | 1   |          | *TAILGATE INNER LOCK                      | Damaged       | 271.40 FL   | *271.40 FL   |
| 13  | 1   |          | *TAILGATE INNER HANDLE                    | Not Necessary | 217.30 FL   | *- FL        |
| 14  | 1   |          | *TAILGATE INNER TRIM                      | Not Necessary | 368.70 FL   | *- FL        |
| 15  | 1   |          | *TAILGATE WEATHERSTRIP                    | Cut           | 316.80 FL   | *316.80 FL   |
| 16  | 1   |          | *TAIL LAMP                                | N/s Cut       | 589.20 FL   | *294.60 FL   |
| 17  | 1   |          | *TAIL LAMP PANEL LH                       | Repair        | 434.70 FL   | *- FL        |
| 18  | 1   |          | *REAR SIDE PANEL LH                       | Not Necessary | 1,540.20 FL | *- FL        |
| 19  | 1   |          | *REAR SIDE INNER PANEL LH                 | Not Necessary | 1,769.40 FL | *- FL        |
| 20  | 1   |          | *REAR INNER CORNER PANEL LH (LOWER)       | Repair        | 476.40 FL   | *- FL        |
| 21  | 1   |          | *REAR END PANEL (OUTER)                   | Dented        | 598.60 FL   | *598.60 FL   |
| 22  | 1   |          | *REAR END PANEL (INNER)                   | Repair        | 1,489.50 FL | *- FL        |
| 23  | 1   |          | *REAR FLOOR PANEL MAT                     | Not Necessary | 1,219.80 FL | *- FL        |
| 24  | 1   |          | *REAR FLOOR PANEL                         | Repair        | 1,696.90 FL | *- FL        |
| 25  | 1   |          | *REAR FLOOR CORNER EXTEND PANEL LH        | Not Necessary | 294.10 FL   | *- FL        |
| 26  | 1   |          | *REAR SPARE TYRE BRACKET                  | Not Necessary | 439.70 FL   | *- FL        |
| 27  | 1   |          | *REAR SPARE TYRE BRACKET BOLT             | Not Necessary | 72.10 FL    | *- FL        |
| 28  | 1   |          | *REAR EXHAUST PIPE                        | Not Necessary | 759.40 FL   | *- FL        |
| 29  | 1   |          | *REAR EXHAUST MOUNTING                    | Not Necessary | 43.20 FL    | *- FL        |
| 30  | 1   |          | *SET REAR EXHAUST GASKET                  | Not Necessary | 75.10 FL    | *- FL        |
| 31  | 1   |          | *REAR NUMBER PLATE                        | Not Necessary | 50.00 FS    | *- FS        |
| 32  | 1   |          | *SET REAR BUMPER CLIP                     | Necessary     | 50.00 FS    | *30.00 FS    |
| 33  | 1   |          | *SET TAIL LAMP CLIP                       | Necessary     | 30.00 FS    | *10.00 FS    |
| 34  | 2   |          | *TAIL LAMP PANEL SEALANT                  | Not Necessary | 120.00 FS   | *- FS        |
| 35  | 1   |          | *TAILGATE STICKER 70KM/H                  | Necessary     | 30.00 FS    | *15.00 FS    |
| 36  | 1   |          | *TAILGATE STICKER 5PAX                    | Necessary     | 40.00 FS    | *15.00 FS    |
| 37  | 1   |          | *SET TAILGATE INNER TRIM CLIP             | Not Necessary | 50.00 FS    | *- FS        |
| 38  | 1   |          | *TAILGATE WINDSCREEN SEALANT              | Necessary     | 80.00 FS    | *40.00 FS    |
| 39  | 1   |          | *TAILGATE WINDSCREEN INNER SEAL           | Necessary     | 60.00 FS    | *30.00 FS    |
| 40  | 1   |          | *REAR SIDE INNER PANEL SEALANT            | Not Necessary | 300.00 FS   | *- FS        |
| 41  | 1   |          | *REAR INNER SIDE PANEL SEALANT            | Not Necessary | 300.00 FS   | *- FS        |
| 42  | 1   |          | *REAR END PANEL (OUTER) SEALANT           | Necessary     | 150.00 FS   | *60.00 FS    |

Report was unsubmitted during this print-out.

| No.                                           | Qty | Part No. | Particulars                     | Condition                                           | Repairer's | Amount   |
|-----------------------------------------------|-----|----------|---------------------------------|-----------------------------------------------------|------------|----------|
| 43                                            | 1   |          | *REAR END PANEL (INNER) SEALANT | Not Necessary                                       | 150.00 FS  | *- FS    |
| 44                                            | 1   |          | *REAR FLOOR PANEL SEALANT       | Not Necessary                                       | 250.00 FS  | *- FS    |
| 45                                            | 1   |          | *REAR SPARE TYRE                | Not Necessary                                       | 500.00 FS  | *- FS    |
| 46                                            | 1   |          | *SET REVERSE SENSOR             | Not Necessary                                       | 220.00 FS  | *- FS    |
| F=Franchise part. S=SpcNett. L=ListItemDisc.  |     |          |                                 |                                                     |            |          |
|                                               |     |          |                                 | Sub Total (\$\$)                                    | 19,074.59  | 4,959.89 |
|                                               |     |          |                                 | - List Item Discount on L Items 10.00/10.00% (\$\$) | 1,669.46   | 475.99   |
|                                               |     |          |                                 | Total Parts (\$\$)                                  | 17,405.13  | 4,483.90 |
| Report was unsubmitted during this print-out. |     |          |                                 |                                                     |            |          |

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                       | Particulars                                                                                   | Lab.Type | Repairer's      | Amount          |
|--------------------------|-----------------------------------------------------------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>      |                                                                                               |          |                 |                 |
| 1                        | PANEL BEATING AND REPLACE PARTS                                                               | New      | 2,400.00        | 800.00          |
| 2                        | SPRAY PAINTING TO AFFECTED AREA                                                               | New      | 2,000.00        | 800.00          |
| 3                        | WIRING, BULB CHECKING                                                                         | New      | 180.00          | 30.00           |
| 4                        | TRANSFER TAILGATE MECHANISM                                                                   | New      | 80.00           | 80.00           |
| 5                        | CONDUCT WATER LEAKAGE TEST                                                                    | New      | 120.00          | 0.00            |
| 6                        | REAR CHASSIS ALIGNMENT                                                                        | New      | 250.00          | 0.00            |
| 7                        | REMOVE AND REFIX REAR REVERSE SENSOR                                                          | New      | 80.00           | 0.00            |
| 8                        | REMOVE AND REFIX REAR WINDSCREEN                                                              | New      | 120.00          | 120.00          |
| 9                        | REMOVE AND REFIX FUEL TANK TO FACILIATE FENDER REPLACEMENT                                    | New      | 80.00           | 0.00            |
| 10                       | REMOVE AND REFIX REAR EXHAUST PIPE                                                            | New      | 180.00          | 0.00            |
| 11                       | TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC | New      | 180.00          | 0.00            |
| Gross Labour Cost (\$\$) |                                                                                               |          | <b>5,670.00</b> | <b>1,830.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >