

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22001234/AVY3N2**Date:** 23/05/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMHCSNW00008152100

Claimant Vehicle No : GBG2779M **Insured Vehicle No :** SGX914D

Date of Loss: 30/01/2022 Nature of Claim: TP Claim No: SNM22D200907/C02/TANKW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBG2779M**

Make & Model: TOYOTA DYNA 150 MANUAL, 3.0 D (M) Engine No: 1KD2700475

Reg. Date: 03/07/2017 (Man. Year: 2017) Chassis No: JTFAT35Y50K208026

Colour: Silver Odometer: 158056 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195R15C Rear Tyre Size: 155R12C

Front Left Side: Habilead 6 mm Rear Left Side: Lingam 6 mm

Front Right Side: Habilead 6 mm Rear Right Side: Lingam 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,486.44	3,500.50	1,985.94	36.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,960.00	1,300.00	660.00	33.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	7,446.44	4,800.50	2,645.94	35.53
Approved Total (Overridden) (\$\$)		3,800.00		
(\$\$)	7,446.44	3,800.00	3,646.44	48.97
+ GST 7.00/7.00% (\$\$)	521.25	266.00	255.25	48.97
Nett Amount (\$\$)	7,967.69	4,066.00	3,901.69	48.97

INSPECTION

Date of Assignment: 09/02/2022

Date Inspected: 09/02/2022 Inspected At: N-51 Automotive Pte Ltd (HQ)
BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT
AUTOHUB
Singapore 417921

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 20 May 2022)	
Parts:	N/A	TOYOTA DYNA 150 MANUAL 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBG2779M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR EXHAUST SILENCER PIPE	Bent	618.30 FL	*618.30 FL
2	1		*REAR EXHAUST SILENCER PIPE RUBBER MOUNTING	Torn	61.10 FL	*61.10 FL
3	2		*REAR LOWER SIDE STOPPER BRACKET L/R	Bent	197.20 FL	*197.20 FL
4	2		*REAR LOWER SIDE STOPPER L/R	N/s Torn/O/s Missing	86.20 FL	*86.20 FL
5	2		*REAR NUMBER PLATE LAMP L/R	Cracked	121.40 FL	*121.40 FL
6	1		*REAR NUMBER PLATE PANEL	Bent	228.60 FL	*228.60 FL
7	1		*REAR NUMBER PLATE PANEL BRACKET	Bent	57.10 FL	*57.10 FL
8	1		*REAR SPARE TYRE CARRIER	Damaged	295.30 FL	*295.30 FL
9	1		*REAR TAILGATE	Dented	1,116.70 FL	*1,116.70 FL
10	1		*REAR TAILGATE TOYOTA STICKER	Necessary	238.90 FL	*238.90 FL
11	1		*REAR TAILGATE HINGES	Bent (2 Pcs only)	416.00 FL	*208.00 FL
			4 Pcs			
12	1		*REAR TAILGATE LOWER PANEL	Repair	585.80 FL	*- FL
13	2		*REAR TAILLAMP BRACKET L/R	Bent	123.60 FL	*123.60 FL
14	2		*REAR TAILLAMP L/R	Cut	502.60 FL	*502.60 FL
15	1		*SIDE GATE FLIP LOCK HANDLE L/R	O/s Bent	278.00 FL	*139.00 FL
16	1		*SET ALUMINIUM PANEL REPAIR KIT	Not Necessary	150.00 FS	*- FS
17	1		*REAR NUMBER PLATE	Bent	25.00 FS	*25.00 FS
18	1		*SET REAR REVERSE SENSOR	Damaged	250.00 FS	*200.00 FS
19	1		*SET REAR REVERSE SENSOR BRACKET	Damaged	80.00 FS	*40.00 FS
20	1		*REAR STEP BRACKET	Bent	300.00 FS	*200.00 FS
21	1		*REAR TAILGATE 13 PAX STICKER	Necessary	20.00 FS	*20.00 FS
22	1		*REAR TAILGATE 70KM/H STICKER	Necessary	20.00 FS	*20.00 FS
23	1		*REAR TAILGATE ALUMINIUM PANEL	Not Necessary	700.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,471.80	4,499.00
- List Item Discount on L Items 20.00/25.00% (\$\$)	985.36	998.50
Total Parts (\$\$)	5,486.44	3,500.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,REINSTALL ELECTRICAL WIRING HARNESS,CHECK LIGHTING AND REWIRE FOR PARKING SENSOR	New	60.00	60.00
2	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS,REPAIR PORTION,AND WHERE CONSISTENT TO THE ACCIDENT	New	800.00	500.00
3	TO REMOVE AND CHANGE EXHAUST SILENCER BOX WITH PIPE,RE-ALIGN WHERE NECESSARY CONSISTENT TO THE ACCIDENT	New	120.00	80.00
4	TO PROVIDE LABOUR,WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS,REPAIR,RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	900.00	600.00
5	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	80.00	60.00
Gross Labour Cost (\$\$)			1,960.00	1,300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >