

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	LONPAC INSURAN		Ref:	CS3/LPC22001235/Eqf3e2		
	300 BEACH ROAD SINGAPORE 1995	#17-04/07 THE CONCOURSE 55		Date:	14/02/2022	
				Code:	LPC2	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	GBD 9704Z	Veh. Inspected		GBF 6427H	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	21/22/22/VC00/025441	Excess (\$)		0.00	
	Assign From	GERALD POH	Assign Date		09/02/2022	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA HIACE	c.c		2982	
	Engine No.	HIDDEN	Year of Reg.		2017	
	Chassis No.	JTFHT02P900213962	Colour		SILVER	
	Odometer	106509 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195 R15C	GOODYEAR		4 mm	
	L/H Front Tyre	195 R15C	GOODYEAR		4 mm	
	R/H Rear Tyre	195 R15C	GOODYEAR		4 mm	
	L/H Rear Tyre	195 R15C	GOODYEAR		4 mm	
4. Description of Damages						
	THE VEHICLE SUS	STAINED DAMAGES AT THE REAR PORTION.				
5.	General Information					
	Accident Date	08/02/2022	Inspect Date / 1	Гime	10/02/2022 (10:31 AM)	
	Survey held at	eld at V-TECH AUTO SERVICE				
		No.1 SOON LEE STREET #06-04/05/06/07 PIONEER CENTRE SINGAPORE 627605				
5a.	5a. Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					

Report Ref No. CS3/LPC22001235/Eqf3e2

Inspected By

CHEN TSUE YEE

Automotive Assessor

M

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser