

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22001236/UTY3E2

Date: 04/03/2022

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00039892104
Claimant Vehicle No: FBP9753T Insured Vehicle No: XD7136R
Date of Loss: 07/02/2022 Nature of Claim: TP Claim No: SNM22D200862/C02/TANKW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBP9753T**
Make & Model: HONDA SUPRA GTR 150, 149cc Engine No: KB21E1083625
Reg. Date: 06/07/2019 (Man. Year: 2019) Chassis No: MH1KB2118KK086603
Colour: Black Odometer: 12917 km
Engine Capacity: 149 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 90-80-17 Rear Tyre Size: 120-70-17
Front Left Side: IRC 7 mm Rear Left Side: IRC 7 mm
Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,080.00	2,596.00	1,484.00	36.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	700.00	280.00	420.00	60.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,780.00	2,876.00	1,904.00	39.83
Approved Total (Overridden) (S\$)		2,200.00		
(S\$)	4,780.00	2,200.00	2,580.00	53.97
+ GST 7.00/7.00% (S\$)	334.60	154.00	180.60	53.97
Nett Amount (S\$)	5,114.60	2,354.00	2,760.60	53.97

INSPECTION

Date of Assignment: 09/02/2022
Date Inspected: 10/02/2022 Inspected At: New Union Company (HQ)
BLK 9004 TAMPINES STREET 93 #01-106
Singapore 528838
Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 04 Mar 2022)	
Parts:	N/A	HONDA SUPRA GTR 150 149cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBP9753T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER SET OUTER ASSY	Cracked	650.00 F	*650.00 FL
2	1		*COVER SET INNER ASSY	Cracked	285.00 F	*285.00 FL
3	1		*FORK OUTER	Bent	180.00 F	*180.00 FL
4	1		*FORK OIL	Necessary	20.00 F	*20.00 FL
5	1		*FORK INNER TUBE	Twisted	100.00 F	*100.00 FL
6	1		*RIM SHAFT, FRONT	Bent	65.00 F	*65.00 FL
7	1		*MAIN STAND	Not Necessary	120.00 F	*- FL
8	1		*SIDE STAND	Not Necessary	55.00 F	*- FL
9	1		*EXHAUST	Repair	120.00 F	*- FL
10	1		*HANDLE BAR	Bent	180.00 F	*180.00 FL
11	1		*SIGNAL SET (PAIR), FRONT	Cracked	250.00 F	*250.00 FL
12	1		*HEAD LAMP ASSY	Not Necessary	220.00 F	*- FL
13	1		*STEERING CORN	Necessary	120.00 F	*80.00 FL
14	1		*FORK SEAL SET (PAIR)	Necessary	60.00 F	*60.00 FL
15	1		*METER STAY BRACKET	Not Necessary	105.00 F	*- FL
16	1		*CLUTCH LEVER	Not Necessary	35.00 F	*- FL
17	1		*HEAD LAMP STAY BRACKET	Bent	220.00 F	*220.00 FL
18	1		*HORN	Dented	65.00 F	*65.00 FL
19	1		*BRAKE LEVER	Not Necessary	35.00 F	*- FL
20	1		*NO. PLATE, FRONT	Not Necessary	25.00 F	*- FL
21	1		*BOX, CARRIER	Cut	250.00 F	*250.00 FL
22	1		*HANDLE GRIP RUBBER (PAIR)	Not Necessary	45.00 F	*- FL
23	1		*HANDLE BALANCER (PAIR)	Scratched	75.00 F	*75.00 FL
24	1		*IU	Not Necessary	195.00 F	*- FL
25	2		*WHEEL BEARINGS, FRONT	Damaged	80.00 F	*80.00 FL
26	1		*BRAKE DISC FRONT	Bent	80.00 F	*80.00 FL
27	1		*RIM BUSS, FRONT	Not Necessary	35.00 F	*- FL
28	1		*FRONT RIM (LOCAL REPAIR)	Warped	120.00 FS	*120.00 FS
29	1		*SET MIRROR	Cut	55.00 FS	*55.00 FS
30	1		*EXHAUST COVER	Cut	45.00 FS	*45.00 FS
31	1		*CARRIER BACK	Not Necessary	75.00 FS	*- FS
32	1		*IU BRACKET	Not Necessary	35.00 F	*- FL
33	2		*WHEEL BEARINGS, REAR	Not Necessary	80.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,080.00	2,860.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	264.00
Total Parts (\$\$)	4,080.00	2,596.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING	New	50.00	0.00
2	CHASSIS	New	350.00	0.00
3	LABOR CHARGE	New	300.00	280.00
Gross Labour Cost (\$)			700.00	280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >