

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22001237/BQY3Q2**Date:** 14/03/2022REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00015382200

**Claimant Vehicle No :** SLL7476J **Insured Vehicle No :** SNC5641K

Date of Loss: 21/01/2022 Nature of Claim: TP Claim No: SNM22D200599/C02/CSC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLL7476J**

Make & Model: MITSUBISHI ATTRAGE, 1.2 (A) Engine No: 3A92UDP6785

Reg. Date: 09/03/2017 (Man. Year: 2016) Chassis No: MMBSTA13AHH004138

Colour: Red Odometer: 35824 km

Engine Capacity: 1193 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 185/55 R16 Rear Tyre Size: 185/55 R16

Front Left Side: Yokohama 5 mm Rear Left Side: Yokohama 5 mm

Front Right Side: Yokohama 5 mm Rear Right Side: Yokohama 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	12,793.86	5,534.58	7,259.28	56.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,400.00	2,120.00	2,280.00	51.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>17,193.86</b>	<b>7,654.58</b>	<b>9,539.28</b>	<b>55.48</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>6,100.00</b>		
<b>(S\$)</b>	17,193.86	6,100.00	11,093.86	64.52
<b>+ GST 7.00/7.00% (S\$)</b>	1,203.57	427.00	776.57	64.52
<b>Nett Amount (S\$)</b>	<b>18,397.43</b>	<b>6,527.00</b>	<b>11,870.43</b>	<b>64.52</b>

INSPECTION

Date of Assignment: 15/02/2022

Date Inspected: 09/02/2022 Inspected At: 160 SIN MING DR  
#01-14 SIN MING AUTO CITY  
SINGAPORE 575722  
Repairer: Team Autopro Pte Ltd (Sin Ming)

Estimated Period of Repair: 10.0 days

**Adjuster:** Lim Teow Guan**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 13 Mar 2022)	
<b>Parts:</b> 143	MITSUBISHI ATTRAGE 1.2 (A) (Catalogue:Merimen Singapore 1.0)	
<b>Labour:</b> Repairer's	(Price-denominated Standard List)	
<b>Print Code:</b>	(Unsubmitted, no print-code for SLL7476J)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Dented	894.10 FL	*695.00 FL
2	1		*BONNET LOCK ASSY	Not Damaged	134.60 FL	*- FL
3	2		*BONNET HINGE	Bent	176.00 FL	*176.00 FL
4	1		*FRONT BUMPER	Broken	791.00 FL	*687.20 FL
5	1		*FRONT BUMPER LOWER GRILLE	Broken	326.00 FL	*168.00 FL
6	1		*FRONT BUMPER REINFORCEMENT	Dented	486.00 FL	*350.00 FL
7	1		*FRONT BUMPER FOG LAMP RH	Not Damaged	458.00 FL	*- FL
8	1		*FRONT BUMPER FOG LAMP OUTER GARNISH RH	Broken	365.00 FL	*138.50 FL
9	1		*FRONT BUMPER TOW CAP	Missing	71.00 FL	*36.00 FL
10	2		*HEADLAMP ASSY	Broken	1,709.60 FL	*1,709.60 FL
11	1		*HEADLAMP BRACKET RH	Not Damaged	176.00 FL	*- FL
12	1		*FRONT GRILLE	Broken	830.00 FL	*549.00 FL
13	1		*FRONT GRILLE LOGO	Necessary	78.00 FL	*45.00 FL
14	1		*FRONT GRILLE INNER PANEL	Not Necessary	299.80 FL	*- FL
15	1		*FRONT GRILLE CHROME	No such part	168.00 FL	*- FL
16	1		*FRONT FENDER RH	Dented	695.30 FL	*438.90 FL
17	1		*FRONT FENDER INNER COWLING RH	Torn	164.80 FL	*98.00 FL
18	1		*FRONT FENDER EMBLEM ECO	Necessary	85.00 FL	*59.00 FL
19	1		*FRONT SUPPORT TOP PANEL	Bent	898.00 FL	*799.00 FL
20	1		*FRONT SUPPORT TOP PANEL GARNISH	No such part	185.00 FL	*- FL
21	1		*FRONT WHEEL HOUSE PANEL RH	Not Necessary	920.40 FL	*- FL
22	1		*RADIATOR	Not Damaged	1,287.90 FL	*- FL
23	1		*AIRCON CONDENSER	Not Damaged	1,185.00 FL	*- FL
24	1		*WIPER WASHER TANK	Bent	410.00 FL	*67.00 FL
25	1		*WIPER WASHER TANK MOTOR	Not Damaged	288.90 FL	*- FL
26	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
27	1		*BONNET SEALANT	Necessary	100.00 FS	*30.00 FS
28	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
29	2		*FRONT BUMPER SIDE RETAINER	Not Necessary	178.80 FS	*- FS
30	1		*FRONT BUMPER LOWER GRILLE CLIPS	No such part	50.00 FS	*- FS
31	1		*FRONT GRILLE CLIPS	No such part	50.00 FS	*- FS
32	1		*FRONT FENDER SEALANT	No such part	100.00 FS	*- FS
33	1		*FRONT FENDER INNER COWLING CLIPS	Necessary	50.00 FS	*30.00 FS
34	1		*FRONT SUPPORT TOP PANEL SEALANT	Necessary	100.00 FS	*30.00 FS
35	1		*FRONT SUPPORT TOP PANEL GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
36	1		*RADIATOR COOLANT	Not Necessary	80.00 FS	*- FS
37	1		*AIRCON FLUID	Not Necessary	80.00 FS	*- FS
38	1		*FRONT NUMBER PLATE W/CASING	Not Damaged	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>14,102.20</b>	<b>6,136.20</b>
<b>- List Item Discount on L Items 10.00/10.00% (S\$)</b>	1,308.34	601.62
<b>Total Parts (S\$)</b>	<b>12,793.86</b>	<b>5,534.58</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	R&R RADIATOR	New	150.00	60.00
2	R&R AIRCON CONDENSER	New	150.00	60.00
3	DIAGNOSTIC RESET FAULT CODE	New	300.00	0.00
4	UPHOLSTERY	New	300.00	0.00
5	CHECK WIRING	New	100.00	0.00
6	PANEL BEATING	New	1,600.00	1,200.00
7	RUST PROOFING	New	200.00	0.00
8	SPRAY PAINTING	New	1,600.00	800.00
			<b>Gross Labour Cost (\$)</b>	<b>2,120.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >