

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22001240/DQY3Q2**Date:** 24/05/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00118652100

Claimant Vehicle No : SFG2876T **Insured Vehicle No :** SLX8932P

Date of Loss: 06/02/2022 Nature of Claim: TP Claim No: SNM22D200912/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SFG2876T**

Make & Model: MERCEDES-BENZ C180, 1.6 Avantgarde (R17 LED) (A) Engine No: 27491030200066

Reg. Date: 13/10/2014 (Man. Year: 2014) Chassis No: WDD2050402F038175

Colour: Silver Odometer: 76986 km

Engine Capacity: 1595 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50 R17 Rear Tyre Size: 225/50 R17

Front Left Side: Pirelli 5 mm Rear Left Side: Pirelli 5 mm

Front Right Side: Pirelli 5 mm Rear Right Side: Pirelli 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	119,053.95	34,144.18	84,909.77	71.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	14,600.00	2,900.00	11,700.00	80.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	133,653.95	37,044.18	96,609.77	72.28
Approved Total (Overridden) (S\$)		14,700.00		
Nett Amount (S\$)	133,653.95	14,700.00	118,953.95	89.00

INSPECTION

Date of Assignment: 26/02/2022

Date Inspected: 10/02/2022 Inspected At: C.S. Ong Auto Pte Ltd (AMK)
10 Ang Mo Kio Industrial Park 2A, #02-16, AMK
Auto Point
Singapore 568047

Estimated Period of Repair: 8.0 days

Adjuster: BRYAN TANI**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 08 Mar 2022)

Parts: 143 MERCEDES-BENZ C180 1.6 Avantgarde (R17 LED) (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SFG2876T)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Not Necessary	4,259.10 FL	*- FL
2	1		*BONNET INSULATOR	Not Necessary	1,049.80 FL	*- FL
3	1		*BONNET SEAL	Not Necessary	210.00 FL	*- FL
4	1		*BONNET LOGO	Not Necessary	149.00 FL	*- FL
5	2		*BONNET HINGE LH/RH	Not Necessary	438.00 FL	*- FL
6	1		*HEAD LAMP LH/RH	O/S Cracked / N/SNot Necessary	12,996.00 FL	*6,498.00 FL
7	2		*HEAD LAMP LOWER BRACKET LH/RH	Not Necessary	796.00 FL	*- FL
8	2		*HEAD LAMP ECU LH/RH	Not Necessary	3,960.00 FL	*- FL
9	1		*HEAD LAMP WIRE HARNESS	Not Necessary	4,189.00 FL	*- FL
10	1		*FRONT GRILLE (BASE)	Cracked	1,419.20 FL	*1,419.20 FL
11	1		*FRONT GRILLE GARNISH	No such part	410.00 FL	*- FL
12	1		*SET FRONT GRILLE GARNISH CHROME	Obstructed	619.00 FL	*- FL
13	1		*FRONT GRILLE LOGO	Not Necessary	1,298.00 FL	*- FL
14	1		*FRONT BUMPER	Distorted / Mtg Cracked	2,198.00 FL	*2,198.00 FL
15	2		*FRONT BUMPER SIDE GARNISH LH/RH	Not Necessary	820.00 FL	*- FL
16	2		*FRONT BUMPER SIDE CHROME TOP L+R	Not Necessary	638.58 FL	*- FL
17	2		*FRONT BUMPER SIDE CHROME BOTTOM L+R	Not Necessary	718.20 FL	*- FL
18	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	891.00 FL	*- FL
19	1		*FRONT BUMPER LOWER LID	Not Necessary	698.00 FL	*- FL
20	1		*FRONT BUMPER LOWER LID CHROME	Not Necessary	419.20 FL	*- FL
21	1		*FRONT BUMPER UNDER COVER	Not Necessary	510.00 FL	*- FL
22	2		*FRONT BUMPER SIDE RETAINER LH/RH	Not Necessary	638.00 FL	*- FL
23	1		*FRONT BUMPER TOW HOOK COVER	Not Necessary	101.00 FL	*- FL
24	1		*FRONT BUMPER NO PLATE HOLDER	Serviceable	231.00 FL	*- FL
25	4		*FRONT BUMPER SENSOR	Serviceable	1,400.00 FL	*- FL
26	1		*SET FRONT BUMPER SENSOR HOLDER	Not Necessary	80.00 FL	*- FL
27	1		*SET FRONT BUMPER SENSOR WIRE HARNESS	Not Necessary	3,198.70 FL	*- FL
28	1		*FRONT BUMPER SPONGE	Torn	412.00 FL	*412.00 FL
29	1		*FRONT REINFORCEMENT BAR	Not Necessary	1,984.50 FL	*- FL
30	1		*FRONT SUPPORT PANEL	Not Necessary	2,894.50 FL	*- FL
31	1		*FRONT BUMPER CONSOLE CENTRE	Broken	480.50 FL	*480.50 FL
32	1		*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	410.90 FL	*- FL
33	2		*FRONT SUPPORT PANEL SIDE GARNISH LH/RH	Not Necessary	758.20 FL	*- FL
34	1		*FRONT INTER-COOLER ASSY	Not Necessary	3,149.00 FL	*- FL
35	1		*A/C CONDENSOR ASSY	Not Necessary	2,398.00 FL	*- FL
36	1		*A/C CONDENSOR DISCHARGE HOSE	Not Necessary	1,094.00 FL	*- FL
37	1		*A/C CONDENSOR SUCTION HOSE	Not Necessary	481.00 FL	*- FL
38	1		*RADIATOR ASSY	Not Necessary	2,784.50 FL	*- FL
39	1		*RADIATOR TOP HOSE	Not Necessary	103.00 FL	*- FL
40	1		*RADIATOR BOTTOM HOSE	Not Necessary	129.00 FL	*- FL
41	1		*RADIATOR FAN ASSY COMPLETE	Not Necessary	1,698.00 FL	*- FL
42	1		*FRONT FENDER LH /RH	Not Necessary	3,780.00 FL	*- FL
43	1		*FRONT FENDER INNER SHIELD LH/RH	Not Necessary	620.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
44	1		*FRONT DRIVER SEAT BELT	Activated	1,692.50 FL	*1,692.50 FL
45	1		*FRONT PASSENGER SEAT BELT	Activated	1,692.50 FL	*1,692.50 FL
46	2		*REAR PASSENGER SEAT BELT L+R	Activated	2,900.40 FL	*2,900.40 FL
47	4		*SEAT BELT BUCKLE	Serviceable	2,051.20 FL	*- FL
48	1		*SRS CONTROL MODULE	Activated	2,980.40 FL	*2,980.40 FL
49	1		*BOOTLID	Bent	4,190.00 FL	*4,190.00 FL
50	1		*BOOTLID LOGO	Necessary	198.00 FL	*198.00 FL
51	1		*BOOTLID C180 EMBLEM	Necessary	182.00 FL	*182.00 FL
52	1		*BOOTLID C&C EMBLEM	Necessary	201.00 FL	*201.00 FL
53	1		*BOOTLID CENTER CHROME MOULDING	Serviceable	890.00 FL	*- FL
54	1		*BOOTLID WEATHERSTRIP	Not Necessary	412.00 FL	*- FL
55	1		*BOOTLID SWITCH	Not Necessary	298.00 FL	*- FL
56	1		*BOOTLID LOCK	Not Necessary	471.00 FL	*- FL
57	1		*BOOTLID INNER TRIM	Not Necessary	1,498.00 FL	*- FL
58	2		*BOOTLID HINGE LH/RH	Not Necessary	462.00 FL	*- FL
59	2		*TAIL LAMP LH/RH	Mtg Cracked	4,258.00 FL	*4,258.00 FL
60	2		*TAIL LAMP LOWER BRACKET LH/RH	Not Necessary	658.00 FL	*- FL
61	2		*TAIL LAMP PANEL LH /RH	Not Necessary	1,258.00 FL	*- FL
62	1		*REAR BUMPER	Distorted	2,598.70 FL	*2,598.70 FL
63	2		*REAR BUMPER SIDE RETAINER LH/RH	Serviceable	684.00 FL	*- FL
64	1		*REAR BUMPER LOWER LID	Distorted	1,390.00 FL	*1,390.00 FL
65	1		*REAR BUMPER LOWER LID CHROME CENTER	Cracked	890.00 FL	*890.00 FL
66	2		*REAR BUMPER LOWER LID CHROME LH/RH	No such part	1,196.00 FL	*- FL
67	2		*REAR BUMPER SIDE CHROME MOULDING LH/RH	Necessary	1,020.00 FL	*1,020.00 FL
68	1		*REAR BUMPER CENTER CARRIER	Not Necessary	475.00 FL	*- FL
69	2		*REAR BUMPER BRACKET LH/RH	Cracked	882.00 FL	*882.00 FL
70	1		*REAR BUMPER SENSOR (4 PCS)	2PCS Damaged/2PCSNot Necessary	1,400.00 FL	*700.00 FL
71	1		*SET REAR BUMPER SENSOR HOLDER	Serviceable	80.00 FL	*- FL
72	1		*REAR BUMPER SENSOR WIRE HARNESS	Not Necessary	3,198.70 FL	*- FL
73	1		*REAR BUMPER UNDER COVER	Torn	617.00 FL	*617.00 FL
74	1		*REAR BUMPER SPONGE	No such part	428.00 FL	*- FL
75	1		*REAR REINFORCEMENT	Not Necessary	1,984.00 FL	*- FL
76	1		*REAR END PANEL	Repair	3,198.00 FL	*- FL
77	1		*REAR END PANEL TOP GARNISH	Not Necessary	529.00 FL	*- FL
78	1		*REAR KEYLESS SENSOR	Mtg Cracked	410.00 FL	*410.00 FL
79	1		*REAR KEYLESS BUZZER	No such part	429.00 FL	*- FL
80	1		*SPARE WHEEL PANEL	Serviceable	4,195.00 FL	*- FL
81	1		*SPARE WHEEL PANEL TOP BOARD	Not Necessary	1,095.00 FL	*- FL
82	1		*SPARE WHEEL PANEL TOOL BOX	Not Necessary	890.00 FL	*- FL
83	2		*REAR FENDER QUARTER GLASS MOULDING LH/RH	Not Necessary	682.00 FL	*- FL
84	2		*REAR FENDER INNER TRIM BOARD LH/RH	Not Necessary	3,758.00 FL	*- FL
85	1		*REAR WINDSCREEN MOULDING	Not Necessary	329.00 FL	*- FL
86	1		*REAR EXHAUST PIPE	Not Necessary	4,190.00 FL	*- FL
87	1		*REAR EXHAUST MOUNTING	Not Necessary	200.00 FL	*- FL
88	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	340.00 FL	*- FL
89	1		*BONNET INSULATOR CLIPS	Not Necessary	50.00 FS	*- FS
90	1		*FRONT GRILLE CLIPS	Necessary	50.00 FS	*15.00 FS
91	1		*HEAD LAMP CLIPS	Not Necessary	50.00 FS	*- FS
92	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*20.00 FS
93	1		*FRONT BUMPER LOWER GRILLE CLIPS	Not Necessary	50.00 FS	*- FS
94	1		*FRONT BUMPER SIDE GRILLE CLIPS	Not Necessary	50.00 FS	*- FS
95	1		*COOLANT	Not Necessary	100.00 FS	*- FS
96	1		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
97	1		*REAR WINDSCREEN DAMPING SEAL	Not Necessary	30.00 FS	*- FS
98	1		*REAR WINDSCREEN INNER SEAL	Not Necessary	80.00 FS	*- FS
99	1		*BOOTLID INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS

Report was unsubmitted during this print-out.

5/24/22, 3:13 PM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
100	1		*BOOTLID LAMP CLIPS	Not Necessary	50.00 FS	*- FS
101	1		*TAIL LAMP CLIPS	Not Necessary	50.00 FS	*- FS
102	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*20.00 FS
103	1		*REAR BUMPER LOWER LID CLIPS	Necessary	50.00 FS	*15.00 FS
104	1		*REAR END PANEL SEALANT	Not Necessary	80.00 FS	*- FS
105	1		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
106	1		*REAR FENDER INNER TRIM CLIPS	Not Necessary	80.00 FS	*- FS
107	1		*FRONT & REAR NO PLATE & CASING	1 PC Bent / 1 PC Not Necessary	200.00 FS	*45.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)						132,143.28 37,925.20
- List Item Discount on L Items 10.00/10.00% (\$\$)						13,089.33 3,781.02
Total Parts (\$\$)						119,053.95 34,144.18
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ALL INTERIOR UPHOLSTERY ITEMS TO FACILITATE REPAIRS	New	300.00	80.00
2	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS (FRONT)	New	2,400.00	600.00
3	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS (FRONT)	New	2,400.00	300.00
4	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS (REAR)	New	3,000.00	800.00
5	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS (REAR)	New	3,000.00	600.00
6	TO TUFF COAT DAMAGED AREAS	New	300.00	40.00
7	TO RNR FRONT BUMPER SENSOR TO FACILITATE REPAIRS	New	200.00	20.00
8	TO RNR INTER COOLER TO FACILITATE REPAIRS	New	200.00	0.00
9	TO RNR A/C CONDENSOR & REFILL GAS TO FACILITATE REPAIRS	New	200.00	0.00
10	TO RNR RADIATOR & REFILL COOLANT TO FACILITATE REPAIRS	New	200.00	0.00
11	TO RNR REAR WINDSCREEN TO FACILITATE REPAIRS	New	400.00	0.00
12	TO RNR BOOTLID MECHANISM TO FACILITATE REPAIRS	New	200.00	60.00
13	TO RNR REAR BUMPER SENSOR TO FACILITATE REPAIRS	New	200.00	40.00
14	TO RNR EXHAUST & ATTACHMENT PARTS TO FACILITATE REPAIRS	New	200.00	0.00
15	TO RNR ALL AFFECTED SEAT BELTS TO FACILITATE REPAIRS }	New	600.00	180.00
16	TO RNR CENTER CONSOLE TO REPLACE SRS CONTROL MODULE }	New	300.00	0.00
17	TO CHECK & REFIX ALL ELECTRICAL WIRINGS	New	200.00	30.00
18	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS ,RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	150.00
Gross Labour Cost (\$\$)			14,600.00	2,900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >