

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	AXA INSURANCE	PTE LTD		Ref:	CS3/ASM22001245/Vty3e2
	8 SHENTON WAY SINGAPORE 0688	#24-01 AXA TOWER 11		Date:	10/03/2022
				Code:	ASM
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHD 3420K	Veh. Inspected	d t	SJD 1962C
	Policy No.	VFX/P2419138	Coverage (\$)		0.00
	Claim No.	S2M03SVX	Excess (\$)		0.00
	Assign From	ONG KIAN THENG DERICK	Assign Date		09/02/2022
2.	Vehicle Particulars & Condition				
	Make & Model	HONDA ODYSSEY ABSOLUTE	c.c		2354
	Engine No.	HIDDEN	Year of Reg.		2008
	Chassis No.	RB11400726	Colour		SILVER
	Odometer	258589 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		SPORTS RIM
	General	GOOD			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	215/55 R17	BRIDGESTONE		6 mm
	L/H Front Tyre	215/55 R17	BRIDGESTONE		6 mm
	R/H Rear Tyre	215/55 R17	BRIDGESTONE		6 mm
	L/H Rear Tyre	215/55 R17	BRIDGESTONE		6 mm
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
5.	General Information				
	Accident Date	31/01/2022	Inspect Date /	Time	10/02/2022 (05:00 PM)
	Survey held at	KIANG MOTOR	•		
	BLK 25 KAKI BUKIT ROAD 4 #08-26 SYNERGY @ KB SINGAPORE 417800				
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days				

Report Ref No. CS3/ASM22001245/Vty3e2

Inspected By

THEVAN THOMAS KARTHIKESAVAN

The

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser