

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMQ 9053U

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	PANEL BUMPER,PRIMED,REAR (BASIS PDC)(SN)	DENTED	1,035.00	1,035.00
1	FLAP,TOWING EYE,PRIMED (SN)	BROKEN	43.25	43.25
1	GUIDE,BUMPER,SIDE INNER RIGHT (SN)	NOT NECESSARY	161.15	-
1	SET,MOUNTS,PDC SENSOR,REAR (SN)	NECESSARY	61.80	61.80
1	LEFT PROTECTION FOIL (SN)	NECESSARY	11.25	11.25
1	RIGHT PROTECTION FOIL (SN)	NECESSARY	11.25	11.25
1	SUPPORT (SN)	NOT NECESSARY	46.35	-
8	HEX NUT WITH PLATE (M6)(SN)	NOT NECESSARY	14.40	-
1	CARRIER,BUMPER REAR (SN)	NOT NECESSARY	483.40	-
1	REAR REFLECTOR,REAR RIGHT (SN)	BROKEN	39.05	39.05
2	ULTRASONIC SENSOR ALPINE WHITE (U300)(SN)	NOT NECESSARY	766.30	-
4	DECOUPLING RING PDC TORQUE (SN)	NECESSARY	20.60	20.60
1	SUNDRIES (SN)	NECESSARY	100.00	60.00
			2,793.80	1,282.20
	<u>LABOUR</u>			
	TO REPLACE REAR BUMPER AND ATTACHMENTS INCLUDE MAKING GOOD THE TAIL END PANEL AND KNOCKING OUT DENTS CAUSED BY THE ACCIDENT.		2,160.00	720.00
	TO SPRAY PAINT THE REAR BUMPER AND TAIL END PANEL.		1,500.00	700.00
	TO TRANSFER PDC ASSEMBLY FROM OLD TO NEW BUMPER INCLUDE RECONNECTING TO NEW BUMPER AND CONDUCTING CHECKS FOR PROPER FUNCTION.		150.00	120.00
	TO REMOVE AND INSTALL REAR BOOT COMPARTMENT CARPET AND GARNISH TO FACILITATE REPAIRS.	NOT NECESSARY	225.00	-
	TO CARRY OUT DIAGNOSIS TESTS-ABL.		500.00	350.00
			4,535.00	1,890.00
	GRAND TOTAL		7,328.80	3,172.20

Report Ref No. CS/AGI22001246/Etf3n2



Page No.:2 of 2

RECOMMENDED COST OF REPAIRS 3,172.20

Report Ref No. CS/AGI22001246/Etf3n2



Automotive Assessor



ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser