

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22001247/KVY3Q2**Date:** 04/04/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNA00004192100
Claimant Vehicle No :	SKB4070E	Insured Vehicle No :	SMW8131C
Date of Loss:	06/02/2022	Nature of Claim:	TP
		Claim No:	SNM22D200941/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKB4070E	Engine No:	R18A13850148
Make & Model:	HONDA STREAM, 1.8 L (A)	Chassis No:	JHMRN68609C200147
Reg. Date:	26/05/2011 (Man. Year: 2009)	Odometer:	140939 km
Colour:	Metallic Silver		
Engine Capacity:	1799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Tourador 7 mm	Rear Left Side:	Tourador 7 mm
Front Right Side:	Tourador 7 mm	Rear Right Side:	Tourador 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,808.12	893.68	1,914.44	68.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,840.00	950.00	890.00	48.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	4,648.12	1,843.68	2,804.44	60.33
+ GST 7.00/7.00% (\$\$)	325.37	129.06	196.31	60.33
Nett Amount (\$\$)	4,973.49	1,972.74	3,000.75	60.33

INSPECTION

Date of Assignment:	09/02/2022	NO 10 ANG MO KIO IND PK 2A #01-09 AMK AUTOPOINT SINGAPORE 568047 Repairer: Ah Lim Motor Company (Sin Ming)
Date Inspected:	10/02/2022 Inspected At:	
Estimated Period of Repair:	3.0 days	

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$1,129.44 NETT)

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Apr 2022)
Parts:	M1-MPV	HONDA STREAM 1.8 L (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKB4070E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Necessary	50.90 FL	*50.90 FL
2	1		*TAILGATE	Bent	991.20 FL	*991.20 FL
3	1		*TAILGATE EMBLEM	Not Necessary	24.90 FL	*- FL
4	1		*TAILGATE NUMBER PLATE GARNISH	Serviceable	182.40 FL	*- FL
5	1		*TAILGATE LOCK	*Check	124.50 FL	*- FL
6	1		*TAILGATE LOCK CATCH	Repair	27.00 FL	*- FL
7	1		*TAILGATE RUBBER	Serviceable	133.90 FL	*- FL
8	1		*TAILGATE INNER TRIMBOARD BOTTOM	Serviceable	170.30 FL	*- FL
9	1		*REAR BUMPER	*Check	704.90 FL	*- FL
10	2		*REAR BUMPER CLIPS	*Check	7.40 FL	*- FL
11	1		*REAR END PANEL	Repair	333.10 FL	*- FL
12	1		*REAR END PANEL GARNISH	Serviceable	140.90 FL	*- FL
13	1		*REAR VIEW CAMERA (NPA)	Serviceable	0.00 FS	*- FS
14	1		*INNER SEAL	Necessary	20.00 FS	*20.00 FS
15	1		*SEALANT	Necessary	40.00 FS	*40.00 FS
16	1		*NUMBER PLATE	Serviceable	35.00 FS	*- FS
17	1		*REVERSE SENSOR (4-IN-1)	*Check	400.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,386.40	1,102.10
- List Item Discount on L Items 20.00/20.00% (\$\$)	578.28	208.42
Total Parts (\$\$)	2,808.12	893.68

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIT REAR WINDSCREEN	New	120.00	120.00
2	TO REMOVE AND REINSTALL /REPLACE FRONT BUMPER SENSORS (*Check)	New	60.00	0.00
3	TO SPRAY ANTI -RUST COATING ON AFFECTED AREAS	New	60.00	30.00
4	TO DISMANTLE ALL DAMAGED PARTS .TO CUT & WELD REAR END PANEL .TO KNOCK & REPAIR SPARE TYRE PANEL ,INNER PANELS AND AFFECTED AREAS .TO REFIT LISTED PARTS BACK SAME	New	800.00	400.00
5	TO SPRAY TAILGATE ,REAR BUMPER ,REAR END PANEL ,SPARE TYRE PANEL	New	800.00	400.00
Gross Labour Cost (\$\$)			1,840.00	950.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >