

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22001249/UQY3N2**Date:** 21/03/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00098252100

**Claimant Vehicle No :** SMG3926T **Insured Vehicle No :** GBL4790P

Date of Loss: 28/01/2022 Nature of Claim: TP Claim No: SNM22D200939/C02/IRENE

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SMG3926T**

Make & Model: TOYOTA SIENTA, 1.5 (A) Engine No: 2NRX409340

Reg. Date: 18/12/2018 (Man. Year: 2018) Chassis No: MHFZ28H3800061258

Colour: Brown Odometer: 9936 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 195/50R16 Rear Tyre Size: 195/50R16

Front Left Side: Bridgestone 8 mm Rear Left Side: Bridgestone 8 mm

Front Right Side: Bridgestone 8 mm Rear Right Side: Bridgestone 8 mm

*The above values represent the remaining tyre tread depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,118.75	1,297.25	2,821.50	68.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,130.00	750.00	380.00	33.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>5,248.75</b>	<b>2,047.25</b>	<b>3,201.50</b>	<b>61.00</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,600.00</b>		
<b>(S\$)</b>	5,248.75	1,600.00	3,648.75	69.52
<b>+ GST 7.00/7.00% (S\$)</b>	367.41	112.00	255.41	69.52
<b>Nett Amount (S\$)</b>	<b>5,616.16</b>	<b>1,712.00</b>	<b>3,904.16</b>	<b>69.52</b>

**INSPECTION**

Date of Assignment: 09/02/2022

Date Inspected: 16/02/2022 Inspected At: Progressive Car Care Pte Ltd (HQ)  
Blk 3022A Ubi Road 1, #01-45/46  
Singapore 408716

Estimated Period of Repair: 3.0 days

**Adjuster:** MARCUS CHUA**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Mar 2022)
Parts:	M1-MPV	TOYOTA SIENTA 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMG3926T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Dented	653.00 FL	*653.00 FL
2	2		*BONNET HINGES-LH/RH	Not Necessary	150.00 FL	*- FL
3	5		*BONNET INSULATOR CLIPS	Not Necessary	25.00 FL	*- FL
4	1		*BONNET LOCK	Not Necessary	145.00 FL	*- FL
5	1		*BONNET INNER RUBBER STOPPER-LH/RH	Not Necessary	25.00 FL	*- FL
6	1		*HEAD LAMP UNIT	Not Necessary	3,050.00 FL	*- FL
7	1		*FRONT BUMPER	Dented/Deformed	486.00 FL	*486.00 FL
8	2		*FRONT BUMPER SIDE HOLDER-LH/RH	Not Necessary	184.00 FL	*- FL
9	10		*FRONT BUMPER CLIPS	Necessary	50.00 FL	*50.00 FL
10	1		*FRONT BUMPER RUBBER	Not Necessary	50.00 FL	*- FL
11	1		*FRONT BUMPER TOW COVER	Not Necessary	35.00 FL	*- FL
12	1		*FRONT GRILLE BASE WITH CHROME	Cut	494.00 FL	*494.00 FL
13	1		*FRONT GRILLE LOGO	Not Necessary	98.00 FL	*- FL
14	1		*FRONT NUMBER PLATE WITH CASING	Cut	35.00 FS	*35.00 FS
					Sub Total (S\$)	5,480.00 1,718.00
					- List Item Discount on L Items 25.00/25.00% (S\$)	1,361.25 420.75
					Total Parts (S\$)	4,118.75 1,297.25

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO KNOCK OUT DENTS,REMOVE,REPLACE ACCIDENT PARTS	New	550.00	300.00
2	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	500.00	400.00
3	TO CHECK WIRING	New	50.00	20.00
4	TO TUFF-KOTE	New	30.00	30.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,130.00</b>	<b>750.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >