

Vehicle Damage Assessment Report for [SKT5386T]

Estimate Created: 10/02/2022 12:36 by Insurlogic 1 (Insurlogic_Pte_Ltd)
Owned: 14/06/2023 18:25 by LKK_cs-a (LKK_Auto_Consultants_Pte_Ltd)

General Information

Insurance Company	India International Insurance	Claim Number
Claim Type	TP	
Workshop	Insurlogic_Repair_Shop	Reference Number

Vehicle Information

Brand	Hyundai	Model	Elantra
Engine Type			
License Plate Number	SKT5386T	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- FINAL REVIEW BASE ON INFORMATION PROVIDED BY LKK:
CONCLUDED THE COST OF REPAIR AT \$4,450.00 AND 5 WORKING
DAYS.

Insurlogic 4 (14/06/2023 18:24)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
BOOT		1	1650.20	-20.00 %	1,320.16
BOOT EMBLEM		1	32.00	-20.00 %	25.60
BOOT BADGE ELANTRA		1	56.00	-20.00 %	44.80
BOOT BADGE ELITE		1	73.00	-20.00 %	58.40
BOOT LAMP LH		1	274.90	-20.00 %	219.92
BOOT LAMP GASKET LH		1	26.00	-20.00 %	20.80
BOOT LOCK		1	133.00	-20.00 %	106.40
BOOT TRIM BOARD		1	93.00	-20.00 %	74.40
BOOT STOPPER		1	12.50	-20.00 %	10.00
BOOT TRIM BOARD CLIPS		12	3.00	-20.00 %	28.80
BOOT REMOTE OPENER SENSOR		1	180.00	-20.00 %	144.00
REAR BUMPER		1	459.00	-20.00 %	367.20
REAR BUMPER CLIPS		12	3.00	-20.00 %	28.80
REAR BUMPER BRACKETS		2	42.00	-20.00 %	67.20
REAR BUMPER REINFORCEMENT		1	320.00	-20.00 %	256.00
REAR BUMPER LOWER RETAINERS		3	51.00	-20.00 %	122.40
REAR BUMPER TOP RETAINERS		2	55.00	-20.00 %	88.00
REAR BUMPER LOWER LIP		1	90.30	-20.00 %	72.24
REAR BUMPER REFLECTORS LH		1	30.00	-20.00 %	24.00
REAR BUMPER INNER BOOT KEY SENSOR		1	175.00	-20.00 %	140.00
END PANEL		1	447.00	-20.00 %	357.60
END PANEL GARNISH		1	69.00	-20.00 %	55.20
REAR FENDER TRIM BOARD LH		1	215.00	-20.00 %	172.00

Parts Subtotal 3,803.92

Materials

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
BOOT WEATHERSTRIP		1.0	53.00	0.00 %	53.00
REAR BUMPER REVERSE SENSOR		1.0	200.00	0.00 %	200.00
REAR NUMBER PLATE		1.0	45.00	0.00 %	45.00

Materials Subtotal 298.00

Labor

Replace/RnR

Description	Type	Cost	Markup/Disc %	Price
TO DISMANTLE /TRANSFER BOOT FITTINGS /ANCILLARY ACCESSORIES	RnR	50.00	0.00 %	50.00
TO CONDUCT REAR ELECTRICAL CHECK ,REPLACE REVERSE SENSORS ,MODULE REWIRING ETC	RnR	60.00	0.00 %	60.00
TO SUPPLY END PANEL BODY SEALANT	RnR	30.00	0.00 %	30.00
TO APPLY RUST PROOFING /RESEAL TUFF COATING TREATMENT TO RESPRAY /REPLACED /REPAIR PANEL	RnR	60.00	0.00 %	60.00
TO DISMANTLE /REFIT TRUNK COMPARTMENT BOARDS & TRIMS	RnR	60.00	0.00 %	60.00
PANEL BEATING	RnR	600.00	0.00 %	600.00

Repair

Description	Severity	Cost	Markup/Disc %	Price
BOOT HINGE	Medium	0.00	0.00 %	0.00
BOOT LOCK CATCH	Medium	0.00	0.00 %	0.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
SPRAY PAINTING	Full spray	600.00	0.00 %	600.00

Labor Rate	S\$ 50 / Hour	General Labor Subtotal	860.00
		Paint Labor Subtotal	600.00
		Labor Subtotal	1,460.00

Summary

Repair Cost	5,561.92
Discount(20 %)	(1,112.38)
	4,449.54
Excess	(0.00)
GST(0.00 %)	0.00
Grand Subtotal	4,449.54