



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLS 8731D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER (CONSISTENT)	CUT	669.00	474.40
1	FRONT BUMPER RETAINER LH (CONSISTENT)	SERVICEABLE	56.00	-
1	FRONT BUMPER RETAINER RH (CONSISTENT)	NECESSARY	56.00	56.00
1	FRONT BUMPER SPONGE (CONSISTENT)	SERVICEABLE	134.00	-
1	FRONT BUMPER REINFORCEMENT (CONSISTENT)	SERVICEABLE	386.00	-
1	FRONT BUMPER FOG LAMP LH (CONSISTENT)	SERVICEABLE	298.00	-
1	FRONT BUMPER FOG LAMP COVER LH (CONSISTENT)	SERVICEABLE	134.00	-
1	FRONT HEADLAMP RH (CONSISTENT)	SCRATCHED	1,589.00	1,198.80
	LESS 20% DISCOUNT		-664.40	-345.84
			2,657.60	1,383.36
<u>SPECIAL NETT ITEMS</u>				
1	SET FRONT BUMPER CLIP (SN) (CONSISTENT)	NECESSARY	40.00	20.00
			40.00	20.00
<u>LABOUR</u>				
	CHECK FRONT WIRING AND LIGHTNING SYSTEM.		100.00	30.00
	PANEL BEATING ON AFFECTED AREAS AND RENEW DAMAGE PARTS.		600.00	200.00
	SPRAY PAINTING ON AFFECTED AREAS.		500.00	200.00
	APPLY ANTI RUST ON AFFECTED AREAS.		100.00	30.00
			1,300.00	460.00
GRAND TOTAL			3,997.60	1,863.36
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,500.00

Report Ref No. CS/ASM22001254/Vty3e2

THEVAN THOMAS KARTHIKESAVAN

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.