

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG22001259/VVY3N2**Date:** 24/05/2022**REFERENCE**

Insured/Claimant:	LIEW MUN KIONG	Policy No:	7210074983	
Date of Loss:	04/02/2022	Nature of Claim:	OD	Claim No: 2223138160SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SMQ8218T</b>		
Make & Model:	AUDI Q3 SPORTBACK, 1.4 TFSI S TRONIC (17) (A)	Engine No:	CZDC41672
Reg. Date:	28/07/2021 (Man. Year: 2021)	Chassis No:	WAUZZZF30M1128013
Colour:	Red	Odometer:	4674 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$186,000.00		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	215/65 R17	Rear Tyre Size:	215/65 R17
Front Left Side:	Continental 7 mm	Rear Left Side:	Continental 7 mm
Front Right Side:	Continental 7 mm	Rear Right Side:	Continental 7 mm

*The above values represent the remaining tyre tread depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	15,774.00	8,789.84	6,984.16	44.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,432.00	5,152.00	5,280.00	50.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>26,206.00</b>	<b>13,941.84</b>	<b>12,264.16</b>	<b>46.80</b>
<b>- Excess (S\$)</b>	800.00	800.00	0.00	0.00
<b>(S\$)</b>	25,406.00	13,141.84	12,264.16	48.27
<b>+ GST 7.00/7.00% (S\$)</b>	1,778.42	919.93	858.49	48.27
<b>Nett Amount (S\$)</b>	<b>27,184.42</b>	<b>14,061.77</b>	<b>13,122.65</b>	<b>48.27</b>

**INSPECTION**

Date of Assignment:	10/02/2022	
Date Inspected:	08/02/2022	Inspected At: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	5.0 days	

**Adjuster:** Thevan Thomas Karthikesavan**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER-LH	Scratched	1,423.00 FS	*1,138.40 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	433.00 FS	*- FS
3	1		*FRONT BUMPER CLOSING ELEMENT-LH	Serviceable	66.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT END PLATE	Serviceable	212.00 FS	*- FS
5	1		*FRONT BUMPER SPOILER	Scratched	850.00 FS	*679.60 FS
6	1		*FRONT BUMPER BRACKET	Necessary	24.00 FS	*18.56 FS
7	1		*FRONT BUMPER AIR GUIDE GRILLE-LH	Serviceable	171.00 FS	*- FS
8	1		*FRONT BUMPER TRIM-LH	Serviceable	182.00 FS	*- FS
9	1		*FRONT PARKING AID SENSOR SUPPORT-LH	Necessary	29.00 FS	*22.72 FS
10	1		*FRONT BUMPER GUIDE SECTION-LH	Serviceable	43.00 FS	*- FS
11	1		*FRONT BUMPER TOP COVER	Serviceable	137.00 FS	*- FS
12	1		*CAUTION STICKER	Serviceable	16.00 FS	*- FS
13	1		*AIR COND STICKER	Serviceable	9.00 FS	*- FS
14	1		*FRONT FENDER-LH	Broken	1,445.00 FS	*1,156.00 FS
15	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	66.00 FS	*- FS
16	1		*FRONT FENDER BRACE-LH	Necessary	98.00 FS	*77.68 FS
17	1		*FRONT FENDER BRACKET-LH	Necessary	39.00 FS	*30.48 FS
18	1		*FRONT FENDER CLOSING ELEMENT-LH	Serviceable	37.00 FS	*- FS
19	1		*FRONT WHEEL HOUSING LINER-LH	Not Necessary	260.00 FS	*- FS
20	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	105.00 FS	*- FS
21	1		*FRONT WHEEL HOUSING LINER COVER-LH	Not Necessary	18.00 FS	*- FS
22	1		*HEADLIGHT MOUNTING-LH	Serviceable	132.00 FS	*- FS
23	1		*HEADLIGHT-LH	Scratched	5,952.00 FS	*4,761.60 FS
24	1		*LIFT CYLINDER-LH	Serviceable	231.00 FS	*- FS
25	1		*LIFT CYLINDER HOSE-LH	Serviceable	92.00 FS	*- FS
26	2		*FRONT WHEEL ARCH COVER-LH/RH	Cut	1,132.00 FS	*904.80 FS
27	1		*FRONT DOOR COVER-LH	Not Necessary	390.00 FS	*- FS
28	1		*REAR DOOR COVER-LH	Not Necessary	368.00 FS	*- FS
29	1		*ALUMINIUM RIM	Serviceable	1,414.00 FS	*- FS
30	1		*SUNDRIES	Not Necessary	400.00 FS	*- FS

F=Franchise part. S=SpcNett.

**Total Parts (S\$) 15,774.00 8,789.84**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	250.00
3	TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM.TO REMOVE AND REINSTALL LHS WING MIRROR ASSY TO FACILITATE RESPRAY OF LHS FRONT DOOR	New	280.00	280.00
4	TO DISMANTLE AND RENEW FRONT BUMPER,LHS FRONT FENDER LHS HEADLIGHT.TO REPAIR LHS FRONT DOOR,RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	2,800.00	1,500.00
5	TO RESPRAY FRONT BUMPER,FRONT BUMPER LOWER SPOILER.LHS FRONT FENDER,LHS FRONT DOOR.LHS REAR DOOR,TWO DOOR COVERS AND BOTH FRONT WHEEL ARCH TRIMS	New	6,000.00	2,450.00
6	TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	0.00
7	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (\$\$)</b>			<b>10,432.00</b>	<b>5,152.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >