

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC3/AIG16022405/SGA3Q2-1**Date:** 01/06/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999995242
<b>Claimant Vehicle No :</b>	SHF375S	<b>Insured Vehicle No :</b>	SKG5974P
Date of Loss:	22/11/2016	Nature of Claim:	TP
		Claim No:	0766401970SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SHF375S</b>	Engine No:	HIDDEN
Make & Model:	CHEVROLET EPICA, 2.0 (A)	Chassis No:	KL1LA69RJBB133745
Reg. Date:	18/12/2012 (Man. Year: 2012)	Odometer:	348986 km
Colour:	Maroon		
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/65 R15	Rear Tyre Size:	205/65 R15
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	8,623.94	880.75	7,743.19	89.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,786.00	1,380.00	2,406.00	63.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>12,409.94</b>	<b>2,260.75</b>	<b>10,149.19</b>	<b>81.78</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,100.00</b>		
<b>Nett Amount (S\$)</b>	<b>12,409.94</b>	<b>2,100.00</b>	<b>10,309.94</b>	<b>83.08</b>
<b>+ Loss of Use (5.0 x S\$60.00/day) (S\$)</b>		300.00		
<b>+ Car Rental (5.0 x S\$112.35/day) (S\$)</b>		561.75		
		<b>(S\$) 2,961.75</b>		
<b>Liable Amount (50.00%) (S\$)</b>		<b>1,480.88</b>		
<b>+ Doc/Search Fee (S\$)</b>		5.00		
<b>Nett Liability (S\$)</b>		<b>1,485.88</b>		
<b>Global Sum Settlement (S\$)</b>		<b>1,500.00</b>		

INSPECTION

Date of Assignment:	23/11/2016	
Date Inspected:	23/11/2016	Inspected At: SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705
Estimated Period of Repair:	4.0 days	

**Adjuster:** Sebastian Yeang Wai Keen**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LINER FENDER FRT LH (PROTECTOR) (DISC 10%)	Torn	49.00 F	*44.10 F
2	1		*CAP HUB (DISC 10%)	Scratched	21.95 F	*19.75 F
3	1		*LAMP HEAD LH (DISC 10%)	Cracked	841.00 F	*756.90 F
4	1		*SMRT LOGO DOOR (SN)	Necessary	60.00 F	*60.00 F
5	1		*PANEL LH FRONT DOOR	Repair	2,020.00 F	*- F
6	1		*MIRROR LH	Repair	844.00 F	*- F
7	1		*PANEL FRT FENDER LH	Repair	606.00 F	*- F
8	1		*TYRE RIM	Repair	328.99 F	*- F
9	1		*BUMPER FRT ASSY	Repair	1,238.00 F	*- F
10	1		*MOLDING PANEL LH ROCKER	Not Necessary	304.00 F	*- F
11	1		*BEAM FRT BUMPER IMPACT	Not Necessary	465.00 F	*- F
12	1		*ABSORBER ENGY FRT BUMPER	Not Necessary	219.00 F	*- F
13	1		*BRACKET FRT BUMPER SIDE LH	Not Necessary	9.00 F	*- F
14	1		*PANEL FRT SUPPORT PANEL	Not Necessary	574.00 F	*- F
15	1		*PANEL FRT HOOD	Not Necessary	1,044.00 F	*- F
F=Franchise part.						
Total Parts (S\$)					8,623.94	880.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING & BODY WORK	New	1,014.00	600.00
2	SPRAY PAINT	New	2,232.00	700.00
3	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	30.00
4	TO APPLY RUST-PROOFING ON AFFECTED AREA	New	100.00	0.00
5	TO DO WHEEL ALIGNMENT /TYRE BALANCING	New	120.00	0.00
6	TO REMOVE AND REFIX WING MIRROR	New	120.00	50.00
7	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	New	120.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,786.00</b>	<b>1,380.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >