

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC3/TMI22001264/KTY3N2**Date:** 21/02/2022REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MM000073
<b>Claimant Vehicle No :</b>	SHD9443E	<b>Insured Vehicle No :</b>	SLQ7308K
Date of Loss:	15/01/2022	Nature of Claim:	TP
		Claim No:	M2200356

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SHD9443E</b>	Engine No:	2ZR2C16146
Make & Model:	TOYOTA PRIUS PLUS, 1.8 (A)	Chassis No:	JTDKB3FU903080508
Reg. Date:	24/05/2019 (Man. Year: 2018)	Odometer:	265727 km
Colour:	Metallic Pearl White/Red		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Sailun 8 mm	Rear Left Side:	Sailun 8 mm
Front Right Side:	Sailun 8 mm	Rear Right Side:	Sailun 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,497.17	2,430.20	2,066.97	45.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,990.00	435.00	4,555.00	91.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>9,487.17</b>	<b>2,865.20</b>	<b>6,621.97</b>	<b>69.80</b>
<b>+ GST 7.00/7.00% (S\$)</b>	664.10	200.56	463.54	69.80
<b>Nett Amount (S\$)</b>	<b>10,151.27</b>	<b>3,065.76</b>	<b>7,085.51</b>	<b>69.80</b>

INSPECTION

Date of Assignment:	18/02/2022		
Date Inspected:	07/02/2022	Inspected At:	Trans-cab Auto Services Pte Ltd No 2 Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	2.0 days		

**Adjuster:** KENNETH KONG**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 21 Feb 2022)
<b>Parts:</b>	M1-MPV	TOYOTA PRIUS PLUS 1.8 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHD9443E)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*COVER,FRONT BUMPER	Buckled/Dented	516.00 FL	-	*516.00 FL
2	1		*FRONT BUMPER SIDE RETAINER RH	Serviceable	80.10 FL	-	*- FL
3	1		*JAR ASSY,WINDSHIELD WASHER	Serviceable	219.10 FL	-	*- FL
4	1		*ABSORBER,FRONT BUMPER ENERGY	Serviceable	79.60 FL	-	*- FL
5	1		*LAMP ASSY,FOG,RH	Serviceable	951.40 FL	-	*- FL
6	1		*UNIT ASSY,HEADLAMP,RH	Mtg Cracked	2,637.60 FL	-	*2,637.60 FL
7	1		*FENDER SUB-ASSY,FRONT RH	Repair	977.80 FL	-	*- FL
8	1		*LINER,FRONT FENDER,RH	Serviceable	206.70 FL	-	*- FL
9	1		*FRONT FENDER EMBLEM RH	Not Necessary	54.60 FL	-	*- FL
10	1		*FRT BUMPER CLIP	Necessary	65.00 FS	-	*65.00 FS
11	1		*FRT BUMPER SIDE RETAINER CLIP	Not Necessary	65.00 FS	-	*- FS
12	1		*FENDER LINER CLIP	Not Necessary	75.00 FS	-	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>5,927.90</b>	<b>3,218.60</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	1,430.73	788.40
<b>Total Parts (\$\$)</b>	<b>4,497.17</b>	<b>2,430.20</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	250.00	0.00
2	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,800.00	220.00
3	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR	New	380.00	0.00
4	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	15.00
5	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	2,000.00	200.00
6	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
7	TO TRANSFER OF REAR FENDER PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>4,990.00</b>	<b>435.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >