

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG22001267/AEA3Q2**Date:** 30/09/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7990000051
<b>Claimant Vehicle No :</b>	SLG7909D	<b>Insured Vehicle No :</b>	SKB6744G
Date of Loss:	09/02/2022	Nature of Claim:	TP
		Claim No:	3843541380SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLG7909D</b>	Engine No:	MR20906395B
Make & Model:	NISSAN X-TRAIL, 2.0 CVT ABS 4WD S/R 7-STR (A)	Chassis No:	JN1JANT32Z0002567
Reg. Date:	14/10/2016 (Man. Year: 2016)	Odometer:	90248 km
Colour:	Red		
Engine Capacity:	1997 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/60 R18	Rear Tyre Size:	225/60 R18
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	15,019.06	6,705.70	8,313.36	55.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,330.00	1,350.00	1,980.00	59.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>18,349.06</b>	<b>8,055.70</b>	<b>10,293.36</b>	<b>56.10</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>6,400.00</b>		
<b>(S\$)</b>	18,349.06	6,400.00	11,949.06	65.12
<b>+ GST 7.00/7.00% (S\$)</b>	1,284.43	448.00	836.43	65.12
<b>Nett Amount (S\$)</b>	<b>19,633.49</b>	<b>6,848.00</b>	<b>12,785.49</b>	<b>65.12</b>
<b>+ Loss of Use (6.0 x S\$100.00/day) (S\$)</b>		600.00		
<b>+ Doc/Search Fee (S\$)</b>		36.45		
<b>Nett Liability (S\$)</b>		<b>7,484.45</b>		
<b>Global Sum Settlement (S\$)</b>		<b>7,480.00</b>		

INSPECTION

Date of Assignment:	10/02/2022	
Date Inspected:	10/02/2022 Inspected At:	Ryder Auto Pte Ltd (HQ) 2 Kaki Bukit Ave 2, #02-19 AutoHub @ Kaki Bukit Singapore 417921
Estimated Period of Repair:	4.0 days	

**Adjuster:** ADRIAN LING**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	811.00 FN	*693.00 FN
2	1		*REAR BUMPER CLIPS (16 PCS)	Necessary	30.00 FS	*30.00 FS
3	1		*REAR BUMPER ENFORCEMENT	Dented	693.90 FN	*569.00 FN
4	2		*REAR BUMPER O/S & N/S REFLECTOR	Not Necessary	120.60 FN	*- FN
5	1		*REAR BUMPER DIFFUSER	Not Necessary	136.50 FN	*- FN
6	1		*REAR TAILGATE	Cracked	4,200.00 FN	*4,200.00 FN
7	1		*REAR TAILGATE LOCK	Damaged	570.00 FN	*570.00 FN
8	1		*REAR TAILGATE LOCK HANDLE	Not Necessary	75.60 FN	*- FN
9	1		*REAR TAILGATE INNER GARNISH	Cracked	588.40 FN	*452.00 FN
10	2		*REAR O/S & N/S SHOCK ABSORBER	Not Necessary	2,430.60 FN	*- FN
11	2		*REAR O/S & N/S TAIL GATE SENSOR	Not Necessary	1,020.40 FN	*- FN
12	2		*REAR O/S & N/S TAIL LAMP	Not Necessary	865.40 FN	*- FN
13	2		*REAR O/S & N/S REFLECTOR	Not Necessary	560.00 FN	*- FN
14	1		*REAR END PANEL	Repair	526.40 FN	*- FN
15	1		*REAR END PANEL INNER TRIM	Not Necessary	310.20 FN	*- FN
16	1		*REAR END PANEL METAL PLATE	Not Necessary	125.60 FN	*- FN
17	1		*REAR BUZZER	Not Necessary	265.50 FN	*- FN
18	1		*REAR X-TRAIL EMBLEM	Necessary	78.00 FN	*78.00 FN
19	1		*REAR NISSAN EMBLEM	Necessary	91.00 FN	*91.00 FN
20	4		*REAR REVERSE SENSOR	Damaged (2 PCS ONLY)	1,380.00 FN	*520.00 FN
21	1		*REAR WINDSCREEN MOULDING	Necessary	160.00 FS	*160.00 FS
22	1		*WINDSCREEN SEALANT	Necessary	80.00 FS	*60.00 FS
23	2		*REAR O/S & N/S FENDER INNER TRIM (NPA)	Not Necessary	0.00 FN	*- FN
24	2		*REAR O/S & N/S WHEEL ARCH GARNISH	Not Necessary	465.40 FN	*- FN
25	2		*REAR O/S & N/S BUMPER STAY	Not Necessary	164.20 FN	*- FN
26	2		*REAR END PANEL O/S & N/S (CARDBOARD GARNISH)	Not Necessary	315.60 FN	*- FN
27	1		*REAR BUMPER CENTRE GARNISH (BLACK)	Not Necessary	96.50 FN	*- FN
28	2		*REAR N/S & O/S END PANEL ENFORCEMENT STAY	Not Necessary	432.60 FN	*- FN
29	1		*REAR REGN PLATE	Not Necessary	28.00 FS	*- FS
30	1		*REAR REGN BRACKET	Not Necessary	30.00 FS	*- FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

<b>Sub Total (\$\$)</b>	<b>16,651.40</b>	<b>7,423.00</b>
<b>- Nett Item Discount on N Items 10.00/10.00% (\$\$)</b>	1,632.34	717.30
<b>Total Parts (\$\$)</b>	<b>15,019.06</b>	<b>6,705.70</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO DISMANTLE ,REFIT ,REPAIR & REALIGN DAMAGED PARTS	New	1,400.00	500.00
2	TO SPRAY PAINTING	New	1,200.00	500.00
3	TO REMOVE AND REFIT REAR WINDSCREEN	New	180.00	120.00
4	TO REMOVE AND REPLACE REAR TAIL-GATE (MECHANISM)	New	150.00	80.00
5	TO REMOVE AND REFIT REAR REVERSE CAMERA	New	80.00	50.00
6	TO RE-SET ELECTRICAL SYSTEM	New	180.00	30.00
7	TO RE-SEAL ANTI-RUST	New	80.00	40.00
8	TO CHECK WIRING	New	60.00	30.00
			<b>Gross Labour Cost (\$)</b>	<b>3,330.00</b>
				<b>1,350.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >