2/15/22, 3:01 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EGI22001268/KVF3N2

15/02/2022 Date:

REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:

Claimant Vehicle SJT3199S Insured Vehicle No: YN2641S

No:

Date of Loss: 21/01/2022 Nature of Claim: TP Claim No: CDMCG22000154

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJT3199S

Make & Model: TOYOTA COROLLA, 1.3 EE111 (M) Engine No: 3ZZ4939870

Reg. Date: 01/10/2009 (Man. Year: 2009) Chassis No: MR053ZEE106157513

Colour: Metallic Pearl White Odometer: 625838 km

Engine Capacity: 1598 cc Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: Pre-accident Condition: Yes No

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15 Front Left Side: Rear Left Side: Arivo 2 mm West Lake 4 mm Front Right Side: Arivo 2 mm Rear Right Side: West Lake 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		1,796.60	905.33	891.27	49.61
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,250.00	1,070.00	180.00	14.40
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	3,046.60	1,975.33	1,071.27	35.16
	Approved Total (Overridden) (S\$)		1,550.00		
	Nett Amount (S\$)	3,046.60	1,550.00	1,496.60	49.12

INSPECTION

Date of Assignment: 10/02/2022

Date Inspected: 10/02/2022 Inspected At:

BLK 10 AMK IND PK 2A #02-01

Singapore 568047

Ngs Automotive (HQ)

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG Manager: **VERON CHEN**

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 15 Feb 2022)

Parts: 143 TOYOTA COROLLA 1.3 EE111 (M) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJT3199S)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Cracked	447.90 F	*447.90 FL
2	1		*FRT BUMPER RETAINER LH	Distorted	56.50 F	*56.50 FL
3	1		*COVER,FRT BUMPER FOG LAMP LH	Serviceable	80.81 F	*- FL
4	1		*BONNET	Bent	465.17 F	*465.17 FL
5	2		*FRT BUMPER SIDE RETAINER RH/LH	Repeated	96.32 F	*- FL
6	20		*CLIPS,FENDER LINER	Not Necessary	70.00 F	*- FL
7	1		*FRT LOGO BADGE	Necessary	45.30 F	*45.30 FL
8	1		*SUPPORT PANEL	Repair	256.70 F	*-FL
9	1		*BRACE PANEL	Repair	43.00 F	*- FL
10	1		*FRT BUMPER GRILLE LOWER	Serviceable	56.00 F	*- FL
11	1		*RADIATOR GRILL	Distorted	138.90 F	*138.90 FL
12	1		*NO PLATE	Dented	40.00 FS	*40.00 FS
F=Fra	anchise	part. S=SpcN	ett. L=ListItemDisc.			
				Sub Total (S\$)	1,796.60	1,193.77
			- List Item Discount o	n L Items 0.00/25.00% (S\$)	0.00	288.44
				Total Parts (S\$)	1,796.60	905.33

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	TO REMOVE FRT DAMAGED PART WITH ALL NECESSARY COMPONENT/ATTACHN.STRAIGHTEN CHASSIS MEMBER,REPAIR/RESHAPE DENTED BODY PANEL.REPLACE DAMAGED PART.REFIT INTO POSITION	New	600.00	500.00
2	TO SPRAY PAINTING	New	600.00	550.00
3	CHECK WIRING & LIGHT FUNCTION	New	50.00	20.00
	Gross L	abour Cost (S\$)	1,250.00	1,070.00
	Report was unsubmitted during	this print-out		

< END OF ESTIMATES >