

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	LONPAC INSURAN	NCE BHD	Ref:	CS3/LPC22001269/Vvf3e2	
	300 BEACH ROAD #17-04/07 THE CO	NCOURSESINGAPORE 199555	Date:	16/03/2022	
			Code:	LPC2	
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	GBE 5965H	Veh. Inspected	PC 1949B	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	22/22/22/VC05/025437	Excess (\$)	0.00	
	Assign From	GERALD POH	Assign Date	10/02/2022	
2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA HIACE HIROOF	c.c	2982	
	Engine No.	HIDDEN	Year of Reg.	2013	
	Chassis No.	JTFST22P500017809	Colour	ORANGE	
	Odometer	843313 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	195 R15	DUNLOP	5 mm	
	L/H Front Tyre	195 R15	DUNLOP	5 mm	
	R/H Rear Tyre	195 R15	DUNLOP	5 mm	
	L/H Rear Tyre	195 R15	DUNLOP	5 mm	
4.	4. Description of Damages				
	THE VEHICLE SUS	STAINED DAMAGES AT THE REAR PORTION.			
5.	General Information				
	Accident Date	08/02/2022	Inspect Date / Time	23/02/2022 (04:00 PM)	
	Survey held at	A-TEC AUTOMOTIVE PTE LTD			
		8 KAKI BUKIT AVE 4 #05-27 PREMIER SINGAPORE 415875			
5a. Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

Report Ref No. CS3/LPC22001269/Vvf3e2

Inspected By

THEVAN THOMAS KARTHIKESAVAN

The

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser