

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22001272/UTY3N2**Date:** 06/04/2022REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00171322100

**Claimant Vehicle No :** SJT7333U **Insured Vehicle No :** SMP4895U

Date of Loss: 30/01/2022 Nature of Claim: TP Claim No: SNM22D201195/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJT7333U**

Make & Model: MERCEDES-BENZ E200, 1.8 (A) Engine No: 27186030004332

Reg. Date: 28/10/2009 (Man. Year: 2009) Chassis No: WDD2120482A080339

Colour: Grey Odometer: 145346 km

Engine Capacity: 1796 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 225/55R16 Rear Tyre Size: 225/55R16

Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,645.10	2,372.40	2,272.70	48.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,530.00	780.00	750.00	49.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,175.10</b>	<b>3,152.40</b>	<b>3,022.70</b>	<b>48.95</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,500.00</b>		
<b>(S\$)</b>	6,175.10	2,500.00	3,675.10	59.51
<b>+ GST 7.00/7.00% (S\$)</b>	432.26	175.00	257.26	59.52
<b>Nett Amount (S\$)</b>	<b>6,607.36</b>	<b>2,675.00</b>	<b>3,932.36</b>	<b>59.51</b>

INSPECTION

Date of Assignment: 10/02/2022

Date Inspected: 16/02/2022 Inspected At: Progressive Car Care Pte Ltd (HQ)  
Blk 3022A Ubi Road 1, #01-45/46  
Singapore 408716

Estimated Period of Repair: 3.0 days

**Adjuster:** MARCUS CHUA**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 05 Apr 2022)
<b>Parts:</b> 143	MERCEDES-BENZ E200 1.8 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SJT7333U)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed/Cut	1,620.00 FL	*1,620.00 FL
2	2		*FRONT BUMPER SIDE HOLDER-LH/RH	Not Necessary	100.00 FL	*- FL
3	10		*FRONT BUMPER CLIPS	Necessary	90.00 FL	*90.00 FL
4	1		*HEADLAMP ASSY-LH	Not Necessary	1,220.00 FL	*- FL
5	1		*FRONT FENDER COWLING-LH	Distorted	430.00 FL	*430.00 FL
6	10		*FRONT FENDER COWLING CLIPS-LH	Necessary	90.00 FL	*90.00 FL
7	1		*FRONT FENDER BLUE EFFICIENCY WORDINGS	Not Necessary	78.00 FL	*- FL
8	1		*FRONT BUMPER FOG LAMP-LH	Not Necessary	285.00 FL	*- FL
9	1		*FRONT BUMPER FOG LAMP CHROME-LH	Not Necessary	66.00 FL	*- FL
10	1		*FRONT BUMPER FOG LAMP GARNISH-LH	Not Necessary	48.00 FL	*- FL
11	1		*FRONT BUMPER OUTER LOWER CHROME STRIP-LH	Necessary	100.00 FL	*100.00 FL
12	1		*FRONT BUMPER SENSOR (NEAR WHEEL)-LH	Shorted	306.00 FL	*306.00 FL
13	1		*FRONT BUMPER SENSOR (ABOVE FOGLAMP)-LH	Not Necessary	306.00 FL	*- FL
14	1		*FRONT TYRE-LH	Serviceable	380.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>5,119.00</b>	<b>2,636.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$)</b>	473.90	263.60
<b>Total Parts (\$)</b>	<b>4,645.10</b>	<b>2,372.40</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO 4 WHEEL ALIGNMENT	New	100.00	60.00
2	TO KNOCK OUT DENTS,REMOVE & REPLACE ACCIDENT PORTIONS	New	550.00	300.00
3	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	800.00	400.00
4	TO CHECK WIRING	New	50.00	20.00
5	TO TUFF-KOTE	New	30.00	0.00
			<b>Gross Labour Cost (\$)</b>	<b>780.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >