

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22001273/TVY3N2**Date:** 07/04/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMHCSNW00014322100

Claimant Vehicle No : SME3700M **Insured Vehicle No :** SNC9364J

Date of Loss: 04/02/2022 Nature of Claim: TP Claim No: SNM22D200799/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SME3700M**

Make & Model: MAZDA 6, 2.0 SEDAN EXECUTIVE 2WD (A) Engine No: PE21186599

Reg. Date: 27/09/2018 (Man. Year: 2018) Chassis No: JM6GL1072K0303996

Colour: Maroon Odometer: 21828 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55R17 Rear Tyre Size: 225/55R17

Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,311.80	2,225.50	4,086.30	64.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,710.00	5,540.00	2,170.00	28.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	14,021.80	7,765.50	6,256.30	44.62
+ GST 7.00/7.00% (\$\$)	981.53	543.59	437.94	44.62
Nett Amount (\$\$)	15,003.33	8,309.09	6,694.24	44.62

INSPECTION

Date of Assignment: 10/02/2022

Date Inspected: 16/02/2022 Inspected At: Trans Eurokars Pte Ltd (Ubi)
5 Ubi Close
Singapore 408605

Estimated Period of Repair: 6.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Apr 2022)
Parts:	143	MAZDA 6 2.0 SEDAN EXECUTIVE 2WD (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SME3700M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER LH	Bent	383.70 F	*383.70 F
2	1		*STAY FENDER LH	Necessary	48.30 F	*48.30 F
3	1		*MUD GUARD LH FRT	Not Necessary	114.30 F	*- F
4	10		*FASTENER	Not Necessary	30.00 F	*- F
5	1		*DOOR FRONT LH	Bent	975.20 F	*975.20 F
6	1		*STRIPE NO,3 (L) BODY SIDE GL	Necessary	12.90 F	*12.90 F
7	1		*STRIPE NO,1 (L) BODY SIDE GL	Necessary	11.00 F	*11.00 F
8	1		*UPPER HINGE LH FRONT DOOR	Not Necessary	44.10 F	*- F
9	1		*LOWER HINGE LH FRONT DOOR	Not Necessary	41.70 F	*- F
10	1		*WEATHERSTRIP LH FRT DOOR	Not Necessary	90.70 F	*- F
11	10		*FASTENER (L)	Necessary	92.00 F	*92.00 F
12	1		*PAD COVER FRONT DOOR	Not Necessary	5.20 F	*- F
13	12		*GROMMET SCREW	Necessary	36.00 F	*36.00 F
14	1		*GROMMET SCREW	Necessary	3.80 F	*3.80 F
15	5		*FASTENER	Necessary	36.00 F	*36.00 F
16	1		*GARNISH LH FRONT DOOR	Necessary	99.10 F	*99.10 F
17	3		*CLIP,GARNISH	Necessary	36.90 F	*36.90 F
18	1		*GARNISH (L),SAIL-OUT GJ/GL	Necessary	96.60 F	*96.60 F
19	3		*CLIP,GARNISH	Necessary	33.00 F	*33.00 F
20	1		*MOULD OUTER FRONT DOOR LH	Not Necessary	96.00 F	*- F
21	1		*STONE GUARD LH	Necessary	198.00 F	*198.00 F
22	13		*CLIP	Necessary	130.00 F	*130.00 F
23	2		*CLIP	Necessary	13.00 F	*13.00 F
24	1		*HARNESS,FRONT DOOR LH	Not Necessary	250.70 F	*- F
25	1		*INSULATOR FENDER FRT LH	Not Necessary	81.30 F	*- F
26	1		*PLATE SEAL FENDER FRT LH	Not Necessary	55.20 F	*- F
27	1		*WHEEL,DISC 17X7	Not Necessary	1,196.80 F	*- F
28	1		*FRONT ABSORBER LH	Not Necessary	392.40 F	*- F
29	1		*BEARING TOP FRT ABSORBER	Not Necessary	55.80 F	*- F
30	1		*RUBBER MOUNTING TOP FRT ABSORBER	Not Necessary	96.50 F	*- F
31	1		*FRONT LOWER ARM LH	Not Necessary	503.90 F	*- F
32	1		*KNUCKLE LH FRT	Not Necessary	420.00 F	*- F
33	1		*HUB WHEEL BEARING FRT LH	Not Necessary	566.70 F	*- F
34	1		*NUT	Not Necessary	15.00 F	*- F
35	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	6,311.80	2,225.50
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RESPRAY FRONT FENDER LH,FRONT DOOR LH,ROCKER PANEL LH AND ALL AREAS AFFECTED BY THE ACCIDENTS	New	2,520.00	2,520.00
2	TO TRANSFER THE DOOR MECHANISM	New	660.00	180.00
3	TO REPLACE AXLE AND SUSPENSION MECHANISM	New	660.00	0.00
4	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT	New	560.00	560.00
5	TO MOUNT SPORT RIM AND CONDUCT WHEEL BALANCING	New	120.00	0.00
6	TO CHECK ELECTRICAL SYSTEM FOR PFOPER FUNCTIONING	New	250.00	120.00
7	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	300.00	180.00
8	TO REPLACE FRONT FENDER LH,FRONT DOOR LH,TO REPAIR ROCKER PANEL LH AND ALL AREAS AFFECTED BY THE ACCIDENTS	New	2,640.00	1,980.00
Gross Labour Cost (\$\$)			7,710.00	5,540.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >