

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22001274/VNY3Q2**Date:** 11/08/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00041822100

Claimant Vehicle No : SKK3373R **Insured Vehicle No :** SGS5436K

Date of Loss: 07/02/2022 Nature of Claim: TP Claim No: SNM22D200915/C02/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKK3373R**

Make & Model: NISSAN QASHQAI, 1.2 (A) Engine No: HRA2638119A

Reg. Date: 26/06/2018 (Man. Year: 2018) Chassis No: SJNFEAJ11U2306272

Colour: Grey Odometer: 45447 km

Engine Capacity: 1197 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R17 Rear Tyre Size: 215/60 R17

Front Left Side: Yokohama 7 mm Rear Left Side: Yokohama 7 mm

Front Right Side: Yokohama 7 mm Rear Right Side: Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,161.70	6,025.10	3,136.60	34.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,540.00	1,520.00	2,020.00	57.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	12,701.70	7,545.10	5,156.60	40.60
Approved Total (Overridden) (\$\$)		6,050.00		
Nett Amount (\$\$)	12,701.70	6,050.00	6,651.70	52.37

INSPECTION

Date of Assignment: 08/08/2022

Date Inspected: 11/02/2022 Inspected At: 8 KAKI BUKIT AVENUE 4#01-49 PREMIER @KAKI BUKIT

Estimated Period of Repair: 5.0 days Repairer: J.E.W AUTO PTE LTD

Adjuster: Thevan Thomas Karthikesavan**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Aug 2022)
Parts:	M1-SUV	NISSAN QASHQAI 1.2 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKK3373R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	2,936.00 FL	*2,936.00 FL
2	1		*TAILGATE LOGO	Necessary	60.00 FL	*60.00 FL
3	1		*TAILGATE QASHQAI EMBLEM	Necessary	87.00 FL	*87.00 FL
4	1		*TAILGATE PULL HANDLE	Serviceable	26.00 FL	*- FL
5	1		*TAILGATE INNER TRIM BOARD	Cracked	317.00 FL	*317.00 FL
6	1		*TAILGATE LOCK	Serviceable	117.00 FL	*- FL
7	1		*TAILGATE LOCK CATCH	Serviceable	32.00 FL	*- FL
8	1		*TAILGATE RH LAMP	Cracked	216.00 FL	*216.00 FL
9	1		*TAILGATE LH LAMP	Cracked	216.00 FL	*216.00 FL
10	1		*TAILGATE WEATHERSTRIP	Cut	159.00 FL	*159.00 FL
11	1		*TAILGATE WINDSCREEN GLASS RUBBER MOULDING	Necessary	118.00 FL	*118.00 FL
12	1		*REAR BUMPER	Dented	755.00 FL	*755.00 FL
13	1		*SET REAR BUMPER CLIPS	Necessary	70.00 FL	*70.00 FL
14	1		*REAR BUMPER RH REFLECTOR	Cracked	55.00 FL	*55.00 FL
15	1		*REAR BUMPER LH REFLECTOR	Cracked	55.00 FL	*55.00 FL
16	1		*REAR BUMPER REINFORCEMENT	Bent	620.00 FL	*620.00 FL
17	1		*REAR BUMPER REINFORCEMENT RH BRACKET	Serviceable	126.00 FL	*- FL
18	1		*REAR BUMPER REINFORCEMENT LH BRACKET	Serviceable	126.00 FL	*- FL
19	1		*REAR BUMPER RH SIDE RETAINER	Necessary	36.00 FL	*36.00 FL
20	1		*REAR BUMPER LH SIDE RETAINER	Necessary	36.00 FL	*36.00 FL
21	1		*REAR BUMPER SPONGE	Cracked	127.00 FL	*127.00 FL
22	1		*REAR BUMPER TOWING COVER	Distorted	28.00 FL	*28.00 FL
23	1		*END PANEL	Bent	483.00 FL	*483.00 FL
24	1		*END PANEL INNER GARNISH	Deformed	65.00 FL	*65.00 FL
25	1		*END PANEL ANTENNA SENSOR	Serviceable	76.00 FL	*- FL
26	1		*REAR RH FENDER INNER TRIM BOARD	Serviceable	366.00 FL	*- FL
27	1		*REAR LH FENDER INNER TRIM BOARD	Serviceable	366.00 FL	*- FL
28	1		*REAR FLOOR PANEL RH SIDE TRAY GARNISH	Serviceable	234.00 FL	*- FL
29	1		*REAR FLOOR PANEL LH SIDE TRAY GARNISH	Serviceable	234.00 FL	*- FL
30	1		*REAR FLOOR PANEL RH SPONGE TRAY	Serviceable	85.00 FL	*- FL
31	1		*REAR FLOOR PANEL LH SPONGE TRAY	Serviceable	85.00 FL	*- FL
32	1		*REAR FLOOR PANEL TOP COVER	Serviceable	395.00 FL	*- FL
33	1		*EXHAUST SILENCER HEAT SHIELD	Serviceable	138.00 FL	*- FL
34	1		*EXHAUST SILENCER	Serviceable	823.00 FL	*- FL
35	1		*EXHAUST SILENCER GASKET	Serviceable	45.00 FL	*- FL
36	1		*REAR NUMBER PLATE	Serviceable	70.00 FS	*- FS
37	1		*END PANEL SEALANT	Necessary	50.00 FS	*30.00 FS
38	1		*SET REAR REVERSE SENSORS	Cut	300.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,133.00	6,669.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	971.30	643.90
Total Parts (\$\$)	9,161.70	6,025.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REPLACE PARTS AND ALL AFFECTED AREAS	New	1,000.00	600.00
2	SPRAY PAINTING ON ALL AFFECTED PARTS AND AREAS	New	1,200.00	600.00
3	CHECK WIRING AND LIGHTING SYSTEM	New	100.00	30.00
4	APPLY RUST COATING ON AFFECTED AREAS	New	100.00	30.00
5	REMOVE AND REFIT TAILGATE WINDSCREEN GLASS	New	250.00	120.00
6	REMOVE AND REPLACE TAILGATE INNER PARTS TO NEW TAILGATE	New	220.00	60.00
7	REMOVE AND REPLACE REAR REVERSE SENSORS	New	100.00	20.00
8	REMOVE AND REPLACE REAR GARNISH AND BOARDS	New	350.00	60.00
9	REMOVE AND REPLACE EXHAUST SILENCER	New	220.00	0.00
Gross Labour Cost (\$\$)			3,540.00	1,520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >