

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22001276/UQY3N2**Date:** 25/02/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00236072101

Claimant Vehicle No : SLV1596H **Insured Vehicle No :** SME6622K

Date of Loss: 29/01/2022 Nature of Claim: TP Claim No: SNM22D200810/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLV1596H**

Make & Model: HONDA SHUTTLE HYBRID, 1.5 (A) Engine No: LEB6325459

Reg. Date: 22/12/2017 (Man. Year: 2017) Chassis No: GP71120654

Colour: Black Odometer: 97699 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/55 R15 Rear Tyre Size: 195/55 R15

Front Left Side: Maxxis 6 mm Rear Left Side: Yokohama 6 mm

Front Right Side: Maxxis 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,904.13	3,397.36	3,506.77	50.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,180.00	2,040.00	1,140.00	35.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,084.13	5,437.36	4,646.77	46.08
Approved Total (Overridden) (S\$)		4,300.00		
(S\$)	10,084.13	4,300.00	5,784.13	57.36
+ GST 7.00/7.00% (S\$)	705.89	301.00	404.89	57.36
Nett Amount (S\$)	10,790.02	4,601.00	6,189.02	57.36

INSPECTION

Date of Assignment: 14/02/2022

Date Inspected: 15/02/2022 Inspected At: SHIN AUTOMOBILE & TRADING PTE LTD (HQ)
15 Kaki Bukit Rd 4, #01-46 BARTLY BIZ CENTRE
Singapore 417808

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 25 Feb 2022)	
Parts:	N/A	HONDA SHUTTLE HYBRID 1.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLV1596H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,150.60 FL	*953.00 FL
2	2		*REAR BUMPER SIDE RETAINER	Necessary	56.80 FL	*56.80 FL
3	2		*REAR BUMPER SPONGE	Not fitted	113.00 FL	*- FL
4	2		*REAR BUMPER REFLECTOR	Not Necessary	90.40 FL	*- FL
5	2		*REAR BUMPER REFLECTOR GARNISH	Not Necessary	91.60 FL	*- FL
6	2		*REAR BUMPER TOW COVER	Not Necessary	26.50 FL	*- FL
7	1		*TAIL GATE	Badly Dented	1,193.20 FL	*1,193.20 FL
8	1		*TAIL GATE WEATHERSTRIPE	Twisted	168.40 FL	*168.40 FL
9	1		*TAIL GATE LOCK	Bent	96.90 FL	*96.90 FL
10	1		*TAIL GATE OUTER GARNISH	Not Necessary	168.40 FL	*- FL
11	1		*TAIL GATE EMBLEM LOGO	Not Necessary	80.70 FL	*- FL
12	1		*TAIL GATE EMBLEM SHUTTLE	Necessary	55.40 FL	*55.40 FL
13	1		*TAIL GATE INNER TRIM BOARD	Torn	320.40 FL	*320.40 FL
14	2		*TAIL GATE REFLECTOR	Serviceable	681.60 FL	*- FL
15	1		*TAIL GATE PULL POCKET	Not Necessary	65.60 FL	*- FL
16	1		*REAR WINDSCREEN GLASS MOULDING	Necessary	149.20 FL	*149.20 FL
17	2		*TAIL LAMP	Not Necessary	1,041.00 FL	*- FL
18	1		*REAR END PANEL	Dented	560.80 FL	*560.80 FL
19	2		*REAR END SIDE PANEL	Bent	217.60 FL	*217.60 FL
20	1		*REAR END PANEL INNER TRIM	Not Necessary	287.60 FL	*- FL
21	1		*SET REVERSE SENSOR	Shorted	250.00 FS	*200.00 FS
22	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*50.00 FS
23	1		*SET TAIL GATE INNER TRIM BOARD CLIPS	Not Necessary	80.00 FS	*- FS
24	1		*SET REAR WINDSCREEN CLIPS	Not Necessary	80.00 FS	*- FS
25	1		*SET TAIL GATE OUTER GARNISH CLIPS	Not Necessary	80.00 FS	*- FS
26	1		*SET REAR END PANEL INNER TRIM CLIPS	Not Necessary	80.00 FS	*- FS
27	1		*SET REAR WINDSCREEN GLASS INNER SEAL	Necessary	80.00 FS	*40.00 FS
28	1		*SET REAR WINDSCREEN GLASS SEALANT	Necessary	60.00 FS	*40.00 FS
29	1		*SET TAILGATE SEALANT	Not Necessary	80.00 FS	*- FS
30	1		*SET REAR END PANEL SEALANT	Necessary	80.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	7,565.70	4,151.70
- List Item Discount on L Items 10.00/20.00% (\$)	661.57	754.34
Total Parts (\$)	6,904.13	3,397.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING SYSTEM	New	80.00	20.00
2	TO RESET AND REPROGRAMME AFTER REPAIR	New	200.00	50.00
3	TO REMOVE & REFIX INTERIOR UPHOLSTERY	New	200.00	80.00
4	TO REMOVE & REFIX REAR WINDSCREEN GLASS	New	150.00	120.00
5	TO REMOVE & REFIX REVERSE SENSOR	New	100.00	50.00
6	TO REMOVE & REFIX TAILGATE MECHANISM	New	100.00	60.00
7	TO RESET AND REPROGRAMME AFTER REPAIR	New	200.00	0.00
8	TO CUT AND WELD ON REAR END PANEL.TO PANEL BEAT AND STRAIGHTEN ON SPARE TYRE PANEL,REAR BOTH FENDERS.TO R&R REAR BUMPER,TAILGATE,TAILLAMPS AND OTHER ATTACHMENTS	New	1,000.00	800.00
9	TO PUTTY AND RESPRAY ON REAR BUMPER,TAIL GATE,REAR BOTH FENDERS,REAR END PANEL,SPARE TYRE PANEL AND ACCIDENT AFFECTED AREAS	New	1,000.00	800.00
10	TO TUFF COAT AFFECTED AREAS	New	150.00	60.00
Gross Labour Cost (\$\$)			3,180.00	2,040.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >