



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBJ 8874R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	LH FRONT DOOR	DENTED	2,071.00	1,910.00
2	LH FRONT DOOR QTR GARNISH GROMMET @\$5.50	NECESSARY	11.00	11.00
1	LH FRONT DOOR SEAL	TORN	439.00	439.00
1	LH FRONT DOOR HINGE LOWER	BENT	165.00	125.00
1	LH FRONT DOOR TRIM	NOT NECESSARY	559.00	-
10	LH FRONT DOOR TRIM CLIPS @\$6.00	NOT NECESSARY	60.00	-
1	LH FRONT DOOR WINDOW REGULATOR	BENT	1,363.00	1,200.00
1	FRONT DOOR OUTER GARNISH	NOT NECESSARY	255.00	-
1	DOOR VENTILATION LH	BROKEN	50.00	50.00
1	LH FRONT DOOR SPEAKER	NOT NECESSARY	350.00	-
1	SCUFF PLATE	CRUSHED	150.00	150.00
1	LH FRONT SIDE STEP	NOT NECESSARY	539.00	-
1	LH FRONT CORNER PANEL	TO REPAIR SEE LABOUR	524.00	-
6	LH FRONT CORNER PANEL CLIPS @\$5.00	NOT NECESSARY	30.00	-
1	CORNER PANEL TOP PANEL	NOT NECESSARY	42.00	-
	LESS 25% DISCOUNT		-1,652.00	-971.25
			4,956.00	2,913.75
<u>SPECIAL NETT ITEMS</u>				
1	TYRE 185/75 R15 (SN)	NOT NECESSARY	250.00	-
1	SET RIVET (SN)	NECESSARY	80.00	20.00
1	COMPANY REG STICKER (SN)	NECESSARY	40.00	30.00
			370.00	50.00
<u>LABOUR</u>				
	TO PANEL BEAT /KNOCKING/WELDING THE LH A-PILLAR & ROCKER PANEL .TO REALIGN ALL CONNECTION & REPLACE DAMAGED PARTS.INCLUSIVE OF THE REPAIR OF LH FRONT CORNER PANEL.		500.00	400.00
	TO SPRAY PAINT ON LH CORNER PANEL ,LH A-PILLAR LH LOWER DOOR HINGE ,LH FRONT DOOR ,LH SCUFF PLATE PANEL.		800.00	500.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO APPLY ANTI RUST PROOFING ON LH DOOR ASSY & SCUFF PLATE PANEL.		80.00	20.00
	TO TRANSFER LH FRONT DOOR WINDOW GLASS DOOR LOCK WEATHERSTRIP TO NEW UNIT.		80.00	30.00
	TO CONDUCT WIRING CHECK /DIAGNOSE RESET SYSTEM AFTER REPAIR.		180.00	30.00
	TO CONDUCT WHEEL ALIGNMENT.	NOT NECESSARY	180.00	-
	TO REMOVE & INSTALL STEEL CAGE TO NEW DOOR UNIT.		180.00	30.00
			2,000.00	1,010.00
GRAND TOTAL			7,326.00	3,973.75
RECOMMENDED COST OF REPAIRS				3,973.75

Report Ref No. CC2/MIDA22001277/Epq2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.