

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/GRB21010027/EVF3E2-1

Date: 15/02/2022

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447
Claimant Vehicle No : FBK1759G **Insured Vehicle No :** SLT641C
Date of Loss: 21/09/2021 Nature of Claim: TP Claim No: MFL2021D0004118

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBK1759G**
Make & Model: YAMAHA FZS1000, 998cc Engine No: N511E004913
Reg. Date: 06/04/2005 (Man. Year: 2005) Chassis No: JYARN141000004080
Colour: Red Odometer: 0 km
Engine Capacity: 998 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 120/70Z R17 Rear Tyre Size: 180/55Z R19
Front Left Side: Bridgestone 4 mm Rear Left Side: Bridgestone 4 mm
Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,043.90	3,002.60	4,041.30	57.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,760.00	830.00	930.00	52.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,803.90	3,832.60	4,971.30	56.47
Approved Total (Overridden) (S\$)		3,050.00		
Nett Amount (S\$)	8,803.90	3,050.00	5,753.90	65.36

INSPECTION

Date of Assignment: 10/02/2022
Date Inspected: 28/09/2021 Inspected At: QRWAVE PTE LTD (HQ)
50 Bukit Batok Street 23, #02-25 Midview Building
Singapore 659578
Estimated Period of Repair: 4.0 days

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 15 Feb 2022)	
Parts:	N/A	YAMAHA FZS1000 998cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBK1759G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER REAR FENDER	Not Necessary	521.00 FL	*- FL
2	1		*FENDER REAR	Not Necessary	119.00 FL	*- FL
3	1		*FENDER FRONT	Not Necessary	114.00 FL	*- FL
4	1		*SIDE COVER 2	Grazed / Cracked	211.00 FL	*211.00 FL
5	1		*SIDE DAMPER 1	Necessary	15.00 FL	*15.00 FL
6	1		*SIDE DAMPER 2	Necessary	12.00 FL	*12.00 FL
7	1		*CASE CHAIN	Not Necessary	141.00 FL	*- FL
8	1		*SEAL GUARD	Necessary	55.00 FL	*55.00 FL
9	1		*SWING ARM	Not Necessary	890.00 FL	*- FL
10	1		*BODY FRONT UPPER 1	Cracked	542.00 FL	*380.00 FL
11	1		*FRONT BODY UPPER INNER GARNISH LH	Cracked	231.00 FL	*231.00 FL
12	1		*PANEL INNER 1	Not Necessary	311.00 FL	*- FL
13	1		*PANEL INNER 2	Not Necessary	214.00 FL	*- FL
14	1		*REAR VIEW MIRROR LH	Grazed	131.00 FL	*131.00 FL
15	1		*FRONT FLASHER LIGHT ASSY RH	Not Necessary	76.00 FL	*- FL
16	1		*FRONT FLASHER LIGHT ASSY LH	Grazed	76.00 FL	*76.00 FL
17	1		*FRONT HEADLIGHT ASSY	Not Necessary	657.00 FL	*- FL
18	1		*LEVER HOLDER ASSY LH	Grazed	119.00 FL	*70.00 FL
19	1		*FOOTREST ASSY LH	Bent	212.00 FL	*212.00 FL
20	1		*FOOTREST BRACKET LH	Not Necessary	341.00 FL	*- FL
21	1		*FOOTREST ASSY BRACKET REAR LH	Not Necessary	192.00 FL	*- FL
22	1		*GEAR SHIFTER PEDAL ASSY	Bent	214.00 FL	*145.00 FL
23	1		*ENGINE COVER	Grazed	354.00 FL	*354.00 FL
24	1		*RADIATOR COVER LH	Grazed	119.00 FL	*119.00 FL
25	1		*HANDLE BAR	Bent	430.00 FL	*140.00 FL
26	1		*SET BALANCE	Grazed	120.00 FL	*120.00 FL
27	1		*HANDLE GRIP LH	Not Necessary	101.00 FL	*- FL
28	2		*SLIDER	Not Necessary	110.00 FL	*- FL
29	1		*FUEL TANK	Dented	832.00 FL	*832.00 FL
30	1		*FRONT NUMBER PLATE	Not Necessary	80.00 FS	*- FS
31	1		*BOT COOLANT	Necessary	60.00 FS	*20.00 FS
32	1		*FoOTREST ASSY REAR LH	Bent	211.00 FL	*211.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,811.00	3,334.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	767.10	331.40
Total Parts (\$\$)	7,043.90	3,002.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE, REALIGN AND ADJUST ABOVE DAMAGE PARTS AND CHECK WIRING AND LIGHTNING SYSTEM	New	600.00	300.00
2	TO KNOCK, STRAIGHTEN CHASSIS AND BODY BALANCING	New	380.00	150.00
3	TO REMOVE / REFIT, STRAIGHTEN FRONT FORK TUDES	New	180.00	0.00
4	SPRAY PAINTING	New	450.00	300.00
5	TOWING SERVICE	New	150.00	80.00
			Gross Labour Cost (\$\$)	1,760.00
				830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >