

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22001283/ATY3N2**Date:** 09/06/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMHCSNW00010152100

**Claimant Vehicle No :** SJU7833M **Insured Vehicle No :** SMP3796D

Date of Loss: 08/02/2022 Nature of Claim: TP Claim No: SNM22D200919/C02

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SJU7833M**

Make & Model: MERCEDES-BENZ C180, 1.5 AVANTGARDE LN (A) Engine No: 27491030372087

Reg. Date: 15/07/2015 (Man. Year: 2015) Chassis No: WDD2050402R058595

Colour: Silver Odometer: 138628 km

Engine Capacity: 1595 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 225/50R17 Rear Tyre Size: 225/50R17

Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	9,558.00	5,790.00	3,768.00	39.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,972.00	1,662.00	3,310.00	66.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>14,530.00</b>	<b>7,452.00</b>	<b>7,078.00</b>	<b>48.71</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,017.10</b>	<b>521.64</b>	<b>495.46</b>	<b>48.71</b>
<b>Nett Amount (S\$)</b>	<b>15,547.10</b>	<b>7,973.64</b>	<b>7,573.46</b>	<b>48.71</b>

**INSPECTION**

Date of Assignment: 08/06/2022

Date Inspected: 15/02/2022 Inspected At: 24 BENOI SECTOR  
SINGAPORE 629857  
REPAIRER: PREMIUM AUTOCARE CENTRE

Estimated Period of Repair: 4.0 days

**Adjuster:** ADRIAN LING**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$260.00 NETT)

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 Jun 2022)
Parts:	143	MERCEDES-BENZ C180 1.5 AVANTGARDE LN (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJU7833M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,820.00 FS	*1,820.00 FS
2	1		*FRONT BUMPER PRESSURE SENSOR	Activated	230.00 FS	*230.00 FS
3	1		*FRONT BUMPER CARRIER	Not Necessary	164.00 FS	*- FS
4	1		*FRONT BUMPER COVER	Not Necessary	90.00 FS	*- FS
5	1		*FRONT BUMPER FILLER FOAM	*Check	224.00 FS	*- FS
6	2		*FRONT BUMPER SIDE GUIDE-LH/RH	*Check	36.00 FS	*- FS
7	2		*FRONT BUMPER SIDE BRACKET-LH/RH	Not Necessary	180.00 FS	*- FS
8	1		*FRONT BONNET	Not Necessary	2,080.00 FS	*- FS
9	2		*FRONT BONNET HINGE-LH/RH	Damaged	380.00 FS	*380.00 FS
10	2		*FRONT BONNET ACTUATOR-LH/RH	Activated	400.00 FS	*400.00 FS
11	1		*FRONT BONNET MERCEDES EMBLEM	Not Necessary	80.00 FS	*- FS
12	1		*FRONT RADIATOR GRILLE BRACKET	Not Necessary	138.00 FS	*- FS
13	1		*FRONT RADIATOR GRILLE CHROME	Not Necessary	210.00 FS	*- FS
14	4		*FRONT RADIATOR GRILLE CHROME TRIM-LH/RH/UPPER	Not Necessary	350.00 FS	*- FS
15	1		*FRONT RADIATOR LOGO BRACKET	Not Necessary	82.00 FS	*- FS
16	1		*MERCEDES STAR EMBLEM	Not Necessary	134.00 FS	*- FS
17	1		*FRONT HEADLIGHT-RH	Cut	2,960.00 FS	*2,960.00 FS
					Total Parts (S\$)	9,558.00 5,790.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	120.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	200.00
3	TO DISMANTLE AND RENEW FRONT BUMPER.TO REMOVE AND REINSTALL BONNET TO FACILITATE RENEWAL OF HINGES.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	2,400.00	350.00
4	TO CARRY OUT CALIBRATION AND CODING FOR AIRBAG SYSTEM (NPA)	New	0.00	0.00
5	TO RESPRAY FRONT BUMPER AND BONNET HINGES	New	1,500.00	800.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (\$\$)</b>			<b>4,972.00</b>	<b>1,662.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >