



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. XE 1119A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	STEP PANEL - LH (CONSISTENT)	TO REPAIR SEE LABOUR	744.59	-
1	ALUMINIUM STAND PANEL LOWER - LH (CONSISTENT)	CRACKED	289.84	289.84
1	STEP PANEL GARNISH LOWER - LH (CONSISTENT)	CRACKED	270.56	270.56
1	STEP PANEL GARNISH LOWER COVER - LH (CONSISTENT)	NOT NECESSARY	229.87	-
1	STEP PANEL BRACKET FRONT - LH (CONSISTENT)	TO REPAIR SEE LABOUR	289.84	-
1	STEP PANEL BRACKET REAR - LH (CONSISTENT)	BENT	324.55	324.55
	LESS 25% DISCOUNT		-537.31	-221.24
			1,611.94	663.71
	<u>LABOUR</u>			
	LABOUR TO CUT, WELD, KNOCK, DISMANTLE ALL PARTS. INCLUSIVE OF THE REPAIR OF STEP PANEL - LH AND STEP PANEL BRACKET FRONT - LH.		1,500.00	420.00
	TO SPRAY & PAINTING ON AFFECTED AREA.		680.00	180.00
	TO RUST PROOFING AFFECTED AREA.	NOT NECESSARY	280.00	-
			2,460.00	600.00
GRAND TOTAL			4,071.94	1,263.71
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,000.00

Report Ref No. CS/ASM22001291/Uvy3e2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.