



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## PRE-REPAIR INSPECTION REPORT

AXA INSURANCE PTE LTD

Ref: CS3/ASM22001296/Rqy3e2

8 SHENTON WAY #24-01 AXA TOWER  
SINGAPORE 068811

Date: 06/05/2022

ATTN: ONG KIAN THENG DERICK

Code: ASM

### 1. Policy Particulars :- (THIRD PARTY CLAIM)

<b>Insured Veh.</b>	SHA 7873B	<b>Veh. Inspected</b>	SMN 3116C
<b>Policy No.</b>	VFX/P2419138	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	S2M03T1H	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	ONG KIAN THENG DERICK	<b>Assign Date</b>	10/02/2022

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	HONDA FIT 1.3 GF CVT	<b>c.c</b>	1317
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2019
<b>Chassis No.</b>	GK33417080	<b>Colour</b>	GREY
<b>Odometer</b>	14533 KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	FAIR		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	175/65 R14	ACENDA	6 mm
<b>L/H Front Tyre</b>	175/65 R14	ACENDA	6 mm
<b>R/H Rear Tyre</b>	175/65 R14	ACENDA	6 mm
<b>L/H Rear Tyre</b>	175/65 R14	ACENDA	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.	
--	---

### 5. General Information

<b>Accident Date</b>	09/02/2022	<b>Inspect Date / Time</b>	11/02/2022 ( 02:52 PM )
<b>Survey held at</b>	BLK 7 SIN MING IND EST SEC C #01-94		
<b>Repairer</b>	MJE MOTOR		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000-\$6,000
---

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	<b>8 Working Days</b>
-------------------------------------	-----------------------

Report Ref No. CS3/ASM22001296/Rqy3e2

#### Inspected By

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.