

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22001302/AEA3Q2**Date:** 15/08/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900170689
Claimant Vehicle No :	SMM4481X	Insured Vehicle No :	SMP5728M
Date of Loss:	01/02/2022	Nature of Claim:	TP
		Claim No:	6536462033SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMM4481X		
Make & Model:	RENAULT GRAND SCENIC IV, 1.5 DCI EU6 (A)	Engine No:	K9KF649D059824
Reg. Date:	28/06/2019 (Man. Year: 2019)	Chassis No:	VF1RFA00X62673000
Colour:	Grey	Odometer:	185125 km
Engine Capacity:	1461 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/55 R20	Rear Tyre Size:	195/55 R20
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	24,999.43	4,475.71	20,523.72	82.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,520.00	1,320.00	3,200.00	70.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	29,519.43	5,795.71	23,723.72	80.37
Approved Total (Overridden) (S\$)		4,600.00		
(S\$)	29,519.43	4,600.00	24,919.43	84.42
+ GST 7.00/7.00% (S\$)	2,066.36	322.00	1,744.36	84.42
Nett Amount (S\$)	31,585.79	4,922.00	26,663.79	84.42
+ Car Rental (6.0 x S\$100.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		5,529.45		
Global Sum Settlement (S\$)		5,520.00		

INSPECTION

Date of Assignment:	09/02/2022		
Date Inspected:	09/02/2022	Inspected At:	Xin Hua Workshop Pte Ltd (HQ) 23 Kaki Bukit Ave 4 #04-01 Singapore 415933
Estimated Period of Repair:	4.0 days		

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RR BUMPER	Torn	1,345.00 FL	*1,345.00 FL
2	1		*RR BUMPER LOW	Repair	645.30 FL	*- FL
3	1		*RR BUMPER LOW MLDG	Not Necessary	812.00 FL	*- FL
4	1		*RR BUMPER TOW COVER	Not Necessary	104.00 FL	*- FL
5	1		*RR BUMPER CENTRE RETAINER	Not Necessary	417.00 FL	*- FL
6	1		*RR BUMPER SIDE RETAINER LH (INNER)	Necessary	171.00 FL	*95.00 FL
7	1		*RR BUMPER SIDE RETAINER LH (OUTER)	Necessary	335.00 FL	*150.00 FL
8	1		*RR BUMPER LOW BRACKET LH	Not Necessary	132.00 FL	*- FL
9	2		*RR BUMPER LOW BRACKET CENTRE	Not Necessary	202.00 FL	*- FL
10	1		*RR FENDER INNERSHIELD END LH	Cut	274.00 FL	*274.00 FL
11	1		*RR BUMPER REINFORCEMENT	Not Necessary	799.00 FL	*- FL
12	1		*RR KEY RECEIVER SENSOR	Not Necessary	297.00 FL	*- FL
13	2		*RR BUMPER REVERSE SENSOR	Not Necessary	594.00 FL	*- FL
14	2		*RR BUMPER REVERSE SENSOR HOLDER	Not Necessary	165.80 FL	*- FL
15	2		*RR BUMPER BLIND SPOT SENSOR	Not Necessary	968.00 FL	*- FL
16	6		*RR BUMPER REVERSE SENSOR RUBBER SEAL	Not Necessary	84.00 FL	*- FL
17	1		*RR BUMPER REVERSE SENSOR WIRE HARNESS	Not Necessary	261.00 FL	*- FL
18	1		*RR BUMPER REFLECTOR LH	Not Necessary	516.00 FL	*- FL
19	1		*RR TAILGATE MLDG	Not Necessary	552.00 FL	*- FL
20	1		*RR TAILGATE	Not Necessary	3,720.00 FL	*- FL
21	1		*RR TAILGATE RENAULT LOGO	Not Necessary	193.00 FL	*- FL
22	1		*RR TAILGATE SCENIC EMBLEM	Not Necessary	176.00 FL	*- FL
23	1		*RR TAILGATE RENAULT EMBLEM	Not Necessary	152.00 FL	*- FL
24	2		*RR TAILGATE NUMBER PLATE LAMP	Not Necessary	80.00 FL	*- FL
25	1		*RR TAILGATE LOCK	Not Necessary	353.00 FL	*- FL
26	1		*RR TAILGATE LOCK STRIKER	Not Necessary	114.00 FL	*- FL
27	1		*RR TAILGATE DAMPER	Not Necessary	265.00 FL	*- FL
28	1		*RR TAILGATE LOCK OPEN SWITCH	Not Necessary	231.00 FL	*- FL
29	1		*RR TAILGATE STOPED	Not Necessary	628.00 FL	*- FL
30	1		*RR TAILGATE INNER TRIM BOARD	Not Necessary	950.00 FL	*- FL
31	1		*RR TAILGATE REFLECTOR LH	Not Necessary	640.00 FL	*- FL
32	1		*RR TAILGATE WEATHERSTRIP	Not Necessary	230.00 FL	*- FL
33	1		*RR TAILLAMP LH	Not Necessary	640.00 FL	*- FL
34	1		*RR END PANEL OUTER	Not Necessary	1,088.00 FL	*- FL
35	1		*RR END PANEL INNER	Not Necessary	492.00 FL	*- FL
36	1		*RR END PANEL SUPORT LH	Not Necessary	359.00 FL	*- FL
37	1		*RR END PANEL TOP GARNISH	Not Necessary	332.00 FL	*- FL
38	1		*RR TAILLAMP PANEL LH	Not Necessary	419.00 FL	*- FL
39	1		*RR FENDER INNERSHIELD LH	Not Necessary	391.00 FL	*- FL
40	1		*RR FENDER AIR DUCT LH	Not Necessary	195.00 FL	*- FL
41	1		*RR FENDER MUDGUARD LH (RR)	Not Necessary	135.00 FL	*- FL
42	1		*RR FENDER INNER TRIM LH	Not Necessary	749.00 FL	*- FL
43	1		*RR FENDER LH	Repair	1,254.90 FL	*- FL
44	1		*RR DOOR LH	Buckled	1,548.60 FL	*1,548.60 FL
45	1		*SIDESKIRT LH	Not Necessary	879.60 FL	*- FL
46	1		*RR RIM LH	Cut	1,312.47 FS	*880.00 FS
47	1		*RR WHEEL HUB BEARING LH	Damaged	549.30 FL	*549.30 FL
48	1		*RR ABSORBER LH	Not Necessary	385.90 FL	*- FL
49	10		*RR BUMPER CLIP	Necessary	100.00 FS	*30.00 FS
50	10		*RR TAILGATE GARNISH CLIP	Not Necessary	50.00 FS	*- FS
51	1		*RR NUMBER PLATE	Not Necessary	200.00 FS	*- FS
52	1		*SET RR FENDER INNER SHIELD CLIPS	Not Necessary	30.00 FS	*- FS
53	1		*BODY PANEL JOINT SEALER	Not Necessary	65.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **27,581.87** **4,871.90**

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
- List Item Discount on L Items 10.00/10.00% (S\$)					2,582.44	396.19
Total Parts (S\$)					24,999.43	4,475.71

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE /RENEW THE ACCIDENT DAMAGED PORTION ,TO PANEL BEATING ,RESHAPE ,STRAIGHTEN ,ORIENTATE AND ALIGN REPAIR/REPLACEMENT PARTS	New	1,800.00	400.00
2	CARRY OUT SPRAY PAINTING ON AFFECTED AREA	New	1,800.00	800.00
3	TO CONDUCT ANTI RUST OF UNDER CARRIAGE TUFF COAT	New	100.00	40.00
4	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS ,RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR	New	120.00	30.00
5	TO REMOVE AND REFIX REVERSE SENSOR AND CONDUCT TEST	New	120.00	50.00
6	TO REMOVE AND REFIX REVERSE CAMERA AND CONDUCT TEST	New	120.00	0.00
7	TO CONDUCT TRANSFER OF PARTS FROM OLD TAILGATE TO NEW TAILGATE	New	180.00	0.00
8	TO CONDUCT WATER LEAKAGE TEST AFTER REPAIRS OF VEHICLE	New	80.00	0.00
9	TO REMOVE AND REFIX REAR UNDERCARRIAGE	New	200.00	0.00
Gross Labour Cost (\$\$)			4,520.00	1,320.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >