

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22001303/BTF3N2**Date:** 06/04/2022**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00143252100

Claimant Vehicle No : SJX9993E**Insured Vehicle No :** SMU6993E

Date of Loss: 29/01/2022

Nature of Claim: TP

Claim No: SNM22D200809/C02/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SJX9993E**

Make & Model: TOYOTA CAMRY, 2.0 (A)

Engine No: 1AZ3209999

Reg. Date: 10/11/2005 (Man. Year: 2005)

Chassis No: MR053BK3106012787

Colour: Grey

Odometer: 145510 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55ZR17

Rear Tyre Size: 205/55ZR17

Front Left Side: Rydanz 5 mm

Rear Left Side: Rydanz 5 mm

Front Right Side: Rydanz 5 mm

Rear Right Side: Rydanz 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,929.46	9,183.12	12,746.34	58.12
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,080.00	2,800.00	5,280.00	65.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	30,009.46	11,983.12	18,026.34	60.07
Approved Total (Overridden) (S\$)		9,500.00		
(S\$)	30,009.46	9,500.00	20,509.46	68.34
+ GST 7.00/7.00% (S\$)	2,100.66	665.00	1,435.66	68.34
Nett Amount (S\$)	32,110.12	10,165.00	21,945.12	68.34

INSPECTION

Date of Assignment: 30/03/2022

Date Inspected: 15/02/2022 Inspected At:

Bifrost Auto Pte Ltd (Kaki Bukit)
8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit
Singapore 415875

Estimated Period of Repair: 9.0 days

Adjuster: Lim Teow Guan**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Apr 2022)
Parts:	143	TOYOTA CAMRY 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJX9993E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Broken	950.20 FL	*561.80 FL
2	2		*REAR BUMPER SIDE RETAINER (LONG)	Necessary	130.00 FL	*69.40 FL
3	2		*REAR BUMPER SIDE RETAINER (SHORT)	Necessary	104.00 FL	*104.00 FL
4	1		*REAR BUMPER REINFORCEMENT	Bent	794.60 FL	*420.70 FL
5	1		*REAR BUMPER REINFORCEMENT ABSROBER	No such part	384.63 FL	*- FL
6	10		*REAR BUMPER CLIP	Necessary	68.00 FL	*30.00 FL
7	1		*BOOT LID	Dented	1,255.00 FL	*681.20 FL
8	1		*BOOT LID HINGE	Not Damaged	158.00 FL	*- FL
9	1		*BOOT LID HINGE	Not Damaged	158.00 FL	*- FL
10	1		*BOOT LID INSULATOR	Torn	602.30 FL	*251.80 FL
11	1		*BOOT LID KEY LOCK ASSY	Not Damaged	567.80 FL	*- FL
12	10		*BOOT LID INSULATOR CLIP	Necessary	68.00 FL	*30.00 FL
13	1		*BOOT LID CABLE	Not Damaged	185.00 FL	*- FL
14	1		*BOOT LID LOCK	Jammed	385.00 FL	*102.30 FL
15	1		*BOOT LID CATCH	Not Damaged	193.00 FL	*- FL
16	1		*BOOT LID WEATHERSTRIP	Torn	255.00 FL	*169.30 FL
17	1		*BOOT LID LOGO	Necessary	75.00 FL	*38.50 FL
18	1		*BOOT LID CAMRY EMBLEM	Necessary	58.00 FL	*58.00 FL
19	1		*BOOT LID NUMBER PLATE GARNISH	Broken	255.50 FL	*136.00 FL
20	1		*REAR NUMBER PLATE LAMP ASSY	Not Damaged	135.00 FL	*- FL
21	1		*BOOT LID LAMP LH	Broken	480.00 FL	*358.90 FL
22	1		*BOOT LID LAMP RH	Broken	480.00 FL	*358.90 FL
23	1		*REAR END PANEL	Dented	711.75 FL	*380.40 FL
24	1		*REAR END PANEL GARNISH	Broken	325.80 FL	*158.60 FL
25	1		*REAR FENDER INNER TRIM RH	Torn	620.50 FL	*285.00 FL
26	1		*REAR FENDER INNER TRIM LH	Torn	620.50 FL	*285.00 FL
27	20		*REAR FENDER INNER TRIM CLIPS	Necessary	100.00 FL	*60.00 FL
28	1		*REAR FENDER INNER SHIELD LH	Not Damaged	180.00 FL	*- FL
29	1		*REAR FENDER INNER SHIELD RH	Not Damaged	180.00 FL	*- FL
30	10		*REAR FENDER INNER SHIELD CLIPS	Not Necessary	100.00 FL	*- FL
31	1		*TAILLAMP RH	Broken	685.00 FL	*420.00 FL
32	1		*TAILLAMP LH	Broken	685.00 FL	*420.00 FL
33	1		*TAILLAMP PANEL RH	Deformed	368.00 FL	*258.00 FL
34	1		*TAILLAMP PANEL LH	Dented	368.00 FL	*258.00 FL
35	1		*SPARE TYRE PANEL	Dented	1,090.30 FL	*925.10 FL
36	1		*SPARE TYRE BOARD	Broken	520.30 FL	*285.40 FL
37	1		*FRONT BUMPER	Broken	785.00 FL	*536.00 FL
38	2		*FRONT BUMPER SIDE RETAINER	Necessary	151.60 FL	*126.80 FL
39	1		*FRONT BUMPER REINFORCEMENT	Not Damaged	580.00 FL	*- FL
40	1		*FRONT BUMPER BRACE PANEL	No such part	125.00 FL	*- FL
41	1		*FRONT BUMPER PLATE BASE	No such part	85.00 FL	*- FL
42	1		*FRONT TOW HOOK COVER (7280)	Not Damaged	30.00 FL	*- FL
43	1		*RADIATOR GRILLE ASSY	Broken	650.00 FL	*466.80 FL
44	1		*LOGO EMBLEM	Necessary	80.00 FL	*45.00 FL
45	1		*FRONT BUMPER SPONGE	Broken	135.20 FL	*135.20 FL
46	1		*HEADLAMP RH	Broken	1,580.00 FL	*713.80 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*HEADLAMP LH	Broken	1,580.00 FL	*713.80 FL
48	1		*FRONT SUPPORT PANEL	Not Damaged	1,150.00 FL	*- FL
49	1		*RADIATOR	Not Damaged	1,125.80 FL	*- FL
50	1		*CONDENSER	Not Damaged	985.90 FL	*- FL
51	1		*REVERSE CAMERA	Not Damaged	350.00 FS	*- FS
52	1		*REVERSE SENSOR	Short Circuit	250.00 FS	*200.00 FS
53	1		*REAR NUMBER PLATE	Broken	45.00 FS	*30.00 FS
54	1		*FRONT NUMBER PLATE	Broken	45.00 FS	*30.00 FS
55	1		*RADIATOR GRILLE ASSY	Repeated	650.00 FL	*- FL
56	1		*FRONT FENDER RH	Bent	820.00 FL	*581.90 FL
57	1		*FRONT FENDER LH	Bent	820.00 FL	*581.90 FL
58	1		*BONNET	Bent	1,430.00 FL	*890.00 FL
59	1		*SPARE WHEEL PANEL	Repeated	1,258.60 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	29,009.28	12,157.50
- List Item Discount on L Items 25.00/25.00% (\$)	7,079.82	2,974.38
Total Parts (\$)	21,929.46	9,183.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK LIGHT SYSTEM AND WIRING	New	50.00	0.00
2	TO RECONNECT BROKEN WIRES	New	150.00	0.00
3	ANTI-RUST	New	200.00	0.00
4	TO APPLY BODY SEALANT ON BODY JOINTS	New	200.00	60.00
5	TO REMOVE/REFIT INNER TRIMS AND GARNISHES	New	200.00	80.00
6	INSTALL REVERSE SENSOR	New	80.00	60.00
7	TO CLEAR SRS ABD FAULT CODES W DIAGNOSTIC	New	280.00	0.00
8	TO VACCUM,REOIL AND REGAS AIR CON	New	120.00	0.00
9	TO CONDUCT CHASSIS ALIGNMENT	New	300.00	0.00
10	LABOUR/PANEL BEATING	New	2,500.00	1,200.00
11	SPRAY PAINTING	New	2,000.00	1,400.00
12	TO REMOVE AND REPLACE SPARE PART AND PANEL BEATING	New	1,000.00	0.00
13	TO SPRAY PAINTING AND ETC	New	1,000.00	0.00
Gross Labour Cost (\$\$)			8,080.00	2,800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >