

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22001306/BQF3N2**Date:** 26/04/2022**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMHCSNA00009012101

**Claimant Vehicle
No :** SMS2607H**Insured
Vehicle No :** SLS2990L

Date of Loss: 08/02/2022

Nature of Claim: TP

Claim
No: SNM22D200982/C02/TOHHS**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SMS2607H**

Make & Model: MAZDA 6, 2.0 (A)

Reg. Date: 19/02/2020 (Man. Year: 2019)

Colour: Grey

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

Engine No: PE21302622

Chassis No: JM6GL1072K0322574

Odometer: 34531 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55R17

Front Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

The above values represent the remaining tyre tread depth

Rear Tyre Size: 225/55R17

Rear Left Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	10,171.84	4,027.52	6,144.32	60.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,840.00	2,250.00	1,590.00	41.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	14,011.84	6,277.52	7,734.32	55.20
Approved Total (Overridden) (\$\$)		5,000.00		
(\$\$)	14,011.84	5,000.00	9,011.84	64.32
+ GST 7.00/7.00% (\$\$)	980.83	350.00	630.83	64.32
Nett Amount (\$\$)	14,992.67	5,350.00	9,642.67	64.32

INSPECTION

Date of Assignment: 12/02/2022

Date Inspected: 15/02/2022 Inspected At:

Bifrost Auto Pte Ltd (Kaki Bukit)
8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit
Singapore 415875

Estimated Period of Repair: 6.0 days

Adjuster: Lim Teow Guan**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Apr 2022)
Parts:	143	MAZDA 6 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMS2607H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Broken	1,099.00 FL	*1,047.00 FL
2	1		*REAR BUMPER LH SIDE RETAINER	Necessary	41.00 FL	*41.00 FL
3	1		*LH TAILLAMP ASSY	Not Damaged	1,592.00 FL	*- FL
4	1		*REAR LH SPORT RIM	Cut	1,341.00 FL	*800.00 FL
5	1		*REAR LH LOWER ARM	Bent	247.70 FL	*247.70 FL
6	1		*REAR LH SHOCK ABSORBER	Bent	322.20 FL	*322.20 FL
7	1		*REAR LH KNUCKLE ARM	Not Damaged	407.10 FL	*- FL
8	1		*REAR LH WHEEL BEARING	Jammed	480.40 FL	*215.00 FL
9	1		*REAR WINDSCREEN GLASS RUBBER MOULDING	Necessary	117.70 FL	*88.00 FL
10	1		*REAR LH FENDER	Dented	1,120.50 FL	*984.10 FL
11	1		*REAR LH FENDER QUARTER GARNISH	No such part	234.80 FL	*- FL
12	1		*REAR LH DOOR	Dented	958.60 FL	*958.60 FL
13	1		*REAR LH DOOR OUTER HANDLE	Not Damaged	311.70 FL	*- FL
14	1		*REAR LH DOOR FRAME TAPE STICKER	Not Necessary	32.20 FL	*- FL
15	1		*REAR LH DOOR WEATHERSTRIP	Torn	143.30 FL	*143.30 FL
16	1		*REAR LH DOOR LOCK	Not Damaged	222.90 FL	*- FL
17	1		*REAR LH DOOR GLASS REGULATOR GEAR	Not Damaged	149.90 FL	*- FL
18	1		*REAR LH DOOR INNER TRIM BOARD	Not Damaged	2,025.90 FL	*- FL
19	1		*FRONT LH DOOR	Repair	972.20 FL	*- FL
20	1		*FRONT LH DOOR FRAME BLACK TAPE	Not Necessary	32.20 FL	*- FL
21	1		*SET REAR BUMPER CLIPS	Necessary	70.00 FS	*30.00 FS
22	1		*SET REAR LH DOOR INNER TRIM BOARD CLIPS	Necessary	60.00 FS	*30.00 FS
23	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	70.00 FS	*30.00 FS
24	1		*REAR WINDSCREEN GLASS SPONGE SEAL	Necessary	50.00 FS	*30.00 FS
25	1		*REAR LH TYRE	Not Damaged	380.00 FS	*- FS
26	1		*SET REAR LH FENDER INNER TRIM BOARD CLIPS	Necessary	60.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,542.30	4,996.90
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,370.46	969.38
Total Parts (\$\$)	10,171.84	4,027.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE,CHECK,REPLACE AND REINSTALL DAMAGED BODYPARTS.TO PANEL BEATING,CUT/WELD AND REALIGN ALL AFFECTED PANELS AND AREAS	New	1,200.00	800.00
2	SPRAY PAINTING ON AFFECTED AREAS AND PANELS	New	1,000.00	800.00
3	CHECK WIRING AND LIGHTING SYSTEM	New	60.00	0.00
4	APPLY RUST COATING CHEMICAL ON AFFECTED AREAS AND PANELS	New	100.00	0.00
5	REMOVE AND REINSTALL REAR WINDSCREEN GLASS TO ASSIST REPAIR	New	220.00	120.00
6	REMOVE AND REINSTALL REAR BUMPER REVERSE SENSOR TO ASSIST REPAIR	New	100.00	60.00
7	REMOVE AND REINSTALL FUEL TANK,PIPES,HOSES AND SENSORS TO ASSIST REPAIR	New	100.00	0.00
8	REMOVE AND REINSTALL REAR INNER TRIMS,GARNISH,BOARDS,ROOF LINING,CARPET AND SEAT BELTS TO ASSIST REPAIR	New	380.00	0.00
9	REMOVE AND REPLACE REAR LH DOOR INNER MECHANISM TO NEW DOOR	New	100.00	80.00
10	REMOVE AND REPLACE FRONT LH DOOR INNER MECHANISM TO NEW DOOR	New	100.00	80.00
11	TEST DRIVE AND ADJUST WHEEL ALIGNMENT SYSTEM	New	100.00	60.00
12	REMOVE AND REPLACE REAR UNDERCARRIAGE PARTS TO ASSIST REPAIR	New	380.00	250.00
Gross Labour Cost (\$\$)			3,840.00	2,250.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >