

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22001307/APA3Q2**Date:** 14/12/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900149627-01
Claimant Vehicle No :	SMX1458B	Insured Vehicle No :	SKW979A
Date of Loss:	10/02/2022	Nature of Claim:	TP
		Claim No:	5256799332SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMX1458B		
Make & Model:	TOYOTA CAMRY, 2.5 HYBRID ASCENT (A)	Engine No:	A25A0A12857
Reg. Date:	29/12/2020 (Man. Year: 2020)	Chassis No:	JTNB23HK403071321
Colour:	Silver	Odometer:	49259 km
Engine Capacity:	2487 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,866.85	9,424.97	9,441.88	50.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,350.00	2,680.00	1,670.00	38.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,216.85	12,104.97	11,111.88	47.86
Approved Total (Overridden) (S\$)		9,600.00		
(S\$)	23,216.85	9,600.00	13,616.85	58.65
+ GST 7.00/7.00% (S\$)	1,625.18	672.00	953.18	58.65
Nett Amount (S\$)	24,842.03	10,272.00	14,570.03	58.65
+ Car Rental (10.0 x S\$120.00/day) (S\$)		1,200.00		
+ Doc/Search Fee (S\$)		7.45		
+ Other Costs (S\$)		100.00		
Nett Liability (S\$)		11,579.45		
Global Sum Settlement (S\$)		11,530.00		

INSPECTION

Date of Assignment:	11/02/2022	
Date Inspected:	11/02/2022 Inspected At:	Ryder Auto Pte Ltd (HQ) 2 Kaki Bukit Ave 2, #02-19 AutoHub @ Kaki Bukit Singapore 417921
Estimated Period of Repair:	9.0 days	

Adjuster: ADRIAN LING

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	1,275.20 FL	*656.00 FL
2	10		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
3	2		*REAR BUMPER SCREW CLIPS	Not Necessary	20.00 FS	*- FS
4	1		*REAR BUMPER ENFORCEMENT	Dented	550.60 FL	*459.00 FL
5	1		*REAR BUMPER O/S & N/S REFLECTOR	O/S Cracked	242.20 FL	*121.10 FL
6	1		*REAR BUMPER O/S & N/S RETAINER (LOWER)	O/S Damaged	154.00 FL	*77.00 FL
7	1		*REAR BUMPER O/S & N/S RETAINER (UPPER)	O/S Damaged	110.00 FL	*55.00 FL
8	1		*REAR BUMPER CHROME GARNISH	Cracked	300.00 FS	*250.00 FS
9	1		*REAR BUMPER LOWER DIFFUSER	Deformed	1,080.80 FL	*382.00 FL
10	2		*REAR REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
11	2		*REAR REVERSE SENSOR WIRE HARNESS	Not Necessary	180.00 FS	*- FS
12	1		*REAR REVERSE CAMERA	Damaged	680.00 FS	*380.00 FS
13	1		*REAR END PANEL (OUTER)	Distorted	1,043.20 FL	*681.00 FL
14	1		*REAR END PANEL INNER TRIM	Deformed	756.20 FL	*210.00 FL
15	4		*REAR END PANEL INNER TRIM CLIPS	Necessary	20.00 FS	*20.00 FS
16	2		*REAR O/S & N/S TAIL LAMP	N/S Cracked / O/S Smashed	1,912.20 FL	*1,210.00 FL
17	1		*REAR O/S TAIL LAMP PANEL	Dented	265.70 FL	*265.70 FL
18	1		*REAR BOOT COVER	Distorted	1,592.10 FL	*987.00 FL
19	1		*REAR BOOT COVER WEATHERSTRIP	Cut	225.10 FL	*225.10 FL
20	1		*REAR BOOT COVER TOYOTA EMBLEM	Necessary	81.50 FL	*81.50 FL
21	1		*REAR BOOT COVER CAMRY EMBLEM	Necessary	78.50 FL	*78.50 FL
22	1		*REAR BOOT COVER HYBRID EMBLEM	Necessary	81.70 FL	*81.70 FL
23	1		*REAR BOOT COVER INNER TRIM	Torn	250.00 FL	*250.00 FL
24	1		*REAR BOOT COVER INNER TRIM CLIPS (11 PCS)	Necessary	55.00 FS	*30.00 FS
25	2		*REAR BOOT COVER O/S & N/S STOPPER	Not Necessary	90.00 FL	*- FL
26	2		*REAR BOOT COVER O/S & N/S HINGES	Bent	280.40 FL	*280.40 FL
27	1		*REAR BOOT COVER MOULDING CHROME	Cracked	755.60 FL	*571.00 FL
28	4		*REAR BOOT COVER MOULDING CHROME CLIPS	Necessary	20.00 FS	*20.00 FS
29	1		*REAR BOOT COVER LOCK (UPPER)	Damaged	460.60 FL	*359.00 FL
30	1		*REAR BOOT COVER LOCK (LOWER)	Not Necessary	120.00 FL	*- FL
31	1		*REAR BOOT COVER SWITCH	Damaged	310.70 FL	*310.70 FL
32	1		*REAR BOOT COVER SWITCH GARNISH (BLACK)	Not Necessary	180.70 FL	*- FL
33	1		*REAR BOOT COVER O/S GARNISH (BLACK)	Not Necessary	86.20 FL	*- FL
34	2		*REAR BOOT COVER O/S & N/S REFLECTOR	N/S Cracked / O/S Smashed	1,872.20 FL	*886.00 FL
35	1		*REAR SPARE WHEEL PANEL	Repair	1,591.70 FL	*- FL
36	1		*REAR SPARE WHEEL PANEL INSULATOR	Not Necessary	300.00 FS	*- FS
37	1		*REAR SPARE WHEEL BOARD (MIDDLE)	Deformed	955.60 FL	*376.00 FL
38	1		*REAR TOOL SPONGE	Deformed	625.20 FL	*353.00 FL
39	1		*REAR O/S FENDER	Buckled	1,284.60 FL	*1,284.60 FL
40	1		*REAR O/S FENDER WHEEL GUARD	Torn	986.70 FL	*233.00 FL
41	6		*REAR O/S & N/S FENDER WHEEL GUARD CLIPS	Necessary	30.00 FS	*30.00 FS
42	2		*REAR O/S FENDER INNER TRIM	Torn	1,274.20 FL	*459.00 FL
43	12		*REAR O/S FENDER INNER TRIM CLIPS	Necessary	30.00 FS	*30.00 FS
44	1		*REAR EXHAUST	Not Necessary	1,020.20 FL	*- FL
45	1		*REAR UNDERCOVER	Not Necessary	310.20 FL	*- FL
46	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*60.00 FS
47	1		*REAR WINDSCREEN MOULDING	Necessary	320.00 FS	*175.00 FS
48	1		*REAR REGN NO PLATE	Not Necessary	45.00 FS	*- FS
49	1		*REAR REGN NO PLATE BRACKET	Not Necessary	29.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 24,342.80 12,158.30
- List Item Discount on L Items 25.00/25.00% (\$\$) 5,475.95 2,733.33

Total Parts (\$\$) 18,866.85 9,424.97

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE DAMAGED PARTS ,STRAIGHTEN & WELDING	New	2,200.00	1,200.00
2	TO SPRAY PAINTING	New	1,500.00	1,200.00
3	TO REMOVE & REFIT REAR WINDSCREEN	New	150.00	120.00
4	TO REMOVE & REPLACE REAR REVERSE SENSOR CAMERA	New	120.00	50.00
5	TO RE-SET ELECTRICAL SYSTEM	New	180.00	0.00
6	TO CHECK WIRING	New	100.00	30.00
7	TO RE-SEAL ANTI -RUST	New	100.00	80.00
Gross Labour Cost (S\$)			4,350.00	2,680.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >