

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC4/LPC22001312/4003

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: Y93452Dat Workshop m/s LP

of _____

Insured: YN 6187

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 885k

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 5 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: L1A 821266Veh No: Y93452D Yr Regn: 20/7/16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or with craneMake: Isuzu FVR34 c.c. 7790Colour: orange A/C: Insured / Std / NI / NASp. Reading: 136640 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JALFVR34767000836

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 275/70R22.5

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or BycrossFront 6 mm Rear 6/6 mmR/Bal. 6 mm L/Bal. 6/6 mmL/Bal. 6 mm L/Bal. 6/6 mmD.O.A. 9/2/22 D.O.I. 11/2/22

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Ref.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction dep 18k.

1/3/22 None h.A
L/S 6100 informed Alan

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$) S + RS SI☐ : Interview (\$) Photos☐ : Tech. Invs (\$) Others☐ : Weekend (\$)

Report Format : _____

Lump Sum / I.B.I: (\$)

Survey Fee:

Transportation:

TOTAL

Aster

not Authorised
see
11/2/22

FASTECH AUTO PTE LTD
1 Kaki Bukit Ave 6 #01-48 Autobay
Singapore 417883
Tel No: 67452063/ 6746758 Fax No: 67458520
Tax Reg No : 200006262D

2/s \$ 6100
5 days

VEHICLE No: YP 3452D

1PC	FRONT BUMPER	2/surf R 1355	\$2,860.00	
1PC	FRONT BUMPER BRACKET O/S		\$295.00	X
1PC	HEADLAMP O/S	one 480	\$1,855.21	
1PC	FRONT CORNER PANEL O/S	one 920	\$1,845.35	
1PC	FRONT CORNER PANEL LOWER PANEL O/S	surf 100	\$305.00	
1PC	FRONT CORNER PANEL BACK INNER RUBBER O/S	Torn 115	\$288.00	
1PC	FRONT DOOR O/S	2/surf 1905	\$5,430.25	
1PC	FRONT DOOR INNER RUBBER O/S	11	\$388.00	X
1PC	FRONT DOOR INNER LOCK O/S	11	\$450.00	X
2PCS	FRONT DOOR HINGES @\$150.00	11	\$300.00	X
1PC	FRONT DOOR OUTER PILLAR O/S	2 980	\$1,299.00	
1PC	FRONT STEP PANEL GARNISH O/S	one 490	\$886.00	
1PC	FRONT DOOR 'NIPPON PAINT' STICKER O/S	new 15%	\$900.00	450 s/w
			\$17,101.81	

TO CHECK WIRING	\$50.00	20
TO DISMANTLE & REFIX FRONT WINDSCREEN	11 \$200.00	X
TO DISMANTLE & REFIX FRONT DASHBOARD	11 \$300.00	X
TO DISMANTLE & REFIX FRONT DOOR MECHANISM	\$120.00	60
TO SPRAY RUST PROOFING	\$80.00	60
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$1,200.00	900
TO PUTTY & SPRAY PAINTING	\$1,200.00	750
TOTAL	\$20,251.81	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P-6345
15%
P-4393-25
SN-450
2-1790
7633-25
202
6106-60