

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22001313/AQF3M4
Date: 04/07/2022

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00142452100
Claimant Vehicle No :	SKV8526B	Insured Vehicle No :	SMU4470K
Date of Loss:	10/02/2022	Nature of Claim:	TP
		Claim No:	SNM22D201017/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKV8526B	Engine No:	3ZRB592522
Make & Model:	TOYOTA HARRIER, 2.0 ELEGANCE CVT (A)	Chassis No:	ZSU600049874
Reg. Date:	05/10/2015 (Man. Year: 2015)	Odometer:	141909 km
Colour:	Black		
Engine Capacity:	1986 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/65 R17	Rear Tyre Size:	225/65 R17
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	40,012.63	8,339.90	31,672.73	79.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,720.00	2,570.00	6,150.00	70.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	48,732.63	10,909.90	37,822.73	77.61
Approved Total (Overridden) (S\$)		8,700.00		
Nett Amount (S\$)	48,732.63	8,700.00	40,032.63	82.15

INSPECTION

Date of Assignment:	15/02/2022	
Date Inspected:	11/02/2022 Inspected At:	JL PERFECT AUTOWORK PTE LTD 8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875
Estimated Period of Repair:	6.0 days	

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Jul 2022)
Parts:	M1-SUV	TOYOTA HARRIER 2.0 ELEGANCE CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKV8526B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT FENDER LH	Dented	1,012.70 FL	*1,012.70 FL
2	1	*FRONT FENDER COWLING LH	Not Necessary	409.60 FL	*- FL
3	1	*FRONT CROSSMEMBER	Not Necessary	1,876.40 FL	*- FL
4	1	*FRONT STEERING RACK AND PINION	Not Necessary	1,946.70 FL	*- FL
5	1	*FRONT DRIVESHAFT LH	Not Necessary	1,242.30 FL	*- FL
6	1	*FRONT KNUCKLE ARM LH	Not Necessary	587.70 FL	*- FL
7	1	*FRONT WHEEL HUP C/W BEARING LH	Not Necessary	555.30 FL	*- FL
8	1	*FRONT SHOCK ABSORBER LH	Not Necessary	475.70 FL	*- FL
9	1	*FRONT LOWER ARM LH	Not Necessary	679.20 FL	*- FL
10	1	*FRONT LINKAGE LH	Not Necessary	146.70 FL	*- FL
11	1	*FRONT DOOR VIEW MIRROR LH	Cut	2,955.20 FL	*1,303.00 FL
12	1	*FRONT DOOR LH	Distorted	1,550.60 FL	*1,550.60 FL
13	1	*FRONT DOOR OUTER HANDLE LH	Not Necessary	127.20 FL	*- FL
14	1	*FRONT DOOR KEY LOCK LH	Not Necessary	128.70 FL	*- FL
15	1	*FRONT DOOR GLASS LH	Not Necessary	931.10 FL	*- FL
16	1	*FRONT DOOR GLASS SIDE GARNISH LH	Not Necessary	175.80 FL	*- FL
17	1	*FRONT DOOR GLASS CHANNEL LH	Not Necessary	148.70 FL	*- FL
18	1	*FRONT DOOR LOWER CHROME LH	Cut	184.20 FL	*184.20 FL
19	2	*FRONT DOOR STOPPER LH	Not Necessary	31.20 FL	*- FL
20	2	*FRONT DOOR HINGE LH	Not Necessary	170.20 FL	*- FL
21	1	*FRONT DOOR CHECKER LH	Not Necessary	231.70 FL	*- FL
22	1	*FRONT DOOR FRAME STEP GARNISH RHH	Not Necessary	118.50 FL	*- FL
23	1	*FRONT DOOR FRAME WEATHER STRIP LH	Not Necessary	346.80 FL	*- FL
24	1	*FRONT DOOR SPEAKER LH	Not Necessary	390.80 FL	*- FL
25	1	*FRONT DOOR WIRE HARNESS LH	Not Necessary	475.80 FL	*- FL
26	1	*FRONT DOOR INNER LOCK LH	Damaged	603.20 FL	*486.00 FL
27	1	*FRONT DOOR LOCK CATCHER LH	Not Necessary	36.10 FL	*- FL
28	1	*FRONT DOOR WEATHER STRIP LH	Not Necessary	281.90 FL	*- FL
29	1	*FRONT DOOR OUTER STRIP LH	Not Necessary	205.91 FL	*- FL
30	1	*FRONT DOOR LOWER INNER RUBBER LH	Not Necessary	145.80 FL	*- FL
31	1	*FRONT DOOR POWER WINDOW MOTOR C/W REGULATOR LH	Damaged	1,156.10 FL	*495.00 FL
32	1	*FRONT DOOR INNER TRIM BOARD LH	Cracked	1,930.60 FL	*965.00 FL
33	1	*CENTER PILLAR (OUTER) LH	Not Necessary	464.20 FL	*- FL
34	1	*CENTER PILLAR (INNER) LH	Not Necessary	375.10 FL	*- FL
35	1	*CENTER PILLAR INNER TRIM LH	Not Necessary	267.60 FL	*- FL
36	1	*ROCKER PANEL LH (OUTER)	Not Necessary	464.20 FL	*- FL
37	1	*SIDE SKIRT LH	Not Necessary	548.50 FL	*- FL
38	1	*REAR DOOR LH	Dented	1,550.60 FL	*1,550.60 FL
39	1	*REAR DOOR OUTER HANDLE LH	Not Necessary	117.70 FL	*- FL
40	1	*REAR DOOR OUTER LOWER MOULDING LH	Cut	158.60 FL	*158.60 FL
41	1	*REAR DOOR QUARTER GLASS LH	Not Necessary	125.70 FL	*- FL
42	1	*REAR DOOR QUARTER GLASS SUPPORT CHANNEL LH	Not Necessary	92.50 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*REAR DOOR GLASS LH	Not Necessary	643.50 FL	*- FL
44	1		*REAR DOOR GLASS CHANNEL LH	Not Necessary	129.60 FL	*- FL
45	1		*REAR DOOR OUTER STRIP MOULDING LH	Not Necessary	158.70 FL	*- FL
46	1		*REAR DOOR INNER LOCK LH	Not Necessary	600.20 FL	*- FL
47	1		*REAR DOOR INNER TRIM LH	Not Necessary	1,930.10 FL	*- FL
48	2		*REAR DOOR HINGE LH	Not Necessary	164.20 FL	*- FL
49	1		*REAR DOOR CHECKER LH	Not Necessary	231.20 FL	*- FL
50	1		*REAR DOOR LOCK CATCHER LH	Not Necessary	36.10 FL	*- FL
51	1		*REAR DOOR WINDOW GARNISH LH	Not Necessary	175.20 FL	*- FL
52	1		*REAR DOOR POWER WINDOW MOTOR LH	Not Necessary	974.20 FL	*- FL
53	1		*REAR DOOR REGULATOR GEAR LH	Not Necessary	275.80 FL	*- FL
54	1		*REAR DOOR STEP GARNISH LH	Not Necessary	115.10 FL	*- FL
55	1		*REAR DOOR FRAME STEP GARNISH LH	Not Necessary	175.20 FL	*- FL
56	1		*REAR DOOR WEATHER STRIP LH	Not Necessary	275.60 FL	*- FL
57	1		*REAR DOOR FRAME WEATHERSTRIP LH	Not Necessary	346.50 FL	*- FL
58	1		*REAR DOOR WIRE HARNESS LH	Not Necessary	475.10 FL	*- FL
59	2		*REAR DOOR LOWER INNER RUBBER LH	Not Necessary	291.60 FL	*- FL
60	1		*REAR SEAT SIDE GARNISH LH	Not Necessary	245.90 FL	*- FL
61	1		*REAR SEAT REST BACK COVER BOARD LH	Not Necessary	185.70 FL	*- FL
62	1		*REAR FENDER LH	Repair	1,531.80 FL	*- FL
63	1		*REAR FENDER QUARTER GLASS LH	Not Necessary	282.60 FL	*- FL
64	1		*REAR FENDER INNER COWLING LH	Not Necessary	247.30 FL	*- FL
65	1		*REAR ABS SENSOR LH	Not Necessary	417.60 FL	*- FL
66	1		*REAR CROSSMEMBER	Not Necessary	3,120.60 FL	*- FL
67	1		*REAR SHOCK ABSORBER LH	Not Necessary	152.10 FL	*- FL
68	1		*REAR WHEEL HUP WITH BEARING LH	Not Necessary	1,008.20 FL	*- FL
69	1		*REAR ANTI ROLL BAR LINKAGE LH	Not Necessary	179.30 FL	*- FL
70	1		*REAR LOWER ARM LH	Not Necessary	524.60 FL	*- FL
71	1		*REAR KNUCKLE ARM LH	Not Necessary	465.20 FL	*- FL
72	1		*REAR ADJUSTABLE ARM LH	Not Necessary	291.60 FL	*- FL
73	1		*REAR CONTROL ARM LH	Not Necessary	271.20 FL	*- FL
74	1		*REAR BUMPER	Torn	904.80 FL	*904.80 FL
75	1		*REAR BUMPER LOWER	Not Necessary	466.10 FL	*- FL
76	1		*REAR BUMPER SIDE RETAINER	N/s Necessary	165.40 FL	*82.70 FL
77	1		*FRONT WHEEL RIM LH	Cut	1,618.20 FS	*880.00 FS
78	1		*REAR WHEEL RIM LH	Cut	1,953.67 FS	*880.00 FS
79	1		*FRONT DOOR SEALANT RH	Not Necessary	150.00 FS	*- FS
80	1		*SET FRONT DOOR TRIM BOARD CLIP	Necessary	80.00 FS	*30.00 FS
81	1		*FRONT DOOR GLASS SOLAR FILM RH	Not Necessary	550.00 FS	*- FS
82	1		*CENTER PILLAR (OUTER) SEALANT	Not Necessary	150.00 FS	*- FS
83	1		*CENTER PILLAR (INNER) SEALANT	Not Necessary	150.00 FS	*- FS
84	1		*SET CENTER PILLAR INNER TRIM CLIP RH	Not Necessary	80.00 FS	*- FS
85	1		*SET SIDE SKIRT CLIP RH	Not Necessary	120.00 FS	*- FS
86	1		*ROCKER PANEL RH (OUTER) SEALANT	Not Necessary	150.00 FS	*- FS
87	1		*REAR DOOR SEALANT RH	Not Necessary	150.00 FS	*- FS
88	1		*SET REAR DOOR INNER TRIM CLIP RH	Not Necessary	80.00 FS	*- FS
89	1		*SET REAR DOOR WINDOW SIDE GARNISH CLIP	Not Necessary	60.00 FS	*- FS
90	1		*REAR DOOR GLASS SOLAR FILM RH	Not Necessary	550.00 FS	*- FS
91	1		*REAR DOOR QUARTER GLASS SOLAR FIM RH	Not Necessary	150.00 FS	*- FS
92	1		*REAR DOOR QUARTER GLASS STICKER	Not Necessary	120.00 FS	*- FS
93	1		*SET REAR SEAT SIDE GARNISH CLIP RH	Not Necessary	80.00 FS	*- FS
94	1		*REAR FENDER SEALANT RH	Not Necessary	150.00 FS	*- FS
95	1		*SET REAR FENDER INNER COWLING CLIP	Not Necessary	60.00 FS	*- FS
96	1		*SET REAR FENDER INNER TRIM CLIP	Not Necessary	80.00 FS	*- FS
97	1		*REAR FENDER GLASS SEALANT RH	Not Necessary	80.00 FS	*- FS
98	1		*REAR FENDER GLASS INNER SHIELD RH	Not Necessary	60.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
99	1		*REAR FENDER GLASS SOLAR FILM RH	Not Necessary	150.00 FS	*- FS
100	1		*SET TAIL LAMP CLIP	Not Necessary	60.00 FS	*- FS
101	1		*SET REAR BUMPER CLIP	Necessary	120.00 FS	*30.00 FS
102	1		*REAR WHEEL TYRE RH	Not Necessary	650.00 FS	*- FS
103	1		*SET WHEEL CAP	Not Necessary	120.00 FS	*- FS
104	1		*SET SIDE ANGLE MIRROR	Not Necessary	80.00 FS	*- FS
105	1		*SET DOOR STOPPER	Not Necessary	20.00 FS	*- FS
106	1		*BRAKE OIL	Not Necessary	30.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	50,732.88	10,513.20
- List Item Discount on L Items 25.00/25.00% (S\$)	10,720.25	2,173.30
Total Parts (S\$)	40,012.63	8,339.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	New	2,600.00	1,100.00
2	TO SPRAY PAINT AFFECTED AREA	New	2,200.00	1,100.00
3	REMOVE & REFIX CUSHION SEAT/UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	New	350.00	0.00
4	TUFF COAT	New	250.00	50.00
5	WIRING CHECK	New	250.00	30.00
6	REMOVE AND REFIX FRONT DASHBOARD AND SAFETY MODULE UNIT	New	850.00	0.00
7	REMOVE AND REFIX SAFETY BELT	New	250.00	0.00
8	FOUR WHEEL ALIGNMENT	New	120.00	80.00
9	REMOVE & REFIX AUDIO SPEAKER	New	120.00	0.00
10	TRANSFER FRONT DOOR MECHANISM RH	New	80.00	40.00
11	REMOVE & REINSTALL FRONT WINDOW GLASS RH	New	80.00	40.00
12	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
13	TRANSFER REAR DOOR MECHANISM	New	80.00	40.00
14	REMOVE & REINSTALL REAR WINDOW GLASS RH	New	60.00	40.00
15	REMOVE AND REFIX REAR UNDERCARRIAGE	New	650.00	0.00
16	RESET ABS LIGHT	New	350.00	0.00
17	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC	New	350.00	0.00
Gross Labour Cost (S\$)			8,720.00	2,570.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >