



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBR 122M

| Qty | Description of Parts               | Condition           | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|------------------------------------|---------------------|---------------------------|-------------------|
|     | <b><u>REPLACEMENT OF PARTS</u></b> |                     |                           |                   |
| 1   | HANDLE BAR                         | BENT                | 155.00                    | 155.00            |
| 1   | VISOR                              | CRACKED             | 220.00                    | 72.00             |
| 1   | FRONT V PANEL                      | MTG CRACKED         | 250.00                    | 250.00            |
| 1   | BRAKE LEVER                        | DENTED              | 196.00                    | 196.00            |
| 1   | INNER GARNISH PANEL                | CRACKED             | 150.00                    | 150.00            |
| 1   | HEAD LAMP ASSY                     | CRACKED             | 550.00                    | 485.00            |
| 1   | SIGNAL LIGHT LH                    | SCRATCHED           | 98.00                     | 98.00             |
| 1   | LH PILOT LIGHT                     | SERVICEABLE         | 150.00                    | -                 |
| 1   | FRONT LH SIDE PANEL                | CRACKED             | 180.00                    | 180.00            |
| 1   | LH SIDE PANEL INNER GARNISH        | SERVICEABLE         | 190.00                    | -                 |
| 1   | FRONT RH SIDE PANEL                | CRACKED             | 160.00                    | 160.00            |
| 1   | RH INNER PANEL                     | SERVICEABLE         | 180.00                    | -                 |
| 1   | SET FORK ASSY                      | BENT                | 480.00                    | 480.00            |
| 1   | FORK UNDER BRACKET                 | BENT                | 250.00                    | 180.00            |
| 2   | FOOTREST PANEL                     | O/S BENT            | 180.00                    | 90.00             |
| 1   | CVT COVER                          | DENTED / CUT        | 180.00                    | 180.00            |
| 2   | FRONT COVER PANEL                  | CRACKED             | 210.00                    | 210.00            |
| 1   | TRANSMISSION AIR BOX COVER         | SERVICEABLE         | 250.00                    | -                 |
| 1   | FRONT MUDGUARD INNER               | CRACKED             | 180.00                    | 180.00            |
| 1   | FRONT MUDGUARD                     | CRACKED             | 240.00                    | 240.00            |
| 2   | BODY-L PANEL CENTRE                | CRACKED (1 PC ONLY) | 280.00                    | 140.00            |
| 1   | EXHAUST GUARD                      | DENTED / CUT        | 158.00                    | 158.00            |
| 1   | HEAD LAMP LOWER GUARD              | CRACKED             | 190.00                    | 190.00            |
| 1   | LEGSHIELD LH                       | CRACKED             | 120.00                    | 120.00            |
| 2   | FRONT BODY COWLING                 | CRACKED (1 PC ONLY) | 250.00                    | 125.00            |
| 1   | MIRROR                             | DENTED              | 120.00                    | 120.00            |
| 1   | RADIATOR COVER                     | DENTED / CUT        | 280.00                    | 220.00            |
|     | LESS 10% DISCOUNT                  |                     | -584.70                   | -437.90           |
|     |                                    |                     | 5,262.30                  | 3,941.10          |

Report Ref No. CS/SMO22001314/Ktf3n2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty                | Description of Parts                          | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|--------------------|---|-----------|---------------------------|-------------------|
| 1                  | <b><u>SPECIAL NETT ITEMS</u></b>              | NECESSARY |                           |                   |
|                    | BODY DECAL STICKER (SN)                       |           | 120.00                    | 120.00            |
|                    |   |           | 120.00                    | 120.00            |
|                    | <b><u>LABOUR</u></b>                          |           |                           |                   |
|                    | TOWING FEE.                                   |           | 40.00                     | 30.00             |
|                    | REMOVE & REPLACE NECESSARY PARTS,ALIGN & ETC. |           | 300.00                    | 150.00            |
|                    | REMOVE & REPLACE FORK ASSY & TOP UP FORK OIL. |           | 150.00                    | 100.00            |
|                    |   |           | 490.00                    | 280.00            |
| <b>GRAND TOTAL</b> |   |           | <b>5,872.30</b>           | <b>4,341.10</b>   |

|   |  |  |                 |
|---|--|--|-----------------|
| <b>RECOMMENDED COST OF LUMP SUM REPAIRS<br/>(TO ITS PRE-ACCIDENT CONDITION)</b> |  |  | <b>3,450.00</b> |
|---|--|--|-----------------|

Report Ref No. CS/SMO22001314/Ktf3n2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.