

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | | | |
|---|--|---|----------------|-------|-----------------------|--|
| | SOMPO INSURAN | CE SINGAPORE PL | - | Ref: | CS/SMO22001314/Ktf3n2 | |
| | 50 RAFFLES PLAC SINGAPORE LANI | CE #03-03 D TOWERSINGAPORE 048623 | | Date: | 22/03/2022 | |
| | | | | Code: | SMO | |
| 1. | Policy Particulars :- THIRD PARTY CLAIM | | | | | |
| | Insured Veh. | SLD 9275B | Veh. Inspected | | FBR 122M | |
| | Policy No. | | Coverage (\$) | | 0.00 | |
| | Claim No. | CMTD2200370/GPL | Excess (\$) | | 0.00 | |
| | Assign From | GRACE TEO | Assign Date | | 11/02/2022 | |
| 2. Vehicle Particulars & Condition | | | | | | |
| | Make & Model | YAMAHA NVX | c.c | | 155 | |
| | Engine No. | HIDDEN | Year of Reg. | | 2020 | |
| | Chassis No. | MH3SG4640KJ062611 | Colour | | BLUE | |
| | Odometer | 53228 KM | Steering | | IN ORDER | |
| | Brakes | IN ORDER | Modification | | STANDARD ALLOY RIM | |
| | General | GOOD | | | | |
| 3. | . Conditions of Tyres | | | | | |
| | | Size | Make | | Balance | |
| | R/H Front Tyre | 120/70 R14 | PIRELLI | | 5 mm | |
| | L/H Front Tyre | | | | mm | |
| | R/H Rear Tyre | 120/80 R14 | PIRELLI | | 5 mm | |
| | L/H Rear Tyre | | | | mm | |
| 4. | Description of Damages | | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND N/S BODY. | | | | | |
| | DAMAGES SEE DETAILS. | | | | | |
| 5. | General Information | | | | | |
| | Accident Date | 25/01/2022 | Inspection Dat | е | 11/02/2022 | |
| | Survey held at | SG 98 MOTOR PTE LTD | | | | |
| | | BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21 SINGAPORE 569622 | | | | |
| 5a. | | Remarks | | | | |
| | | N)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. | Estimate Days of Repair | | | | | |
| | ESTIMATED NOR | ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days | | | | |