

LKK Auto Consultants Pte Ltd

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMW 268U

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	HEADLAMP RH	NOT NECESSARY	1,978.00	-
1	FRONT BUMPER	SCRATCHED	1,260.00	1,260.00
1	FRONT BUMPER FOG LAMP COVER RH	SCRATCHED	120.00	120.00
1	FRONT BUMPER SIDE RETAINER RH	NOT NECESSARY	71.00	-
1	FRONT FENDER RH	TO REPAIR SEE LABOUR	1,167.00	-
	LESS 10% DISCOUNT		-459.60	-
	LESS 30% DISCOUNT		-	-414.00
			4,136.40	966.00
	SPECIAL NETT ITEMS			
1	FRONT BUMPER CLIPS (SN)	NECESSARY	50.00	30.00
1	SUNDRIES (SAND PAPER, WELDING WIRE ETC.) (SN)	NOT NECESSARY	50.00	-
			100.00	30.00
	<u>LABOUR</u>			
	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACED THE DAMAGED PARTS AND COMPONENTS. INCLUSIVE OF THE REPAIR OF FRONT FENDER RH.		500.00	300.00
	TO REMOVE & REFIT WIRING SYSTEM AT ACCIDENT AND CHECK FOR PROPER FUNCTIONS.	NOT NECESSARY	100.00	-
	TO REMOVE & REFIT FRONT BUMPER PARKING SENSORS.		80.00	60.00
	TO RESPRAY AND SUPPLY EXPANDABLE ITEMS & PUFFY ON PARTS REPLACED.		500.00	400.00
	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS.	NOT NECESSARY	40.00	-
	TO VACUUM, WAXING & CLEAN.	NOT NECESSARY	60.00	-
	TO PERFORM WATER SEEPAGE TEST ON REPAIRED PORTIONS.	NOT NECESSARY	50.00	-
			1,330.00	760.00
	GRAND TOTAL		5,566.40	1,756.00

Report Ref No. CS/SMR22001316/Rvf3e2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS	1,400.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CS/SMR22001316/Rvf3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

P

ANG BRYAN TANI

Automotive Assessor / Investigator