Our Ref: SMW268U Your Ref: SHB712Z

0	QTY	DESCRIPTIONS	ASSESSED CONDITION	EST. BY WORKSHOP
		PARTS REPLACEMENT - LIST ITEMS		TO STORY OF THE ST
	1	HEADLAMP RH XM		\$ 1,978.00
	1	FRONT BUMPER SUL		\$ 1,260.00
	1	FRONT BUMPER FOG LAMP COVER RH SUL	III. III. III. III. III. III. III. III	\$ 120.00
	1	FRONT BUMPER SIDE RETAINER RH		\$ 71.00
	1	FRONT FENDER RH POPULY	STATE OF THE PARTY OF	\$ 1,167.00
	1999		SUB TOTAL	\$ 4,596.00
	The state of		30% LESS 10%	\$ 459.60
			TOTAL AMOUNT	\$ 4,136.40

Our Ref: SMW268U Your Ref: SHB712Z

S/NO	QTY	SPECIAL NETT ITEMS	ASSESSED CONDITION	EST. BY	WORKSHOP
1	1	FRONT BUMPER CLIPS		\$	50.00
No.	The Part of	A DESCRIPTION OF THE PROPERTY OF THE PERSON	SUB TOTAL	\$	50.00
			TOTAL PARTS COST	\$	4,186.40

Our Ref: SMW268U Your Ref: SHR7127

S/NO	DESCRIPTION		EST. BY WORKSHOP	
1 2 3 5 6	LABOUR & PAINTWORN TO REMOVE THE AFFECTED PARTS & FITTINGS TO ORDER TO RESPRAY AND REPLICANCE OF TO REMOVE & REFIT WIRING SYSTEM AT ACCIDENT FUNCTIONS  TO REMOVE & REFIT FRONT BUMPER PAINT OF TO RESPRAY AND SUPPLY EXPANDABLE ITEMS & FOR TO PERFORM ANTI-RUST TREATMENT OF	COMMENCE REPAIRS; PANEL ACED THE DAMAGED PARTS  NT AND CHECK FOR PROPER  ARKING SENSORS  PUFFY ON PARTS REPLACED  N AFFECTED AREAS	\$ \$ \$	300 500.00 NAX 100.00 60 80.00 400 500.00 NAX 40.00 NAX 50.00
7	SUNDRIES (SAND PAPER, WELDING WIRE ETC.)		\$	11× 60.0
8	TO VACUUM, WAXING & CLEAN TO PERFORM WATER SEEPAGE TEST ON REPAIRED PORTIONS		\$	14× 50.0
-	101211.01111111111111111111111111111111	TOTAL BEFORE GST	\$	5,566.4
		GST 7%	\$	389.6
	The state of the s	OTAL (PARTS & LABOUR):	\$	5,956.0

Adjustments / Recommendations

Our estimator have throughly inspected each and every item on the estimate against physical damage found on the vehicle and have listed the breakdown of our finding and recommendation.

Our Workshop has agreed to undertake the job at a sum of \$ 5,956.05 for part by part with the third party insurance.

Yours Faithfully,

Jason Heng Claims Director

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

Pusue 140 900100068 3 days HS 11/02/2281555 Resus after repair

30

400

Lump Sum / 1 R 1 - /9