



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBP 3260M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	EXHAUST SILENCER	TO REPAIR SEE LABOUR	500.00	-
1	EXHAUST COVER (SILVER)	SCRATCHED	120.00	120.00
1	EXHAUST COVER (BLACK)	SCRATCHED	120.00	50.00
1	FRONT FAIRING OUTER	SCRATCHED	250.00	165.00
1	FRONT FAIRING INNER	DISTORTED	250.00	165.00
1	FRONT HEADLAMP	SCRATCHED	350.00	195.00
1	FRONT HEADLAMP FAIRING	SERVICEABLE	280.00	-
1	SET BALANCER	NECESSARY	120.00	80.00
1	FOOTREST RH	BENT	90.00	90.00
1	FOOTREST RUBBER RH	MISSING	60.00	60.00
1	MIDDLE FAIRING LH	CUT	200.00	165.00
1	MIDDLE FAIRING RH	CUT	200.00	165.00
1	FRONT FORK BRACKET	SERVICEABLE	180.00	-
1	GEAR PEDAL	BENT	90.00	90.00
1	BRAKE PEDAL	SCRATCHED	90.00	90.00
1	HANDLE BAR	BENT	250.00	200.00
1	HANDLE BAR BRACKET	BENT	150.00	115.00
1	WING MIRROR	SERVICEABLE	120.00	-
1	SIGNAL LAMP RH	CUT	120.00	120.00
1	PILLION FOOTREST LH	SCRATCHED	90.00	90.00
1	PILLION FOOTREST RH	SERVICEABLE	90.00	-
	LESS 10% DISCOUNT		-372.00	-196.00
			3,348.00	1,764.00
1	SET FRONT FORK (SN)	BENT	600.00	100.00
	LESS 10% DISCOUNT		-60.00	-
			540.00	100.00
	<u>SPECIAL NETT ITEMS</u>			
1	REAR NUMBER PLATE (SN)	SERVICEABLE	50.00	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FORK OIL (SN)	NECESSARY	30.00	15.00
1	FORK SEAL (SN)	NECESSARY	30.00	15.00
			110.00	30.00
	<u>LABOUR</u>			
	TO CHECK WIRING SYSTEM.		60.00	30.00
	REMOVE AND REPLACE FRONT FORK.		200.00	50.00
	TO R&R EXHAUST SILENCER.		150.00	70.00
	TO R&R SUSPENSION, HANDLE BAR, HEADLAMP & FAIRING. INCLUSIVE OF THE REPAIR OF EXHAUST SILENCER.		600.00	200.00
	TO SPRAY FENDER, FAIRINGS AND AFFECTED AREAS.		600.00	200.00
			1,610.00	550.00
GRAND TOTAL			5,608.00	2,444.00

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,000.00
---------------------------------------------------------------------------------	--	--	-----------------

Report Ref No. CS/FCI22001321/Vvf3e2

THEVAN THOMAS KARTHIKESAVAN

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.