

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877 Code: FCI2 1.	Affiliated to Federation Internationale Des Experts En Automobile					
#16-01 CITY HOUSESINGAPORE 068877 Code: FCI2 1.		MS FIRST CAPITA	L INSURANCE LTD	Re	f: CS/FCI22001321/Vvf3e2	
Policy Particulars :- THIRD PARTY CLAIM				Da	ite: 22/03/2022	
Insured Veh. GBA 9523U Veh. Inspected FBP 3260M				Co	de: FCI2	
Policy No. Coverage (\$) 0.00	1.	Policy Particulars :- THIRD PARTY CLAIM				
Claim No. D22000398MFCV Excess (\$) 0.00 Assign From AINI BINTE Assign Date 11/02/2022		Insured Veh.	GBA 9523U	Veh. Inspected	FBP 3260M	
Assign From AINI BINTE Assign Date 11/02/2022 Vehicle Particulars & Condition Make & Model YAMAHA JUPITER 115 c.c 114 Engine No. HIDDEN Year of Reg. 2019 Chassis No. MH3UE1120KJ213202 Colour BLUE Odometer - Steering IN ORDER Brakes IN ORDER Modification STANDARD ALLOY RIM General GOOD 3. Conditions of Tyres R/H Front Tyre 70/90 R17 MICHELIN 6 mm L/H Front Tyre MICHELIN 6 mm L/H Rear Tyre Description of Damages THE VEHICLE SUSTAINED DAMAGES AT THE O/S AND N/S BODY. DAMAGES SEE DETAILS. 5. General Information Accident Date 09/02/2022 Inspection Date 11/02/2022 Survey held at KARZ WORK SOLUTIONS 53 UBI AVE 1 #02-24 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934 A)DAMAGES CONSISTENT TO ACCIDENT REPORT.		Policy No.		Coverage (\$)	0.00	
Nake & Model		Claim No.	D22000398MFCV	Excess (\$)	0.00	
Make & Model		Assign From	AINI BINTE	Assign Date	11/02/2022	
Engine No. HIDDEN Year of Reg. 2019 Chassis No. MH3UE1120KJ213202 Colour BLUE Odometer - Steering IN ORDER Brakes IN ORDER Modification STANDARD ALLOY RIM General GOOD 3. Conditions of Tyres Nake Balance	2. Vehicle Particulars & Condition					
Chassis No. MH3UE1120KJ213202 Colour BLUE Odometer - Steering IN ORDER Brakes IN ORDER Modification STANDARD ALLOY RIM General GOOD 3. Conditions of Tyres R/H Front Tyre 70/90 R17 MICHELIN 6 mm L/H Front Tyre 70/90 R17 MICHELIN 6 mm R/H Rear Tyre 70/90 R17 MICHELIN 6 mm L/H Rear Tyre 70/90 R17 MICHELIN 6 mm L/H Rear Tyre 70/90 R17 MICHELIN 6 mm 4. Description of Damages THE VEHICLE SUSTAINED DAMAGES AT THE O/S AND N/S BODY. DAMAGES SEE DETAILS. 5. General Information Accident Date 09/02/2022 Inspection Date 11/02/2022 Survey held at KARZ WORK SOLUTIONS 53 UBI AVE 1 #02-24 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934 5a. Remarks A)DAMAGES CONSISTENT TO ACCIDENT REPORT.		Make & Model	YAMAHA JUPITER 115	c.c	114	
Odometer - Steering IN ORDER Brakes IN ORDER Modification STANDARD ALLOY RIM General GOOD 3. Conditions of Tyres Size Make Balance		Engine No.	HIDDEN	Year of Reg.	2019	
Brakes IN ORDER Modification STANDARD ALLOY RIM General GOOD 3. Conditions of Tyres Size Make Balance		Chassis No.	MH3UE1120KJ213202	Colour	BLUE	
General GOOD 3. Conditions of Tyres Size Make Balance		Odometer	-	Steering	IN ORDER	
3. Conditions of Tyres Size Make Balance		Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
R/H Front Tyre 70/90 R17 MICHELIN 6 mm L/H Front Tyre mm R/H Rear Tyre 70/90 R17 MICHELIN 6 mm L/H Rear Tyre 70/90 R17 MICHELIN 6 mm L/H Rear Tyre mm 4. Description of Damages THE VEHICLE SUSTAINED DAMAGES AT THE O/S AND N/S BODY. DAMAGES SEE DETAILS. 5. General Information Accident Date 09/02/2022 Inspection Date 11/02/2022 Survey held at KARZ WORK SOLUTIONS 53 UBI AVE 1 #02-24 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934 5a. Remarks A)DAMAGES CONSISTENT TO ACCIDENT REPORT.		General	GOOD			
R/H Front Tyre 70/90 R17 MICHELIN 6 mm L/H Front Tyre mm R/H Rear Tyre 70/90 R17 MICHELIN 6 mm L/H Rear Tyre mm 4. Description of Damages THE VEHICLE SUSTAINED DAMAGES AT THE O/S AND N/S BODY. DAMAGES SEE DETAILS. 5. General Information Accident Date 09/02/2022 Inspection Date 11/02/2022 Survey held at KARZ WORK SOLUTIONS 53 UBI AVE 1 #02-24 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934 5a. Remarks A)DAMAGES CONSISTENT TO ACCIDENT REPORT.	3.		Conditi	ons of Tyres		
L/H Front Tyre			Size	Make	Balance	
R/H Rear Tyre 70/90 R17 MICHELIN 6 mm L/H Rear Tyre Description of Damages THE VEHICLE SUSTAINED DAMAGES AT THE O/S AND N/S BODY. DAMAGES SEE DETAILS. 5. General Information Accident Date 09/02/2022 Inspection Date 11/02/2022 Survey held at KARZ WORK SOLUTIONS 53 UBI AVE 1 #02-24 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934 5a. Remarks A)DAMAGES CONSISTENT TO ACCIDENT REPORT.		R/H Front Tyre	70/90 R17	MICHELIN	6 mm	
L/H Rear Tyre Description of Damages THE VEHICLE SUSTAINED DAMAGES AT THE O/S AND N/S BODY. DAMAGES SEE DETAILS. General Information Accident Date 09/02/2022 Inspection Date 11/02/2022 Survey held at KARZ WORK SOLUTIONS 53 UBI AVE 1 #02-24 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934 5a. Remarks A)DAMAGES CONSISTENT TO ACCIDENT REPORT.		L/H Front Tyre			mm	
4. Description of Damages THE VEHICLE SUSTAINED DAMAGES AT THE O/S AND N/S BODY. DAMAGES SEE DETAILS. 5. General Information Accident Date 09/02/2022 Inspection Date 11/02/2022 Survey held at KARZ WORK SOLUTIONS 53 UBI AVE 1 #02-24 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934 5a. Remarks A)DAMAGES CONSISTENT TO ACCIDENT REPORT.		R/H Rear Tyre	70/90 R17	MICHELIN	6 mm	
THE VEHICLE SUSTAINED DAMAGES AT THE O/S AND N/S BODY. DAMAGES SEE DETAILS. 5. General Information Accident Date 09/02/2022 Inspection Date 11/02/2022 Survey held at KARZ WORK SOLUTIONS 53 UBI AVE 1 #02-24 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934 5a. Remarks A)DAMAGES CONSISTENT TO ACCIDENT REPORT.		L/H Rear Tyre			mm	
5. General Information Accident Date 09/02/2022 Inspection Date 11/02/2022 Survey held at KARZ WORK SOLUTIONS 53 UBI AVE 1 #02-24 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934 5a. Remarks A)DAMAGES CONSISTENT TO ACCIDENT REPORT.	4.	Description of Damages				
5. General Information Accident Date 09/02/2022 Inspection Date 11/02/2022 Survey held at KARZ WORK SOLUTIONS 53 UBI AVE 1 #02-24 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934 5a. Remarks A)DAMAGES CONSISTENT TO ACCIDENT REPORT.		THE VEHICLE SUSTAINED DAMAGES AT THE O/S AND N/S BODY.				
Accident Date 09/02/2022 Inspection Date 11/02/2022 Survey held at KARZ WORK SOLUTIONS 53 UBI AVE 1 #02-24 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934 5a. Remarks A)DAMAGES CONSISTENT TO ACCIDENT REPORT.		DAMAGES SEE DETAILS.				
Survey held at KARZ WORK SOLUTIONS 53 UBI AVE 1 #02-24 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934 5a. Remarks A)DAMAGES CONSISTENT TO ACCIDENT REPORT.	5.	General Information				
53 UBI AVE 1 #02-24 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934 5a. Remarks A)DAMAGES CONSISTENT TO ACCIDENT REPORT.		Accident Date	09/02/2022	Inspection Date	11/02/2022	
PAYA UBI INDUSTRIAL PARK SINGAPORE 408934 5a. Remarks A)DAMAGES CONSISTENT TO ACCIDENT REPORT.		Survey held at	KARZ WORK SOLUTIONS			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT.			PAYA UBI INDUSTRIAL PARK			
	5a.		Re	emarks		
C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.						
5b. Estimate Days of Repair	5b.					
ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days						