3/31/22, 10:46 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22001326/KTF3N2

31/03/2022 Date:

Odometer:

REFERENCE

No:

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No: DMCVSNW00065422104

Claimant Vehicle

SGR9393D

Insured Vehicle GBD8978G

No:

Date of Loss: 08/02/2022 Nature of Claim: TP Claim SNM22D200968/C02/TANKL

31516 km

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGR9393D**

28291480027075 Make & Model: MERCEDES-BENZ A200, 1.3 AMG LINE (A) Engine No: Reg. Date: 04/01/2019 (Man. Year: 2018) Chassis No: WDD1770872N013343

Colour: White

Engine Capacity: 1332 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): **Engine Modification:** Pre-accident Condition: Yes Nο

CONDITION OF TYRES

Front Tyre Size: 245/35ZR19 Rear Tyre Size: 245/35ZR19 Front Left Side: Rear Left Side: Michelin 7 mm Michelin 7 mm Front Right Side: Rear Right Side: Michelin 7 mm Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	949.00	949.00	0.00	0.00
Miscellaneous Items	630.00	110.00	520.00	82.54
Labour	940.00	740.00	200.00	21.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,519.00	1,799.00	720.00	28.58
+ GST 7.00/7.00% (S\$)	176.33	125.93	50.40	28.58
Nett Amount (S\$)	2,695.33	1,924.93	770.40	28.58

INSPECTION

Date of Assignment: 11/02/2022

Cheng Hoe Motor Pte Ltd (Yishun)

Blk 1019 #01-374/382, Yishun Industrial Park A Date Inspected: 23/02/2022 Inspected At:

Singapore 768761

Estimated Period of Repair: 3.0 days

DENISE TAY KWEE CHENG Adjuster: KENNETH KONG Manager:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

3/31/22, 10:46 AM Adjuster Report

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 31 Mar 2022)

Parts: 144 MERCEDES-BENZ A200 1.3 AMG LINE (A) (Catalogue:Merimen Singapore 1.0)

Labour:Repairer's(Price-denominated Standard List)Print Code:(Unsubmitted, no print-code for SGR9393D)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty Pa	art No.	Particulars	Condition	Repairer's	Amount
1	1		*1 PC REAR BUMPER	Buckled/Warped	875.00 F	*875.00 F
2	1		*2 PCS REAR BUMPER SIDE GARNISH @37/PC	Cracked	74.00 F	*74.00 F
F=Fra	anchise part	1.		Total Parts (S\$)	949.00	949.00
			Report was unsubmitted during th	is print-out.		

Recommended Miscellaneous Items

No	Qty	Particulars		Repairer's	Amount		
Mis	Miscellaneous Items						
1	1	1 PC REAR BUMPER LOWER SKIRT		380.00	0.00		
_		Repair					
2	1	1 SET REVERSE SENSOR Shorted		250.00	110.00		
			Sub Total (S\$)	630.00	110.00		

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labe	our Items			
1	REMOVE & REFIX REAR BUMPER ASSY,REAR LOWER SKIRT,REFLECTORS,TO KNOCK & REPAIR REAR BUMPER REINFORCEMENT AND REALIGN THE SAME	New	400.00	300.00
2	PUTTY & RESPRAY ON REAR BUMPER, LOWER SKIRT (TWO TONE)	New	500.00	400.00
3	REMOVE & REFIX REVERSE SENSOR AND RESET SYSTEM	New	40.00	40.00
	Gross Labour Cost (S\$)		940.00	740.00
	Report was unsubmitted during this	s print-out.		

< END OF ESTIMATES >