

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22001327/AVF3N2**Date:** 12/05/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00165792101	
Claimant Vehicle No :	SMZ691P	Insured Vehicle No :	SMH9801A	
Date of Loss:	09/02/2022	Nature of Claim:	TP	Claim No: SNM22D201000/C02/CHNGPW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMZ691P		Engine No:	K12D1098555
Make & Model:	SUZUKI SWIFT, 1.2 GLX CVT (A)		Chassis No:	JSAAZCA3S00523072
Reg. Date:	08/04/2021 (Man. Year: 2021)		Odometer:	50149 km
Colour:	Red			
Engine Capacity:	1197 cc			
Market Value/New Car Price:	N/A			
Sum Insured (\$\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/55R16	Rear Tyre Size:	185/55R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,575.47	893.38	682.09	43.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,520.00	860.00	660.00	43.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	3,095.47	1,753.38	1,342.09	43.36
Approved Total (Overridden) (\$\$)		1,400.00		
(\$\$)	3,095.47	1,400.00	1,695.47	54.77
+ GST 7.00/7.00% (\$\$)	216.68	98.00	118.68	54.77
Nett Amount (\$\$)	3,312.15	1,498.00	1,814.15	54.77

INSPECTION

Date of Assignment:	11/02/2022	
Date Inspected:	28/02/2022 Inspected At:	N-51 Automotive Pte Ltd (HQ) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB Singapore 417921
Estimated Period of Repair:	4.0 days	

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 May 2022)
Parts:	144	SUZUKI SWIFT 1.2 GLX CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMZ691P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	510.40 FL	*510.40 FL
2	4		*REAR BUMPER REVERSE SENSOR HOLDER BRACKET	Necessary	112.00 FL	*112.00 FL
3	1		*REAR BUMPER RH REVERSE SENSOR	Damaged	330.00 FL	*200.00 FL
4	1		*REAR BUMPER RH REVERSE SENSOR O RING	Necessary	10.00 FL	*10.00 FL
5	1		*REAR BUMPER SIDE RETAINER L/R	O/s Necessary	40.00 FL	*20.00 FL
6	1		*REAR RH FENDER INNER SHIELD	Deformed	128.05 FL	*128.05 FL
7	1		*REAR RH TAILLAMP	Not Necessary	512.60 FL	*- FL
8	1		*REAR RH TAILLAMP PANEL	Not Necessary	57.50 FL	*- FL
9	1		*REAR BUMPER CLIPS - SET	Necessary	50.00 FS	*30.00 FS
10	1		*REAR RH FENDER INNER SHIELD CLIPS - SET	Necessary	50.00 FS	*30.00 FS
11	1		*REAR RH TAILLAMP CLIPS - SET	Not Necessary	30.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	1,830.55	1,040.45
- List Item Discount on L Items 15.00/15.00% (\$\$)	255.08	147.07
Total Parts (\$\$)	1,575.47	893.38

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING, AND REWIRE FOR PARKING SENSOR.	New	50.00	30.00
2	TO REMOVE, REINSTALL ROOF TOP TRIM UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET. (TO FR)	New	120.00	0.00
3	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT.	New	700.00	400.00
4	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT.	New	600.00	400.00
5	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.	New	50.00	30.00
Gross Labour Cost (\$)			1,520.00	860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >